

UNIVERSAL SERVICE OBLIGATION FUND

AGREEMENT

FOR

"PROVISION OF 4G BASED MOBILE SERVICES IN IDENTIFIED
UNCOVERED VILLAGES IN ARUNACHAL PRADESH"

With

M/s Bharti Hexacom Limited

(Tender No. USOF/TENDER/ARUNACHAL/30-252-5/2020 Dated: 04/03/2021 for provision of
4G based mobile services in identified uncovered villages in Arunachal Pradesh and two
districts of Assam (Karbi Anglong & Dima Hasao))

No. 30-252-5/2020-USF

Dated: 29.10.2021



GOVERNMENT OF INDIA
MINISTRY OF COMMUNICATIONS
DEPARTMENT OF TELECOMMUNICATIONS
UNIVERSAL SERVICE OBLIGATION FUND (USOF)
20, ASHOKA ROAD, NEW DELHI-110 001, INDIA


रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली / New Delhi

Table of Contents

SECTION-I: AGREEMENT	3
SECTION – II: SCOPE OF THE AGREEMENT	7
SECTION– III: GENERAL CONDITIONS.....	10
SECTION-IV: COMMERCIAL CONDITIONS.....	11
SECTION – V: TECHNICAL CONDITIONS	17
SECTION – VI: OPERATING CONDITIONS.....	24
SECTION – VII: FINANCIAL CONDITIONS.....	27
SECTION – VIII: SPECIAL INSTRUCTIONS TO THE U.S.P,.....	33
SECTION – IX: INTERPRETATION OF TERMS/DEFINITIONS.....	34
ANNEXURE-1: DETAILS OF NUMBER OF UNCOVERED VILLAGES IN ARUNACHAL PRADESH AND USOF SUBSIDY SUPPORT.....	36
ANNEXURE-2: FORMAT FOR CERTIFICATION OF SUBSIDY CLAIM.....	37
ANNEXURE-3: PROFORMA FOR SELF-CERTIFICATION BY UNIVERSAL SERVICE PROVIDER.....	42
ANNEXURE-4: FORMAT FOR AUDITOR’S REPORT ON STATEMENT OF CLAIM FOR SUBSIDY FROM USOF ..	46
ANNEXURE-5: MONTHLY STATEMENT.....	47
ANNEXURE-6: FORMAT FOR THE CERTIFICATION FOR CONTINUATION OF THE SERVICES STATUS.....	48
ANNEXURE-7: FORMAT FOR INSTALLATION OF TOWERS IN ADDITION/DELETION OF PROPOSED TOWERS.....	49
ANNEXURE-8: FORMAT FOR REQUEST FOR SHIFTING OF TOWERS.....	50
ANNEXURE-9: MONTHLY STATEMENT OF PROGRESS OF PROJECT IMPLEMENTATION.....	51
APPENDIX-1: SITE LOCATIONS AND DETAILS.....	52




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

SECTION-I: AGREEMENT

The President of India, acting through the Administrator, Universal Service Obligation Fund (USOF), Department of Telecommunications, under Government of India and having its office at 2nd Floor, Sanchar Bhawan, 20, Ashoka Road, New Delhi- 110001, (hereinafter referred to as the "Administrator", which expression, unless repugnant to the context or meaning thereof, shall include its successors, administrators or assignees;) of the First Party

AND

M/s Bharti Hexacom limited, a company registered under the Companies Act 1956/2013, having its registered office at Bharti Crescent, 1-Nelson Mandela Road Vasant Kunj, Phase-II, New Delhi-110070, India acting through Shri Rahul Vatts the Authorised Signatory (hereinafter called the Universal Service Provider or "USP" which expression shall, unless repugnant to the context or meaning thereof, shall include its successors, administrators or permitted assignees) of the Second Party.

WHEREAS the Government of India has approved a Project/Scheme for "Provision of 4G based mobile services in identified uncovered villages in Arunachal Pradesh and two districts of Assam (Karbi Anglong & Dima Hasao)"

AND WHEREAS the USP has agreed to provide 4G based Mobile Services in Identified Uncovered Villages in Arunachal Pradesh (as mentioned in the tender) and the Administrator has, subject to the USP performing all the obligations on their part, agreed to provide subsidy on the terms and conditions hereinafter;

NOW THIS AGREEMENT WITNESSETH AS FOLLOWS:

In consideration of the mutual covenants set out in this Agreement, the parties agree as follows:

1. The USP hereby agrees and undertakes to provide 4G based Mobile Services in Identified Uncovered Villages in Arunachal Pradesh (as per terms and conditions of this agreement and list of 1683 uncovered villages to be provided with mobile services enclosed at Appendix-1) and the Administrator, in consideration of the USP having agreed to set up and manage the aforesaid mobile service sites, does hereby agree to grant subsidy to the USP, in accordance with this Agreement.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निर्देशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
संचार विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली/New Delhi.

2. This Agreement will remain valid for ten (10) years & Eighteen months unless revoked earlier for any reason whatsoever. Date of effect of this Agreement shall be the date of signing of the agreement.
3. The USP hereby agrees and unequivocally undertakes to fully comply with all terms and conditions stipulated in this Agreement without any deviation or reservation of any kind.
4. Unless otherwise mentioned or appearing from the context, the Tender Document No. USOF/TENDER/ARUNACHAL/30-252-5/2020 issued on 04/03/2021 for "Provision of 4G based mobile services in identified uncovered villages in Arunachal Pradesh & two districts of Assam (Karbi Anglong & Dima Hasao)" and clarifications and amendments/ modifications to the tender document issued shall form part and parcel of this Agreement.
5. This Agreement is divided into nine Sections. Apart from the present Section-I, other Sections are as under:

- II Scope of the Agreement
- III General Conditions
- IV Commercial Conditions
- V Technical Conditions
- VI Operating Conditions
- VII Financial Conditions
- VIII Special Instructions to the USP
- IX Interpretation of Terms/Definitions

All the Sections and Annexures together form the Agreement.

6. **No Partnership**- Nothing in this Agreement shall be construed to constitute a partnership or agency between the Parties and the USP shall not make any assurance, promise or covenant nor shall hold himself out as competent to do so on behalf of the Administrator nor shall pledge the credit of the Administrator for any transaction in relation to this Agreement.
7. **No Employment** - Nothing in this Agreement shall constitute an offer or assurance of employment of any nature whatsoever to the USP or any person employed by or under him for this Agreement.
8. **Indemnify the Administrator** - The USP shall indemnify and at all times keep the Administrator indemnified and harmless against any direct loss to it or any claims by any third person, for any personal injury to anybody or loss to property, movable or immovable, caused by or attributable to any act or omission of the USP or any of



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यु.एन.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

his officer, employee, agent or professional etc. while performing or purporting to perform this Agreement.

9. **Dispute Settlement:**

- 9.1 In the event of dispute of difference between the parties hereto, such disputes or differences shall be resolved amicably by mutual consultation within 3 months. If such resolution is not possible, then the unresolved dispute or difference shall be referred to arbitration of the sole arbitrator to be appointed as per mutual consent of both parties within 60 days. The provisions of Arbitration and Conciliation Act, 1996 (No. 26 of 1996) or of any modifications, Rules or re-enactments thereof shall be applicable to the arbitration. The language of arbitration proceedings shall be English. The arbitrator shall make a reasoned award (the "Award"), which shall be final and binding on the parties." The cost of the arbitration shall be shared equally by the parties to the Agreement. However, expenses incurred by each party in connection with the preparation, presentation shall be borne by the party itself.
- 9.2 The venue of the arbitration proceeding shall be at New Delhi.
- 9.3 Notwithstanding any dispute or claim of the pendency of any arbitration or other proceedings, USP shall continue to provide the service for the whole duration of the Agreement.
- 9.4 Pending the submission of and/or decision on a dispute, difference or claim or until the arbitral award is published; the Parties shall continue to perform all of their obligation under this Agreement without prejudice to final adjustment in accordance with such award.
- 9.5 The Agreement shall be exclusively subject to jurisdiction of the courts at New Delhi.
10. **Waiver** - Neither the failure of either Party to insist on any occasion upon the Performance of the provisions of this Agreement nor time or other indulgence granted by a Party to the other Party shall be treated or deemed as waiver of such breach or acceptance of any variation or the relinquishment of any such right thereunder. Waiver by either Party of any default by the other Party in the observance or performance of any provision of this Agreement shall not operate or be construed as a waiver of any other or subsequent default or of other provisions of or obligations under this Agreement nor shall affect the validity or enforceability of this Agreement in any manner.
11. **Severability of Terms** - If for any reason whatsoever, any provision of this Agreement is or becomes invalid, illegal or unenforceable or is declared by any court of competent jurisdiction or any other instrumentality to be invalid, illegal or unenforceable, the validity, legality or enforceability of the remaining provisions shall not be affected in any manner.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

12. IEMs appointed by DoT shall oversee the implementation of Integrity Pact Program. Name and address of IEM is as below:

1. Shri Arvind Kumar Arora, IDSE
Ex. Director General, MES, Ministry of Defence
B-333, Chittaranjan Park
New Delhi - 110019
Email: arvindarora2016@gmail.com
2. Shri Pradeep Kumar Gupta Ex Spl Director General,
CPWD IEM, Department of Telecom, T-17, Green
Park Extension, New Delhi 110016
E-mail: pradeepkgupta53@gmail.com

IN WITNESS WHEREOF the parties hereto have caused this Agreement to be executed through their respective authorized representatives on the 29th day of October, 2021.

For and on behalf of
M/s Bharti Hexacom limited
SIGNED, SEALED AND DELIVERED by


(Rahul Vatts)
Bharti Hexacom limited
Authorised Signatory
Bharti Crescent, 1, Nelson Mandela Road
Vasant Kunj, Phase-II
New Delhi - 110070

For and on behalf of
President of India
SIGNED, SEALED AND DELIVERED by


(Rameshwar Dhariwal)
Director (T-1), USOF
Department of Telecommunications
Sanchar Bhawan, 20 Ashoka Road
New Delhi - 110001

Witnesses:


(Vishal Ambardar)
Bharti Crescent, 1, Nelson Mandela Road
Vasant Kunj, Phase-II
New Delhi - 110070


(Sahil Garg)
DA (F-1), USOF
DoT, Sanchar Bhawan
20, Ashoka Road, New Delhi-110001



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
संचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

SECTION – II: SCOPE OF THE AGREEMENT

2.1. Scope of the Agreement:

- (i) Objective of the scheme is to provide financial support from USO Fund for a period of five years, for provision of 4G based Mobile Services in Identified Uncovered Villages in Arunachal Pradesh.
- (ii) The USP shall set up (i.e. Supply, Install, Test, and Commission), operate, maintain and manage the respective infrastructure sites required for effective provision of 4G based Mobile Services in Identified Uncovered Villages in Arunachal Pradesh as per the terms and conditions laid down in the agreement.
- (iii) USOF shall provide financial support as per the financial conditions of the agreement.
- (iv) In line with the provisions related to Green Telecom in NDCP – 18 Policy, the Scheme is designed with alternate power source of Renewable Energy Technologies (RETs) or Diesel Generator.
- (v) USP, at its discretion, may share infrastructure with other Licensed Service Providers, subject to compliance of the guidelines /instructions issued by DoT in this regard. However, there shall be no extra financial support from USOF.

2.2. DELIVERABLES

- (i) Deliverables of the Scheme shall be provision of mobile coverage in specified hitherto uncovered village clusters in Arunachal Pradesh, as per the terms and conditions of the USOF Tender. It shall include, inter alia, commissioning of infrastructure and continued provision of 4G based mobile services in inhabited areas of specified uncovered villages in Arunachal Pradesh in compliance with DoT Licenses and TRAI Regulations, as applicable.
- (ii) USP will be responsible for:
 - a) Carrying out survey to identify the exact sites for installation of tower/eNode-B, and decide the exact number and type of towers to be installed considering the variation allowed in tender document and acquisition of sites for installation of mobile infrastructure;
 - b) Supply, install, test, commission and maintenance of telecom towers on the land acquired by them for this purpose in the villages in Arunachal Pradesh as specified in the Tender Document;
 - c) Provision of Electrical connection (where Grid-power available), battery and DG Set/ Renewable Energy of adequate capacity;
 - d) Installation of eNode-B and associated equipment as per specifications given in the Tender Document;
 - e) Installation of Antennas and all other associated equipment as per specifications;
 - f) Providing Backhaul as per requirement of the tender;



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

- g) To maintain the desired quality of service (QoS), as per the TRAI recommendations/ guidelines. (Uptime of minimum 98%).
- h) Commissioning of services and providing 4G based mobile services consistent with the terms and conditions of the License Agreement signed with DoT.
- i) Continued Operation and Maintenance of the Tower and Infrastructure created and provision of 4G based mobile services compliant with the terms and conditions of the License Agreement signed with DoT, for a period of 18 months (rollout period) + Ten years from the date of effect of the agreement with USOF.
- (iii) The USP will have to submit following to USOF:
- (a) A Survey report covering assessment of exact location for installation of towers and detailed information on number and type of towers to be installed at each site considering the variation allowed in tender document in consultation with authorised agency to be appointed by Administrator, USOF, for consideration of USOF.
- (b) Affidavits from the authorised signatory confirming the commissioning of 4G based mobile services through each tower towards claiming the subsidy for the individual tower, based on the Category-specific Representative Rates, along with details of the infrastructure created with cost and specification in the prescribed format in this tender document.
- (c) Quarterly status reports on operation and maintenance of towers confirming that each tower is functional and efficiently providing mobile services consistent with the terms and conditions of the License Agreement signed with USOF. Traffic volume of each eNode-B should also be reported.
- (iv) If any new village is found uncovered which is not a part of this tender document then proposal for installation of infrastructure/ tower for provision of coverage of such uncovered village may be submitted separately with concurrence of respective LSA. However, total number of sites in the bidding unit shall be within +25% of sites, as per tender.
- (v) After deployment of the project, Social Impact Assessment by an independent agency shall be conducted by USP to ascertain the efficacy and utility of the project and submit a report to USOF which would provide input for further deployment and extension of the project.
- (vi) Due care has been taken while preparing the data of uncovered villages attached with the tender document, however, during survey, if any field from Name of Villages or census code or Latitude/ longitude are found to be incorrect but other fields are correct and the location is uncovered then infrastructure for providing mobile for such villages is to be planned/ provided.
- (vii) Latitude / Longitude for 54 uncovered villages of Appendix-1 could not be located on GIS data base, therefore clusters have not been formed for these villages. USP shall try its best, during physical survey, to include these village(s) in any of the nearby village/cluster.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

(viii) USOF shall have the right to appoint a TPA. The TPA shall randomly inspect, verify and certify the progress and completion of the work of mobile towers and mobile services on sample basis. The TPA shall submit its reports to USOF.

2.3. Details of Areas to be Covered:

- (i) The list of identified uncovered villages in Arunachal Pradesh to be provided with mobile services is enclosed at **Appendix-1**.
- (ii) The Administrator will have the right to decrease for the sites already covered or increase up to +25% in each type of infrastructure/ eNode-B [Type A, B for uncovered villages] as specified in the **Annexure-1** in the bidding unit of Arunachal Pradesh based on the suitable justification provided by USP after carrying out the survey of infrastructure sites without any change in the Category-specific Representative Rates so arrived at after the bidding process, or other terms and conditions at the time of signing of Agreement.

2.4. Details of number of sites in uncovered villages in Arunachal Pradesh and USOF Subsidy Support are given at **Annexure-1**.

2.5. Installation of tower and associated infrastructure in an uncovered village is not required if it is already covered from any type of technology i.e. 2G or 3G or 4G or a combination thereof through any TSP. The same should be duly justified and certified by the USP.

2.6. USOF subsidy will be paid only in respect of the sites where mobile tower with backhaul and associated equipment is installed and commissioned under the Scheme and will be limited to the number of sites finalized and approved by USOF.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एन.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली/New Delhi

भारतीय दूरसंचार
नियंत्रण आयोग
भारत सरकार

SECTION- III: GENERAL CONDITIONS

- 3.1 The Agreement shall be subject to the terms and conditions (including transfer, assignment or franchising) of CMTS (Cellular Mobile Telephone Services)/ UASL (Unified Access Service Licensees)/ Unified License/ Migration or award of new license in lieu of CMTS/ UASL.
- 3.2 The USP shall be bound by the terms and conditions of the Agreement or any other instructions issued from time-to-time by the Administrator. The USP shall always be liable to perform the obligations under this Agreement for Provision of 4G based Mobile Services in Identified Uncovered Villages in Arunachal Pradesh for which the Agreement has been entered into during the validity period of the Agreement.
- 3.3 The signing of Agreement will not be treated and taken as grant of fresh License under the Indian Telegraph Act, 1885.
- 3.4 In case USP withdraws from the Scheme after signing of the Agreement, Administrator shall take action as per Exit Clause 7.6 of this agreement.
- 3.5 The USP represents and warrants to the Administrator that
- It is duly organized and validly incorporated under the laws of India, and has full power and authority to execute and perform its obligations under this Agreement;
 - It has taken all necessary corporate and other actions under applicable laws to authorize the execution and delivery of this Agreement and to validly exercise its rights and perform its obligations under this Agreement;
 - It has the financial standing and capacity to undertake and perform the obligations in accordance with this Agreement;
 - This Agreement constitutes its legally valid and binding obligation, enforceable against it in accordance with the terms hereof, and its obligations under this Agreement will be legally valid, binding and enforceable obligations under it in accordance with the terms hereof;
 - The information furnished in the bid and as updated on or before the date of this Agreement is true and accurate in all respects as on the date of this Agreement.
 - The execution, delivery and performance of this Agreement will not conflict with, result in the breach of, constitute a default under, or accelerate performance required by, any of the terms of its memorandum and Articles of Association or any Applicable law or any covenant, contract, agreement, arrangement, understanding, decree or order to which it is a party or by which it or any of its properties or assets is bound or affected.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एन.ओ.एक.
Director (T-1) USOP
दूरसंचार विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली/New Delhi

SECTION-IV: COMMERCIAL CONDITIONS

4.1 The Agreement shall be subject to the terms and conditions (including transfer, assignment or franchising) of UASL (Unified Access Service Licensees)/ Unified License/ Migration or award of new license in lieu of UASL.

4.2 RESPONSIBILITIES OF THE USP UNDER THE SCHEME

4.2.1 The USP would be required to, inter-alia, create the requisite infrastructure for provision of 4G based mobile services covering the following activities:

- (i) Acquisition of site of dimensions as specified in Section-V: Technical Conditions of the Agreement on lease basis/ outright purchase from any agency in the specified villages/ areas. In case, the land is taken on lease basis, the lease Agreement should be signed for a minimum period of Ten years.
- (ii) Supply, install, test, commission and maintain Towers conforming to Section-V: Technical Conditions of the Agreement.
- (iii) Arrange Electrical power connection as specified in Section-V: Technical Conditions from the concerned State Electricity Boards/ Corporations. Necessary coordination will be facilitated by USOF in case of requirement. The rates of electricity will be as per applicable tariff to be borne by the USP only.
- (iv) Supply, install, test and commission Renewable Energy Source, Batteries and Engine Alternators (Diesel Generator Sets) as specified in Section-V: Technical Conditions of the Agreement for providing power backup with changeover arrangements.
- (v) Execution of associated civil and electrical work as per the specification prescribed in Section-V: Technical Condition.
- (vi) Install the eNode-B equipment, antenna and the associated backhaul connectivity to their respective core networks in accordance with the prescribed specifications in Section-V: Technical Conditions.
- (vii) Provide, operate and maintain the 4G based mobile services from all the sites in the specified villages in accordance with the prescribed specifications in Section-V: Technical Conditions.
- (viii) Only new equipment and material shall be provided under the Scheme. For this purpose, the new equipment shall be the one which has been procured not earlier than 12 months of submission of bid and has never been used earlier.
- (ix) Solely responsible for installation, operation & maintenance of necessary equipment & systems, provision of services to the customers, treatment of subscriber complaints, collection of call-charges and issue of receipts thereof, and attending to claims and damages arising out of operations.



रामेश्वर धरियावाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एन.ए.ए.
Director (T-1) USOF
सूचना विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली / New Delhi

(x) All other necessary actions to provide the deliverables as specified in Clause 2.2 of the Agreement.

4.2.2 The infrastructure/ assets so created under this project shall be owned by the USP.

4.2.3 USP shall ensure continued provisioning of 4G based mobile services, during the currency of the Agreement, in the identified uncovered villages as per the broad parameters of Agreement.

4.2.4 During the Agreement period, cost of change of equipment /spectrum, etc., if any, will have to be borne by the USP.

4.2.5 Continued Operation and Maintenance of the Tower and infrastructure so created in order to provide 4G based mobile services compliant with the terms and conditions of the License Agreement, after expiry of the Agreement signed with USOF.

4.2.6 Infrastructure created and services provided under this project will not be counted towards rollout obligations (as specified under the license conditions) of service providers.

4.2.7 DoT/USOF will consider to refer issues such as security and protection for sites etc. to State Governments, where their intervention is required. However, Roll-out period, imposition of LD and other penalty conditions will not be relaxed, due to delay/inaction on the part of State Government or any other concerned agency.

4.3 INSPECTION AND TESTS

4.3.1 The Administrator or his representative or the agencies authorized shall have the right to inspect and test the created infrastructure and provision of 4G based mobile services as per prescribed test schedules for their conformity to the specifications. Where the Administrator decides to conduct such tests on the infrastructure sites created by USP, all reasonable facilities and assistance like testing instruments and other test gadgets including access to drawings and other details shall be furnished to the Authorized Agency at no charge to the Administrator.

4.3.2 Should any inspected or tested components fail to conform to the specifications, the Administrator may reject them and the USP shall either replace the rejected components or make all alterations necessary to meet specification/ requirements free of cost to the Administrator.

4.3.3 If any equipment or any part thereof is found defective or fails to fulfil the requirements of the Agreement, USOF shall give notice to the USP setting forth details of such defects or failure and the USP shall at their own cost make the defective equipment good, or alter the same to make it comply with the requirements of the Agreement forthwith and in any case within a period not exceeding one month of the initial report. These replacements shall be made by the USP free of all charges at site.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एन.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

4.3.4 Nothing in Clause 4.3 shall in any way release the USP from any warranty or other obligations under this contract.

4.4 CHANGES IN AGREEMENT SIGNED

The Administrator may, at any time, by a written order given to a USP, make changes within the general scope of the Agreement in any one or more of the following subject to the condition that such changes will not have any major financial implications:

- (i) Specifications of the Scheme.
- (ii) The location and number of the towers; or
- (iii) The services to be provided by the USP

4.5 DURATION OF AGREEMENT

The Agreement shall be valid for a period of 18 months (rollout period) + Ten years from the effective date unless revoked earlier for reasons as specified elsewhere in the document.

The subsidy support period and subsidy claim and disbursement schedule is as per Section VII: Financial Conditions of this document. USP shall be responsible for operation and maintenance of the created infrastructure and provision of specified services for a period of 18 months (rollout period) + Ten years from the effective date of the agreement and also after the expiry of Agreement period, as the telecom service providers under the license conditions are bound to provide services under the license terms.

4.6 EXTENSION OF AGREEMENT

The Administrator may extend, if deemed expedient, the validity of Agreement for such period and on such terms as may be mutually agreed.

4.7 MODIFICATIONS IN TERMS AND CONDITIONS OF AGREEMENT

The Administrator reserves the right to modify at any time the terms and conditions of the Agreement signed with the USP, if in the opinion of the Administrator it is necessary or expedient to do so in public interest or in the interest of the security of the State or for the proper conduct of the service. The decision of the Administrator shall be final in this regard.

4.8 REQUIREMENT TO FURNISH INFORMATION

The USP shall furnish to the Administrator, on demand, such documents, accounts, estimates, returns, reports or any other information as may be called for by the Administrator pertaining to the creation of infrastructure and provisioning of 4G based mobile services under the scheme.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली / New Delhi

4.9 OTHER OBLIGATIONS

- 4.9.1 Universal Service Provider (USP) would have to ensure that it continues to hold a valid telecom license & necessary spectrum, during the currency of the USOF Agreement.
- 4.9.2 USP, at its discretion, may have back-end tie-up with Infrastructure Providers Category-1 (IP-1) registered with the Department of Telecom. However, USOF will enter into agreement only with universal service provider who will be solely responsible to comply with all the terms and conditions of the tender and to perform all obligations as per the terms and conditions of the tender and USOF Agreement.
- 4.9.3 The provisions of the Indian Telegraph Act, 1885 or the Indian Wireless Telegraphy Act, 1933 as amended or replaced, the rules made and orders passed under these statutes, so far as applicable, shall be binding on the USP.
- 4.9.4 The USP shall be bound by the terms and conditions of the Agreement as well as by such orders/ directions/ regulations of DoT/ TRAI as per provisions of the TRAI Act, 1997 as amended from time to time and instructions/ directions as are issued by the Administrator.
- 4.9.5 The USP shall apply all due diligence in understanding all aspects of the project including the terrain, its remoteness and the possible handicaps, hurdles or reasons for delay and shall have no cause of grievance or abatement on this score.

4.10 TERMINATION OF AGREEMENT

- 4.10.1 The Administrator may, without prejudice to any other remedy available for the breach of any conditions of Agreement, by a written notice of 90 calendar days issued to the USP at its registered office, terminate the Agreement under any of the following circumstances:
- (i) Failure to perform any obligation(s) under the Agreement;
 - (ii) Failing to rectify, within the time prescribed, any defect as may be pointed out by the Administrator.
- 4.10.2 The Agreement shall stand terminated forthwith in case the USP goes into liquidation or is ordered to be wound up.
- 4.10.3 Provided that if the respective CMTS/ UASL/UL license is terminated, as the case may be, then the Agreement for setting up and managing Infrastructure sites and provision of mobile services based on this bidding process shall also stand terminated forth-with.
- 4.10.4 Wherever considered appropriate, Administrator may conduct an inquiry to determine whether there has been any breach in compliance of the terms and conditions of the Agreement by the USP and upon such inquiry the USP shall extend all reasonable facilities and shall endeavour to remove the hindrance of every type.



रामेश्वर धारिवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

4.10.5 It shall be the responsibility of the USP to maintain the Quality of Service as per conditions of the Agreement during the period of notice for termination of Agreement; otherwise this shall be a cause for invocation and forfeiture of PBG.

4.11 ACTIONS PURSUANT TO TERMINATION OF AGREEMENT

4.11.1 Wherever the Agreement is terminated prematurely, retendering may be done.

4.11.2 If the Quality of Service (QoS) had not been maintained as per standard prescribed hereto during the notice period then no subsidy for the notice period shall be payable.

4.11.3 In case of termination of the Agreement before the expiry period, the prescribed PBG will be encashed and forfeited towards damages. Additionally, if it is found that the USP had received any payment in excess of the amounts under the Agreement prior to termination, then such amount shall be paid back immediately by the USP to the Administrator.

4.12 INDEMNITY

Refer clause no. 8 of the section I of this Agreement.

4.13 DISPUTE SETTLEMENT

Refer clause no. 9 of the section I of this Agreement.

4.14 FORCE- MAJEURE

4.14.1 If at any time, during the continuance of the Agreements, the performance in whole or in part, by either party, of any obligation is prevented or delayed, by reason of war or hostility, acts of the public enemy, civic commotion, sabotage, Act of State or direction from Statutory Authority, explosion, epidemic, quarantine restriction, strikes and lockouts (not limited to the establishments or facilities of the USP), fire, floods, natural calamities or any act of GOD (hereinafter referred to as EVENT), provided notice of happenings of any such EVENT is given by the affected party to the other, within 10 Calendar days from the date of occurrence thereof, neither party shall, by reason of such event, be entitled to terminate the Agreement, nor shall either party have any claims for damages against the other, in respect of such non-performance or delay in performance. Provided 4G based mobile services under the Agreement shall be resumed as soon as practicable, after such EVENT comes to an end or ceases to exist.

4.14.2 The decision of the Administrator as to whether the service may be so resumed (and the time frame within which the service may be resumed) or not, shall be final, binding and conclusive.

4.15 SET OFF CLAUSE

4.15.1 In the event any sum of money or claim becomes recoverable from or payable by the USP to the Administrator either against the Agreement or otherwise in any manner, such money or claim can be (without restricting any right of set off for counter claim given or implied by law) deducted or adjusted against any amount or sum of money then due or which at any time thereafter may become due to the USP under this Agreement or any other Agreement or Contract between the Administrator and the USP.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एन.ओ.एफ.
Director (T-1) USOF
सूचना विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

- 4.15.2 The aforesaid sum of money payable by the USP shall include any valuable security convertible into money.
- 4.15.3 After exercising the right of set off, a notice shall always be given immediately by the Administrator to the USP.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptl. of Telecom, Govt. of India
नई दिल्ली/New Delhi

रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptl. of Telecom, Govt. of India
नई दिल्ली/New Delhi

SECTION – V: TECHNICAL CONDITIONS

5.1 GENERAL

- 5.1.1 The Technical Specifications of the scheme for provision of 4G based mobile services from the infrastructure sites set up in Arunachal Pradesh are explained in the forthcoming clauses.
- 5.1.2 The requirements specified herein are the minimum requirements to be complied. USP has to expand /upgrade the eNode-B infrastructure to enhance capacity and provide advanced services based on the traffic/public requirement.
- 5.1.3 The USP shall work within the framework of the Technical conditions of the CMTS/ UASL/UL Agreement. The Technical requirements of the scheme shall supplement "General Conditions" as contained in Section-III & "Commercial Conditions" as contained in Section-IV.
- 5.1.4 The USP shall abide by the existing land laws, labour laws, local customs and the best of prevalent latest practices in the Industry.
- 5.1.5 Administrator, USOF shall not be responsible for any breach of such Act(s)/ Law(s) by the executing entities for whatsoever may be the reason.
- 5.1.6 USP shall be solely responsible to set up, operate and maintain the 4G based mobile services in identified areas by installing the following Components:
- (i) Mobile Tower
 - (ii) eNode-Band associated radio access network equipment,
 - (iii) Associated antennas,
 - (iv) Backhaul connectivity to core networks,
 - (v) Power/RET arrangements and back-up
 - (vi) Other necessary equipment and
 - (vii) Associated civil and electrical works required to provide 4G based mobile services

5.2 The list of sites to be commissioned in Arunachal Pradesh is at **Appendix-1**.

5.3 TOWER

- 5.3.1 The minimum requirements of Towers and eNode-B configurations are given in Table 5.1. USP may deploy the equipment of enhanced capacity/capability as per traffic requirement. These are the minimum requirements of Towers and eNode-B configurations. USP may deploy the equipment of enhanced capacity/capability as per traffic requirement; however, the subsidy payment will be made as per approved representative rates of the nearest lower configuration subject to the variation clause.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एच.ओ.एच.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

Table- 5.1

S.No.	Particular	Technical Requirement
1.	Tower Height	30M for A type eNode-B and 40M for B Type eNode-B
2.	Radiating power	20W
3.	ENode-B Configuration	1+1+1
4.	Antenna Type	Sectoral Antenna
5.	Minimum Radial coverage	4KM
6.	Minimum backhaul bandwidth	VSAT of 8Mbps and OFC/MW of 15Mbps
7.	Services	Voice, SMS and Data

Note: The 4KM coverage requirement as per point no. 5 of Table 5.1 has been put as the capacity/ capability of the eNodeB. In some cases, however due to terrain/ geo-climatic conditions etc. 4KM coverage may not be feasible

- 5.3.2 Tower shall conform to Generic Requirements of Telecom Engineering Centre GR No. GR/TWR-11/01.DEC 2004 for 30 and 40 M height.

(OR)

Alternatively, tower design shall be as per design approved from an organization like Structural Engineering Research Centre (SERC)/ TEC/ IITs for structural fitness, safety, load bearing capacity, ability to withstand minimum wind speed of 180 Km/Hr., *after applying various topological factors including allowable soil bearing capacity*. Necessary certification from an agency like Structural Engineering Research Centre (SERC)/ TEC/ IITs shall be submitted by USP at the time of testing for Proof of Concept as per clause 5.13.1.

- 5.3.3 Towers shall be located in the villages as specified in Appendix-1 of the Agreement to provide 4G based mobile services in those areas.
- 5.3.4 The USP shall make their own arrangements to get the further detailed map of the area to be covered or any other data relevant and necessary for planning & engineering of the 4G based mobile services. The USP has to ensure coverage in the villages mentioned against each tower location in Appendix-1 of the tender document.
- 5.3.5 Installation of tower and associated infrastructure in an uncovered village is not required if it is already covered from any type of technology i.e. 2G or 3G or 4G or a combination thereof through any TSP. The USP is advised to verify non-availability of the coverage in the villages before installing equipment for which it intends to claim support from Universal Service Obligation Fund. No claims shall



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एस.ओ.एफ.
 Director (T-1) USOF
 दूरसंचार विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली / New Delhi

be admissible for cases of duplicate/ redundant infrastructure sites/ towers. Date of survey is to be considered as the cutoff date for existing coverage validation.

- 5.3.6 Care shall be taken to ensure that all proposed infrastructure sites are at a specified distance from the international borders as per the license conditions/ guidelines issued by DoT. However, if any infrastructure site lies within the specified distance from the international border, the same shall be dealt in accordance with the conditions stipulated in this regard in the license Agreements and the same shall also be brought to the notice of Administrator.
- 5.3.7 SACFA clearance shall be the responsibility of the USP.
- 5.3.8 Each tower, including the antenna system and other equipment mounted on the tower shall be strong enough to resist winds with a velocity as indicated in Clause 5.3.2 and to suffer no serious vibrations or torsion, which may deteriorate the network performance. Under operational wind speed, torsion and sway of the structure shall be limited to ± 0.5 degrees, when carrying full or intermediate complement of antennas.
- 5.3.9 The USP shall be responsible for the safety during transportation, handling and erection of tower and associated equipment.
- 5.3.10 The USP shall maintain on site detailed calculations, standards of materials and specification data on the deflection limit of towers and the safety factor used in tower erection, as well as detailed drawings. Alternately, site wise all data can be made available centrally.
- 5.3.11 To conform to Civil Aviation regulations the towers shall be painted in alternate bands of international orange and international white, terminating with orange at top and the bottom, Height of each band should not exceed 6 meters and should not be less than 0.5 meters. The correct shade for the international orange corresponds to ISI shade 592 as given in the Indian Standard Institution Publication-colours for ready mixed paint.

5.4 SIGN BOARD

The USP shall provide a signboard of size of at least 1.5 meters x 1 meters on the tower indicating on it the name of the village, date of installation and name of the IP/ USP and that the infrastructure site has been supported by USOF. The letters on the signboards should be bold enough so that the same are clearly visible from a distance of at least 10 meters.

5.5 POWER Requirement

- 5.5.1 Grid Power connectivity is to be provided for all the sites. USP may commission the site on alternate source while maintaining the mobile services as per Quality of Service set by TRAI. The Grid power connectivity, if not available at some sites, at the time of installation, may, however, be provided at the earliest for these sites.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली/New Delhi

5.5.2 For the purpose of backup power calculation, 1 day of battery autonomy has been taken in each site. Following combination of power source is to be provided for all sites.

Type of energy source	Capacity
Battery	800 AH (Valve Regulated Lead Acid Type)
Alternate power source	DG (7KVA) Or Solar of adequate capacity

5.5.3 The USP shall comply to the minimum power arrangement and battery autonomy as per above, however, if required, USP shall install additional power source to meet the uptime requirement as per TRAI guideline. However, there shall be no extra financial support from USOF.

5.5.4 Capacity of the Battery sets shall be planned such that the battery set is not required to be discharged beyond its rated capacity at any time to meet 100% load.

5.5.5 The battery shall have Output Voltage (say -48V /-24V) depending on the BTS used.

5.5.6 Power unit should be complete with CCU, Power distribution, auto switching unit and remote sensors.

5.5.7 Power plants are to be compatible with the batteries and are to be equipped with Battery Health Check systems and Remote Monitoring facility.

5.5.8 Suitable switching arrangement for inter connection between various items of CCU/SMPS Power Plants, Battery sets and their interconnection in switching cubicle and further power distribution to equipment as required for the ultimate capacity shall be provided.

5.5.9 Complete drawings for power plant and battery and information regarding inter-connecting arrangements and layout shall be made available on site. Maintenance spares including spares for control panel and spare fuses should also be provided at the site. On site availability of this data may not be feasible, so the same could be provided by the USP from a central location.

5.5.10 Integrated Power units supporting above functionalities may also be used.

5.6 eNode-B

5.6.1 The eNode-B shall be based on LTE Technology. Minimum requirements are:

- Voice Service,
- SMS
- Data communication services: Minimum 512 Kbps at cell boundary at 4KM and for VSAT site data rate may be proportionately available as per backhaul of 8Mbps. The 4KM coverage requirement has been put as the capacity/capability of the eNodeB. In some cases, however due to terrain/ geo-climatic conditions etc. 4KM coverage may not be feasible.

5.6.2 The eNode-B shall be of Outdoor versions and preferably tower mounted.

5.6.3 Latest EMI Radiation norms of DoT shall be complied.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एफ.ओ.एफ.
 Director (T-1) USOF
 दूरसंचार विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली/New Delhi

- 5.6.4 eNode-B complying to the requirements given in table 5.1 shall be provided.
- 5.6.5 The Outdoor eNode-B shall be suitable for operation without air-conditioning. Outdoor BTS with proper protection with respect to dust, rust and other environmental degrading factors shall be provided. Minimum standard should be IP 66.
- 5.6.6 The eNode-B shall meet the service requirement mentioned in TSTP document issued by DoT for 4G mobile services.

5.7 BACKHAUL CONNECTIVITY

- 5.7.1 Backhaul Technology may be Microwave or Optical Fibre Cable (OFC) or VSAT. Necessary coordination will be facilitated by USOF, if required, for getting RoW, without any relaxation in timelines. However, RoW permission is the responsibility of the USP.
- 5.7.2 The satellite bandwidth charges shall be separately provided quarterly to the USP over and above EQS for 8 Mbps bandwidth per site, for maximum 15% (147) sites for maximum up to 2 years, based on actual deployment of VSAT media, at the rate Rs. 2.11 Lakh per Mbps per annum or the actual rate on which payment is made by USP, whichever is lower. USP may convert these VSAT sites on microwave/OFC backhaul before 2 years from the date of commissioning. However, USP is free to continue VSAT backhaul of minimum 8 Mbps even beyond 2 years but the subsidy for VSAT bandwidth shall be limited up to 2 years as per tender. No support for VSAT bandwidth charges beyond 2 years shall be provided.
- 5.7.3 The sites installed with satellite backhaul should have minimum bandwidth of 8 Mbps and sites installed with microwave/OFC backhaul should have minimum bandwidth of 15 Mbps.
- 5.7.4 Radio Modems may be used as backhaul as an alternative to Microwave. If ISM band is used, USP shall ensure secured and interference-free communication and data services meeting QOS requirements specified in this document.
- 5.7.5 The backhaul equipment installed shall work without the need for Air-conditioning. The backhaul equipment is the responsibility of the USP and necessary provisioning of air conditioning, if required, to be done by the USP only.

5.8 COVERAGE SPECIFICATIONS

- 5.8.1 The equipment to be installed shall have adequate RF filtering in the transmitter and receiver to avoid adjacent channel interference to any other system or to any other operator and to meet the receiver sensitivity / specifications of the equipment in the network.
- 5.8.2 Details of the signal coverage actually achieved and number of villages actually covered shall be provided by USP in the Self-certification as per **Annexure-3**.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एन.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली/New Delhi

5.9 FIRE ALARM & FIRE EXTINGUISHERS

- 5.9.1 Proper arrangement shall be made for fire detection and fire extinguisher system as per fire safety norms applicable for that location.
- 5.9.2 Fire alarm system is to be provided for each site.

5.10 QUALITY OF SERVICE PARAMETERS

- 5.10.1 The Quality of Service Parameters for Mobile Telecommunication Services as prescribed by TRAI shall be complied.
- 5.10.2 The USP shall ensure provision of reliable services to the customers as per the Quality of Service (QoS) prescribed by the TRAI from time to time. The USP shall adhere to such QoS standards and provide timely information as required therein.
- 5.10.3 The Administrator or TRAI may carry out performance tests either directly themselves or through an Agency Authorized by Administrator, USOF and also evaluate the QoS parameters at any time during the tenure of the Agreement. The USP shall provide ingress and other support including documents, instruments, equipment etc. for carrying out such performance tests and evaluation of Quality of Service parameters.
- 5.10.4 The USP will keep a record of peak latched customers to the eNodeB installed under the scheme and the telecom traffic generated & registered from each site. The USP shall also maintain faults and rectification reports of the eNode-B, Backhaul, Antenna, Battery, Power Plant and other related details in respect of the service rendered which will be produced before the Administrator and/or TRAI as and when and in whatever form desired. The USP shall submit mandatory quarterly and other periodic network reports to TRAI with a copy to Administrator, USOF.
- 5.10.5 The USP shall be responsive to the complaints lodged by the customers. They shall rectify the deficiencies and maintain the history sheets for each installation, statistics and analysis on the overall maintenance status.
- 5.10.6 Proper arrangement should be made by the USP for reporting/ booking service-related complaints.

5.11 GENERAL GUIDELINES

- 5.11.1 The power backup of suitable capacity shall be provided to cater to the backup requirements of each site by the USP.
- 5.11.2 Factory Test Certificates are to be provided for items like eNode-B and accessories, Transmission equipment, power equipment and infrastructure provided.
- 5.11.3 Detailed documentation related to periodical maintenance and procedure for faulty part replacement shall be supplied.
- 5.11.4 Logbooks/ Reports of site maintenance are to be maintained.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

5.11.5 All types of activities are to be recorded either manually or through system generated log.

5.11.6 External Alarms shall be extended to OMC-R.

5.12 CONFORMITY WITH EXISTING LICENSES

USP (Successful CMSPs/ UASL/UL) shall work within the framework of the Technical conditions of CMTS (Cellular Mobile Telephone Services)/ UASL (Unified Access Service Licensees)/ Unified License.

5.13 PROOF OF CONCEPT AND PHYSICAL VERIFICATION

5.13.1 USP shall install and offer one site of both the categories (A & B) for validation of functional parameters (Proof of Concept) to Testing Agency designated by USOF.

5.13.2 The Proof of Concept shall be conducted in accordance with standard test schedule, to be issued by USOF. For other tests such as drive test etc., latest TSTPs issued by DoT will be applicable.

5.13.3 Release of subsidy payments will start only after the Proof of Concept is approved.

5.13.4 Physical verification for all sites under the scheme shall be conducted by an Agency to be authorised by the Administrator, USOF, as per **Annexure-3**.

5.13.5 Self-certification shall be furnished by executing entities along with test results, including drive test results for all sites in prescribed format (as at **Annexure-3**).

5.14 Mobile Charging Facility:

Adequate number of Mobile Charging Facilities shall be provided at each location to the users. The equipment shall support charging of at least four mobile phones simultaneously. The facility shall be available on 24x7 basis. Renewable Energy Technology (RET) based mobile charging facility is desirable.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एच.डी.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

भारत खंडात
दूरसंचार विभाग
नई दिल्ली

SECTION – VI: OPERATING CONDITIONS

6.1 CUSTOMER SERVICE

The terms and conditions of the CMTS or UASL or UL License Agreement, as applicable, shall prevail and shall be binding *mutatis mutandis*. The same shall also be applicable in case of migration to or award of new license in lieu of the CMTS/UASL/UL license.

6.2 RIGHT TO INSPECT, TEST AND MONITOR

6.2.1 The Administrator or his authorized representative shall have the right to inspect the infrastructure sites created for providing the 4G based mobile services and also the equipment installed by the USP at the Infrastructure site so created in particular but not limited to, access to NOC/NMS, backhaul, terminating interfaces, distribution frames etc. and conduct the service performance tests. The USP will provide the necessary facilities at own cost for monitoring of the system, as required by the Administrator or its authorized representative(s). The Inspection will ordinarily be carried out after reasonable notice except in circumstances where giving such a notice will defeat the very purpose of the inspection.

6.2.2 Wherever considered appropriate Administrator may conduct any inquiry either *Suo motu* or on a complaint, to determine whether there has been any breach in compliance of terms & conditions of the Agreement by the USP, and during such inquiry the USP shall extend all reasonable facilities without any hindrance.

6.2.3 Online access to Network Operations Centre (NOC)/Network Management System (NMS) shall be provided to USOF representatives authorised by the Administrator. Web based access to NOC/NMS is desirable.

6.3 PROVISIONING OF 4G BASED MOBILE SERVICES

6.4 The USP shall ensure that peak latched customers to the eNodeB installed under the scheme as mentioned in the monthly report have actually been provided service in the area being served by the eNode-B installed with the subsidy support from USO Fund. A certificate to this effect is to be provided by the USP in the monthly report in the prescribed proforma, **Annexure-5. UPGADATION OF EQUIPMENT**

The USP may upgrade the existing equipment by installing new equipment, if required, during the validity of the Agreement provided it meets all other performance parameters of Quality of Service. USP shall not claim any charges for such up-gradation.




रमेश्वर धरियावाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptl. of Telecom, Govt. of India
नई दिल्ली/New Delhi

6.5 ROLL OUT

- 6.5.1 The indicative locations (Latitude, Longitude) for each site are given at Appendix-1 to the Agreement. The USP, based on field survey, shall determine the optimum type of infrastructure and location for each site to ensure coverage of maximum population in the area, and finalize implementation plan in consultation with Agency to be appointed by Administrator, USOF. The percentage variation permitted for each type of infrastructure (Category-A, Category-B,) in the bidding unit shall be within +25% of the Quantities specified herein.
- 6.5.2 The USP shall complete the field survey for at least 30% of sites in the bidding unit in three months from the date of signing of the agreement, at least another 30% of sites in six months from the date of signing of the agreement and the remaining sites in nine months from the date of signing of the agreement to finalize location and type of infrastructure (A&B,) at each site. The USP shall commission and provide 4G based mobile services from all the infrastructure sites within a period of 18 months from the date of signing of the Agreement.
- 6.5.3 The Rollout period may be extended by the Administrator by Six months without LD charges, if reasons for delay submitted by the implementing USP are justified.
- 6.5.4 The USP shall provide a monthly statement in the format prescribed in **Annexure-5** giving details of the sites commissioned and traffic generated from each site during the month from the sites commissioned respectively.

6.6 LIQUIDATED DAMAGES

- 6.6.1 For the infrastructure sites not commissioned as per the rollout required to be achieved, without prior written concurrence of the Administrator, the delayed period shall entail recovery of liquidated damages (L.D.). Provided further, that for the infrastructure sites that are provided within 30 calendar days of the expiry of the rollout period from the effective date by the USP, the Administrator shall accept the infrastructure site without levy of any L.D. charges.
- 6.6.2 For any shortfall in providing the required number of infrastructure sites and providing the 4G based mobile services (commissioning of eNodeB) after thirty days of the expiry of the Roll-out period as per Clause 6.5, the Administrator shall be entitled to impose and recover Liquidated Damages at the rate of 2% of the Category-specific Representative Rate per site, for those Infrastructure sites for each calendar month of delay or part thereof, subject to maximum of five months delay i.e., max LD shall be 10% of the Category specific Representative Rate for each site, beyond a grace of one month as per Clause 6.6.1.
- 6.6.3 For the purpose of charging the Liquidated Damages, the Representative Rate per site, as discovered in the tendering process, where the relevant roll out obligation of providing 4G based mobile services from Infrastructure/eNode-B sites has not been fulfilled, shall be taken into account.



रामेश्वर धरिवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यु.एन.ओ.एच.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली/New Delhi

6.6.4 In case, the USP fails to roll out the mobile services from the infrastructure sites within 6 months after the expiry of roll-out period, action as per Clause 7.5 of Section VII: Financial Conditions shall be taken and action, as per Clause 4.10 and 4.11 of Section-IV: Commercial Conditions of this Agreement, may be taken.

6.7 CONFIDENTIALITY OF INFORMATION

The terms and conditions as to confidentiality of information of the CMTS or UASL or UL Agreement, as the case may be, shall be binding mutatis mutandis.

6.8 PROHIBITION OF CERTAIN ACTIVITIES BY THE UNIVERSAL SERVICE PROVIDER

The terms and conditions as to prohibition of certain activities of the CMTS or UASL or UL Agreement, as the case may be, shall be binding mutatis mutandis.

6.9 SECURITY CONDITIONS

The terms and conditions as to security conditions of the CMTS or UASL or UL Agreement, as the case may be, shall be binding mutatis mutandis.

6.10 SECURITY CLAUSE AS PER LATEST GUIDELINES AND REQUIREMENT

6.10.1 Mandatory Licensing requirements, policy guidelines, etc., with regards to security related concerns issued by the Government of India from time-to-time shall be strictly followed.

6.10.2 If the entity is found indulging in acts inimical to India's national security, the tender/agreement is liable to be terminated and matter will be reported to concerned authorities for suitable legal/criminal action.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली, New Delhi

SECTION – VII: FINANCIAL CONDITIONS

7.1 SUBSIDY FROM UNIVERSAL SERVICE OBLIGATION FUND

- 7.1.1 Support shall be payable as Category-specific Representative Rate for each site arrived on the basis of the outcome of the bidding process as per details given in Annexure-I.
- 7.1.2 The Representative Rate (RR) of total subsidy support, for each category may vary depending on the location of tower in uncovered villages, type of tower/eNode-B and backhaul type.
- 7.1.3 The Representative Rate (RR) of subsidy emerging from the bidding process is specified in the Annexure – 1 of the Agreement and shall be disbursed in Indian Rupees to the USP for the scheme in two parts- Front Loaded Subsidy (FLS) & Equated Quarterly Subsidy (EQS).
- 7.1.4 First part shall be due and payable, @ 49% of the Category-specific RR, as an FLS at the time of successful commissioning of eNode-B and provision of 4G based mobile services from the identified site. Second part of the subsidy (50%), for each site shall be payable in 20 equated quarterly Subsidy (EQS). These EQS shall be payable over a maximum period of 5 years from the date of commissioning of eNode-B i.e. commencement of 4G based mobile services from the sites identified under the Agreement or up to the expiry of the currency of the Agreement, whichever is earlier. The satellite bandwidth charges shall be separately provided quarterly to the USP over and above EQS for 8 Mbps per site, for maximum 15% (147) sites for maximum up to 2 years, based on actual deployment of VSAT media at the rate of Rs. 2.11 Lakh per Mbps per annum or actual rate on which payment is made by USP, whichever is lower.
- 7.1.5 The Administrator, USOF shall appoint Third Party Agency (TPA) as per departmental procedure to whom maximum 1% of the Representative rate of subsidy emerging from the bidding process will be paid directly. Further, Equated Quarterly Instalment shall be released after verification by a Third-Party Agency (TPA), unless specified otherwise by Administrator.
- 7.1.6 The FLS & EQS components of the subsidy shall be payable within 30 days from the end of quarter, in which it becomes due. Thus, the USP shall be eligible to claim FLS only at the end of the quarter in which the 4G based mobile services are commissioned/ launched from the infrastructure site set up. Similarly, the EQS claim for a quarter can be made by the USP only at the end of that quarter.
- 7.1.7 USOF subsidy will be paid only in respect of the sites where mobile tower with backhaul and associated equipment is installed, commissioned and provision of mobile services (4G) has been made, as per the terms & conditions of the Agreement, duly verified by TPA/Agency authorized by Administrator, USOF, will



रामेश्वर धरियाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

be limited to the number of sites in each Category, subject to the Variation Clause 2.3 of this agreement.

7.2 SCHEDULE FOR DISBURSEMENT OF SUBSIDY

- 7.2.1 The validation/approval of the PoC by USOF as per Clause 5.13 & submission of the same would be a pre-requisite for any release of the subsidy payments. The USP shall be eligible to submit the claim for FLS (49%) within 30 days from the end of quarter in which the 4G based mobile services are commissioned/ launched from the infrastructure site set up. USP shall submit a self-certificate to the respective Controller of Communication Accounts (CCA) office, giving details of the infrastructure site(s), the equipment installed along with system generated reports, traffic reports etc. establishing successful completion/ launch of the 4G based mobile services work as per the proforma given in **Annexure-3**, with a copy to Administrator, USOF.
- 7.2.2 The EQS of remaining 50% subsidy from USOF shall be disbursed by the respective Controller of Communication Accounts office in 20 quarterly instalments during each financial year, within 30 days from the end of quarter. The claim for a part of the quarter will be computed with reference to the actual number of days in that quarter. Each instalment shall be disbursed quarterly generally within 30 days of receipt of a valid claim for the services rendered.
- 7.2.3 The USP shall submit the claim for quarterly subsidy in a statement in the prescribed form given in the three Attachments (A, B & C) to **Annexure-2** showing the computation of subsidy for the quarter. The statement shall be furnished by the USP even if no new Site has been set up during the quarter for provision of 4G based mobile services. The subsidy claim should be submitted in the prescribed formats on a hard copy duly signed by the authorized signatory of the Company.
- 7.2.4 Following supporting documents shall be submitted along with the prescribed Claim Statement and thus are integral part of the subsidy claim:
- The claim shall be duly certified as per prescribed affidavit pro forma as mentioned in **Annexure-2** on a stamp paper by a representative of the USP duly authorized by a board resolution of the USP.
 - All claims for subsidy shall be accompanied by a pre-receipted bill with revenue stamp.
 - In addition to the hard copy, the USP should also submit the claim on a CD ROM in MS Excel format also. The authorized signatory of the company should put his signature and seal of the company on the CD ROM Disc.
 - Monthly statement of Sites Commissioning & mobile traffic generated for the quarter, as per **Annexure-5** and Service interruption report as per **Annexure-6** duly certified by concerned DoT Licensed Service Area unit, the USP (along with




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) डी.एन.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

Annexure-5) shall also provide name of villages (along with Census Code) covered by the installed tower.

(e) Self-Certificate as per **Annexure-3** along with test results, as per Clause 5.13 of the Section V: Technical conditions, with the FLS claim.

7.2.5 The claim along with the supporting documents should be submitted within 30 days from the end of the quarter. Condonation of delays for claims received after this date may be considered by the Administrator under exceptional circumstances.

7.2.6 The claims along with the supporting documents should be submitted at the designated Controller of Communication Account Offices of the respective Licensed Service Area.

7.2.7 Penalty for interruption:

Deduction in subsidy (EQS) shall be made from USP on pro-rata basis, if there is interruption in services for more than 43.2 hours (cumulatively) in a quarter; and the entire EQS shall not be payable for that particular site, if there is interruption in services for 45 days or more in a quarter. The USP shall furnish the details of interruption/ down time of the services along with the payment statement as per the pro forma attached at **Annexure-6**. In addition, the USP, as Licensed Access Service Provider shall be bound by and shall comply with the relevant regulations of TRAI for QoS.

7.2.8 Processing of Front-Loaded Subsidy (FLS) & Equated Quarterly Subsidy (EQS) claims of USP for subsidy disbursement and settlement shall be as per the terms & conditions of the Agreement and through the Office of the designated Controller of Communication Accounts (CCAs) of the respective Telecom Service Area. However the claims of USP would be said to be settled only after adjustment & recovery of any pending LD, penalties, dues, etc. as liable as per the Agreement or recovery of inadmissible/excess subsidy for a site as ascertained on the basis of physical verification by an Agency authorized by Administrator, USOF as per Clause 5.13 & sample inspection conducted by TPA /Administrator representative during the Agreement period, as per instructions issued thereunder for compliance of its provisions, as per the inspection/verification schedule to be prescribed later by USOF.

7.2.9 The aforesaid quarterly statements of each year shall be required to be audited by the auditors of the USP appointed under Section-224 of the Companies Act, 1956 or Section 139 or any other relevant section of the New Companies Act, 2013. The report of the Auditors should be in the prescribed form given in **Annexure-4** to be filed with the Administrator or an authorized agency /CCA as specified within 7 (seven) calendar days of the date of signing of the audit report but not later than 30th September of the following year.



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एन.ओ.एक.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

- 7.2.10 The subsidy for a quarter shall be paid after making adjustments, if any, for the payments made in the previous quarter(s).
- 7.2.11 Final adjustment, if any in respect of excess or shortage in the subsidy disbursed shall be made in the following year based on the quarterly statements duly certified by the auditors of the USP.
- 7.2.12 In case the USP is found to have claimed and received in excess of 10% of the subsidy due to them, the entire amount in excess shall be recovered along with an interest from the date of disbursement at the prime lending rate (PLR) of State Bank of India prevalent on the day the disbursement was made. The interest shall be compounded monthly and a part of the month shall be reckoned as a full month for the purposes of calculation of interest. (Month for this purpose shall be taken as an English calendar month). No further subsidy shall be disbursed until final adjustment of the excess payment.
- 7.2.13 No interest shall be payable for any short/late payment made to the USP by the paying authority.
- 7.2.14 All the relevant records, systems, relevant NOC (Network Operation Centre)/ Network Management System (NMS) data, logbooks, books of accounts of the USP shall be subject to such scrutiny & examination as may be prescribed by the Administrator so as to facilitate independent verification of the subsidy claimed and paid.
- 7.2.15 In order to ensure effective utilisation of the USO fund released for rendering the obligations by USP and proper and correct verification of subsidy paid & ensuring compliance, for the deliverables and agreement conditions, as claimed in its subsidy claim, over the period of the Agreement, the Administrator can issue instructions/directions, prescribe inspection & verification guidelines/procedures, formats for monitoring performance, formats and certificates with respect to physical and financial progress of the project, financial reports for reconciliation and also can modify, alter, or substitute and amend, if deemed necessary, whatever stated in the Agreement.

7.3 BANK GUARANTEES

- 7.3.1 The USP shall submit a Performance Bank Guarantee (PBG) to Administrator USOF in the prescribed proforma valid for 6 months beyond the validity of Agreement, from any scheduled bank in India. The amount of Performance Bank Guarantee shall be Rs. 23,21,19,000/- (Rupees Twenty Three Crore Twenty One Lakh and Nineteen Thousand only) (equivalent to 3% of total subsidy amount payable to the USP, as specified in the **Annexure-1**, for which work has been awarded to the USP). The PBG must be submitted within Fifteen days of issue of letter of intent and before signing of the Agreement.
- 7.3.2 Initially, the bank guarantee (s) shall be valid for a period of Two years. The USP, on its own, shall extend the validity period of the bank guarantee(s) on similar



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL 30
निदेशक (टी-1) यू.एन.ओ.एन.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

terms at least one month prior to the day of its expiry without any demand or notice from the Administrator for a period of one year.

7.3.3 The bank guarantees shall be kept valid for an extended period of six months beyond the period of Agreement or till finalization of accounts i.e. issue of no-dues certificate from the concerned CCA and final settlement of all the subsidy claims, and adjustment & recoveries of any pending LD, penalties, dues, excess claim etc. as per the Agreement & instructions issued thereunder, whichever is later. Any failure to do so, shall amount to violation of the terms of the Agreement and entitle the Administrator to encash the bank guarantee(s) and to convert it into a cash security without any reference to the USP at its risk and cost. No interest or compensation whatsoever shall be payable by the Administrator on such encashment.

7.3.4 Without prejudice to its rights of any other remedy, Administrator may encash bank guarantee and forfeit the amount upon any failure of performance of the terms & conditions of the Agreement by the USP.

7.4 MAINTENANCE OF RECORDS

7.4.1 The Administrator or its authorised representative shall have the right to call for and the USP shall be obliged to maintain, supply and provide for examination the relevant books of accounts, financial records and provide access to its systems and any other records that it maintains in respect of the business carried on to provide the service(s) under this Agreement at any time.

7.4.2 The USP shall invariably preserve all accounting and financial records and other records (electronic as well as hard copy) for a period of three years from the date of publishing of duly audited & approved accounts of the company or until the finalization of accounts, whichever is later. Any dereliction thereof shall be treated as a material breach independent of any other breach, sufficient to give a cause for termination of the Agreement.

7.5 NON-PERFORMANCE PENALTY

7.5.1 In case, USP fails to commission & provide 4G based mobile services from a site(s), within six months of the expiry of the roll-out period (as stated in Clause 6.5), action as per Clause 6.6 shall be taken. In addition, non-performance-penalty @ 5% of the Representative Rate per site shall be payable, in respect of sites not commissioned, as penalty by the USP and the site(s) would be deleted/struck-off from the Agreement. Administrator reserves the right to take necessary action, as deemed fit for provisioning of 4G based mobile services from such sites.

7.5.2 USP shall indemnify and at all times keep the Administrator, USOF indemnified against any loss to it or any claims by any third person. The USP shall be solely responsible to deal with any/all dispute(s)/issue(s) arising out of the said deletion of the site(s) from the Agreement and consequences thereof.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एन.जी.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

7.6 EXIT Policy:

- 7.6.1 A notice of at least 90 days (three months) shall have to be given by the USP seeking exit from the entire scheme in the bidding unit to Administrator, USOF.
- 7.6.2 Date of Exit shall be the date of expiry of three months' notice for exit as given by the USP seeking exit.
- 7.6.3 USP shall pay 50% of the total subsidy amount payable to the USP for the bidding unit, as penalty, as specified in the tender document, for premature exit/withdrawal from the entire scheme.
- 7.6.4 It shall be the responsibility of USP to maintain the Quality of Service as per conditions of the Agreement during the notice period also. If the Quality of Service is not maintained as per standards prescribed in the Agreement during the notice period, then a *Penalty as per Clause 7.2.7* shall be imposed & recovered from the USP.
- 7.6.5 Exit from already commissioned sites will be subject to Terms and Conditions of relevant Telecom License Agreement signed by USP with DoT.
- 7.6.6 Exiting USP shall be solely responsible to deal with any/all dispute(s)/issue(s) arising out of the said exit and consequences thereof including inter-alia matters related to continuity of services to subscribers, compliance to pertinent clauses of relevant telecom license agreement under which USP is operating.
- 7.6.7 In addition, the Administrator shall terminate the Agreement and take action as per Clause 4.11 and recover any Liquidated damages and non-performance penalty, if applicable.



रामेश्वर धारियाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली/New Delhi

SECTION – VIII: SPECIAL INSTRUCTIONS to the U.S.P.

- 8.1 After signing of the Agreements by USP with Administrator USOF, USP shall rollout as per schedule given in clause 6.5.
- 8.2 For shifting of the location of the site/tower from one place to another, the USP shall take up the case for change of location with Administrator as per the prescribed proforma attached at **Annexure-8**.
- 8.3 For installation of additional site(s) or deletion, the USP shall take up the case with Administrator as per the prescribed proforma attached at **Annexure-7**. The variation shall be permitted with the prior approval of Administrator, USOF, subject to Clause 2.3 of this agreement.
- 8.4 The decision of the Administrator for according approval to such requests shall be final and binding on the USP. All the related clauses of the Roll out, LDs, Penalties, Suspension, Termination & other terms & conditions of the Agreement shall be applicable for these new locations also.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
सुरक्षा विभाग, भारत सरकार
Dept. of Telecom, Govt. of India
नई दिल्ली/New Delhi

SECTION – IX: INTERPRETATION OF TERMS/DEFINITIONS

Unless the context otherwise requires, the different terms and expressions used shall have the meaning assigned to them in the following paragraphs:

- 9.1 **ADMINISTRATOR** means the Administrator, Universal Service Obligation Fund in the Department of Telecommunications under Ministry of Communications.
- 9.2 **AGREEMENT** shall mean the Agreement signed by the USP with the Administrator for setting up and managing the infrastructure sites and for Provision of 4G based mobile services in Identified Uncovered Villages for each Implementing Unit, on the basis of the outcome of the bidding process.
- 9.3 **BENCHMARK** is the rate that shall form the upper ceiling for submission of bids and is the estimated rate of Net Cost support assessed in accordance with ITRs, 1951 and is based on a percentage of the capital recovery, depending on the revenue potential and operating expenditure net of revenue, incurred over a period of five years of operation against which the bids shall be received in the first round of financial bidding.
- 9.4 **CAPITAL RECOVERY** means the aggregate of depreciation, interest on debt and return on equity on the capital cost as worked out proportionately and annualized over the period for which support is provided from the Fund.
- 9.5 **DESIGNATED MONITORING AGENCY** refers to the agency authorized by the Administrator to carry out testing & inspection of the records, systems, claims and installations in order to ensure compliance with terms & conditions of the Agreement.
- 9.6 **EFFECTIVE DATE** is the date on which this Agreement comes into effect.
- 9.7 **EQS means** Equated Quarterly Subsidy.
- 9.8 **FLS means** Front loaded Subsidy.
- 9.9 **Infrastructure Providers-I (IP-I)** means IP-I registered with Department of Telecommunications.
- 9.10 **SITES** mean the locations for installation of tower & eNode-B for provision of 4G based mobile services, as per the terms & conditions of the Agreement and as identified in Appendix-1.
- 9.11 **LICENCE** means a License granted or having effect as if granted under the Section-4 of the Indian Telegraph Act, 1885 and the Indian Wireless Act, 1933.
- 9.12 **LICENSED SERVICE AREA** means the territorial jurisdiction as specified under the CMTS / UASL/UL Service License except the areas that may be notified to be excluded from time to time.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
सूचना विभाग, भारत सरकार
Deptl. of Telecom, Govt. of India
नई दिल्ली/New Delhi

- 9.13 LICENSEE** means a registered Indian Company that has been awarded License to provide the service (Basic and/ or CMTS and or Unified Access Service and or Unified License), within the geographical boundaries of the specified Licensed Service Area.
- 9.14 OPERATIONAL EXPENDITURE** means the Annual Operating Expense incurred on routine maintenance of infrastructure and recurring expenditures on diesel, electricity, security etc. including satellite bandwidth charges, to be paid by Universal Service Providers.
- 9.15 QUALITY OF SERVICE (QoS)** is evaluated on the basis of observable measure on the grade of service or the response time and also includes acceptable grade of number of faults per unit population of the subscriber served, the mean time to restore (MTTR), faults carried over beyond the MTTR and the satisfactory disposal thereof.
- 9.16 RURAL CONNECTIONS** mean the connections provided in the rural areas as identified by the Census 2011 and located in the areas served by the eNode-B site installed with the subsidy support from USO Fund.
- 9.17 SUBSIDY** from Universal Service Obligation Fund (USOF) means the disbursements from USOF towards meeting the universal service obligations in terms of the Agreement.
- 9.18 TRAI** means Telecom Regulatory Authority of India constituted under the TRAI Act, 1997 as amended from time to time.
- 9.19 UNIVERSAL SERVICE PROVIDER (USP)** means such entities like CMTS/ UASL/UL Licensees, which have entered into an Agreement with the Administrator for provision of specified Universal Service.
- 9.20 USO** means Universal Service Obligation as enunciated in the Indian Telegraph Act and the Rules framed there under.
- 9.21 USO FUND** means the fund established under the Indian Telegraph Act and the Rules framed there under.




 रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एस.ओ.एफ.
 Director (T-1) USOF
 दूरसंचार विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली/New Delhi

**ANNEXURE-1: DETAILS OF NUMBER OF UNCOVERED VILLAGES IN
ARUNACHAL PRADESH AND USOF SUBSIDY SUPPORT.**

S. No	Site Details (Villages) [Type of infrastructure]	No. of sites	Subsidy Amount per site (in Rs.)	Total subsidy Amount Category wise (in Rs.)
1	Uncovered villages (390) / [Type-A]	390	75,40,000	2,94,06,00,000
2	Uncovered villages (1293) / [Type-B]	590	81,30,000	4,79,67,00,000
	Total Sites	980		
	Total Subsidy (in figures)			Rs. 7,73,73,00,000
	Total Subsidy (in words)			Rupees Seven Hundred Seventy Three Crore Seventy Three Lakh Only

NOTE:

1. The subsidy is not liable to GST hence the Representative Rates are exclusive of taxes.
2. The subsidy rates for Uncovered Villages are excluding satellite bandwidth charges. The satellite bandwidth charges shall be separately provided to the USP for 8 Mbps per site, for maximum 15% (147) sites for maximum up to 2 years, based on actual deployment of VSAT media at the rate of Rs. 2.11 Lakh per Mbps per annum or actual rate on which payment is made by USP, whichever is lower.




RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एस.ओ.एफ.
 Director (T-1) USOF
 दूरसंचार विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली/New Delhi

ANNEXURE-2: Format for Certification of Subsidy Claim

AGREEMENT NO. _____ DATED _____

FOR

UNIVERSAL SERVICE PROVIDER

I, _____, aged about _____ years, s/o d/o of Shri _____, resident of _____, do solemnly affirm and state as under:

1. That I am _____ of _____ (Name of the Company), Universal Service Provider in _____ Licensed Service Area and I am duly authorized by the resolutions dated _____ passed by Board of Directors of the Company to furnish a Certificate on behalf of _____ (Name of the Company).
2. That a claim of Rs. _____ (Rupees _____) is being made for the period _____ to _____. The details of calculation of subsidy are as per Attachments enclosed.
3. That the contents of **Attachments A, B and C** are true and correct to the best of my knowledge, based on the records of the company, which are available for further verification by the appropriate authorities and that the **infrastructure has been commissioned & were functional and 4G based mobile services have been rendered** from the quarter in which they have been shown as installed & commissioned.
4. That the claim pertains to the 4G based mobile services commissioned after the date of entering into the Agreement.
5. That excess payment or shortage, if any, in the subsidy received shall be adjusted in the following year based on the quarterly statements duly certified by the Auditors of the Company and scrutiny as prescribed by the Administrator.



✓
रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOP
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

6. The services/ mobile connections provided under this Agreement have not been utilized in claiming subsidy under any other Agreement entered into with the Administrator.
7. No subsidy has been claimed for the period in which the 4G based mobile services remained disrupted during the quarter as per terms and conditions of the Agreement.
8. The 4G based mobile services shown as commissioned in the said quarter have been completed in the on the dateas provided in the claim.
9. I understand that Administrator or his representative shall have the right to inspect & verify the site and records & systems, during the currency of the Agreement and if any deficiency is observed the subsidy paid to the company shall be recovered forthwith, without prejudice to the right of Administrator to take any other action(s) as deemed fit.

For and on behalf of (Name of the company)

Signature of the authorized signatory of the bidder company




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एन.ओ.एन.
 Director (T-1) USOF
 दूरसंचार विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली/New Delhi

ATTACHMENT A TO ANNEXURE 2: SUMMARY CLAIM STATEMENT FOR QE FROM UNIVERSAL SERVICE PROVIDER

Name of Universal Service Provider : _____ Name of Implementation Unit : _____

S No.	State	Total No. of Mobile Service Sites to be provided (As per Agreement)	No. of Mobile Service Sites provided at the end of the previous quarter	No. of Mobile Service Sites added during the quarter	Total No. of Mobile Service Sites at which Mobile Service is functional	Total subsidy payable for the Mobile Service Sites in col 4 (from Col 15 of Attachment B)	Subsidy payable for Mobile Service Sites in col 5 (from Col 17 of Attachment C)	Total subsidy payable (7+8)	Remarks, if any
		Villages	Villages	Villages	Villages				
1	2	3	4	5	6	7	8	9	10
1									
2									

(Signature of Authorized Signatory) along with Company seal




रामेश्वर धारिवाल
RAMESHWAR DHARIVAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

ATTACHMENT B TO ANNEXURE 2: EQS CLAIM STATEMENT FOR QE FROM UNIVERSAL SERVICE PROVIDER FOR THE 4G based mobile services THAT HAVE ALREADY BEEN COMMISSIONED

Name of Universal Service Provider : _____ Name of Implementation Unit : _____

S. No.	Site ID	State	Site details (District, Block, Village)	Site Location	Date of Completion / Commission of the 4G based mobile services site	Category	Backhaul type	Category-specific EQS component	Satellite Bandwidth amount	Subsidy payable	Duration of interruption of services		Total days for which services were interrupted	Deduction of subsidy on Pro rata basis for Col 13	Net subsidy payable (Col 10-14)	
											From date	To date				
1	2	3	4	5	6	7	8A	8B	9A	9B	10	11	12	13	14	15
1																
2																

(Signature of Authorized Signatory) along with Company seal

Note:

1. Deduction of subsidy on account of interruption of services shall be made on the total no. of days such incidences have happened from the specific site. Further, the details of interruption are to be separately provided.
2. Rounding off the subsidy to the nearest rupee shall be made only in the total subsidy due.




रामेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-3), LICOF
 Government of India
 Deptt. of Telecom, Govt. of India
 New Delhi

ATTACHMENT C TO ANNEXURE 2: FLS CLAIM STATEMENT FOR QE FROM UNIVERSAL SERVICE PROVIDER (FOR THE 4G based mobile services COMMISSIONED DURING THE QUARTER)

Name of Universal Service Provider : _____ Name of Implementation Unit : _____

S. No	State	Site details (District - Block - Village)	Site Location (Latitude/Longitude)	Date of Completion of the Mobile Service site	Category of the Site & backhaul type	Category-specific FLS component	No. of days in the Quarter	No. of days since mobile service site is Commissioned	Subsidy payable	Duration of interruption of services		Total days for which services were interrupted	Deduction of subsidy on Pro rata basis for Col 15	Net subsidy payable (Col 12-16)
										From date	To date			
1	3	4	5	7	8	9	10	11	12	13	14	15	16	17
1														
2														

(Signature of Authorized Signatory along with Company seal)

Note:

1. Deduction of subsidy on account of interruption of services shall be made on the total no of days such incidences have happened from the specific site. The details of interruption are to be separately provided.
2. Rounding off the subsidy to the nearest rupee shall be made only in the total subsidy due.
3. Date of Commissioning/ installation (Col 7) shall be included while calculating the number of days in a quarter for Col 10.
4. The claim shall be accompanied with the Self Certification as per Annexure-3.




रामेश्वर धारिवाल
RAMESHWAR DHARIWAL 41
 Director (C-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

ANNEXURE-3: Proforma for Self-Certification by Universal Service Provider

Proforma for self-certification by Universal Service Provider

1. I,, aged about years s/o, d/o Shri, resident of, do solemnly affirm and state as under:
2. That I amof (Name of the Company), Universal Service Provider inService Area and I am duly authorized by the resolutions dated passed by Board of Directors of the Company to furnish a Certificate on behalf of(Name of the Company).
3. That as per the Agreement signed with Administrator, USOF vide Agreement No. _____ dated _____ for provisioning of 4G based mobile services in the Service Area of _____, the following works have been completed successfully as per the specifications, drawings defined in the terms and conditions of the Agreement and the Tender Document:

A) Acquisition of land:

- (i) Size of the land (Dimensions):
- (ii) Village/ Khasra Number/ Survey Number/ Revenue Record Number:
- (iii) Nearest Identification/ landmark:
- (iv) Whether on lease basis/ outright purchase:
- (v) Copy of the lease agreement/ Sale deed:
- (vi) If on lease, the date and period of lease:
- (vii) Name of the owner:

B) Tower:

- (i) Tower ID:
- (ii) Latitude:
- (iii) Longitude:
- (iv) Name of the Village, Block, District, State :
- (v) Height of the tower:
- (vi) Date of Commissioning:
- (vii) Tower compliance against clause 5.3.2:

C) eNodeB:

- (i) Tower ID:
- (ii) Name of the Village, Block, District, State:
- (iii) Technology :



✓
रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यु.एस.ओ.एल.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

- (iv) Make:
- (v) Model:
- (vi) Type of BTS (A or B):
- (vii) Capacity/ Configuration:
- (viii) Radiated Power in Watts :
- (ix) Date of manufacturing:
- (x) Serial No.:
- (xi) Proof of purchase (Invoice/ Bill):
- (xii) SACFA Clearance Status :
- (xiii) Date of Commissioning:

D) Electrical power connection:

- (i) Capacity of Sanctioned load:
- (ii) Proof of sanction from SEB:
- (iii) Main Energy Meter Type/ Capacity/ Sl. No.:
- (iv) Sub-Energy Meters Type/ Capacity/ Sl. No.:
- (v) Earth Resistance (value in ohms):
- (vi) Date of Installation:

E) Renewable Energy Source

- (i) Capacity :
- (ii) Make:
- (iii) Type:
- (iv) Date of Manufacturing:
- (v) Date of Commissioning:

F) Engine Alternator:

- (i) Rated Capacity of Engine alternator:
- (ii) Make of Engine/ Alternator:
- (iii) Serial Number of Engine/ Alternator:
- (iv) Year of Manufacture:
- (v) Supplied by:
- (vi) Proof of purchase (Invoice/ Bill):
- (vii) Details of other components provided
- (viii) Testing and Commissioning Report:
- (ix) Date of Commissioning:

G) Mandatory Approvals

The following mandatory approvals have been obtained and copies of various certificates are attached.

- (i) Director General of Civil Aviation (in case the tower falls in the corridor)
- (ii) Environment Pollution Clearance
- (iii) Others, if any, as per the local laws.




 रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एन.जी.एफ.
 Director (T-1) USOF
 दूरसंचार विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली / New Delhi

H) Battery:

- (i) Rated Capacity:
- (ii) Make:
- (iii) Type:
- (iv) Date/ Year of Manufacturing:
- (v) Proof of purchase (Invoice/ Bill):
- (vi) Number of Sets:
- (vii) Date of Commissioning:

I) SMPS Power Plant:

- (i) Rated Capacity of each module:
- (ii) Make:
- (iii) Type:
- (iv) Date of Manufacturing:
- (v) Proof of purchase (Invoice/ Bill):
- (vi) Number of Modules:
- (vii) Date of Commissioning:

J) Antenna for eNodeB/ Microwave (To be provided separately):

- (i) Type:
- (ii) Gain:
- (iii) Beam width:
- (iv) Size:
- (v) Weight:
- (vi) Frequency of operation:
- (vii) Location on the Tower:
- (viii) Make:
- (ix) Date of Manufacture:
- (x) Date of Commissioning:

K) Backhaul:

- (i) Type of backhaul:
- (ii) Antenna Specification as per J) above in case of Microwave backhaul:

L) Signal Coverage details:

Certified that the actual coverage achieved from the infrastructure site installed is as per the prevalent TRAI regulations on QoS standards.

Signal Strength	Details of Coverage Area

M) Village Coverage details:

The actual number of villages covered from the infrastructure site installed in the village cluster as against the number of villages to be covered as specified in the



रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) दूर. एका.ओ.एच.
Director (T-1) USOF
दूरसंचार विभाग, नएल सचकार्य
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

Agreement is as given below:

Names of villages to be covered from eNodeB of the Infrastructure Site as per the Agreement	Names of villages actually covered from eNodeB of the Infrastructure Site	Names of villages not covered as proposed in the Agreement

4. That the details of the components mentioned above are true and correct, based on the records of the company, which are available for further verification by the appropriate authorities and that the components **have been provided and are functional/ services are being rendered** from the quarter in which they have been shown as installed/commissioned.
5. That the components at the infrastructure site shown as installed/ commissioned in the said quarter have been completed on the dates as shown above.
6. The contents of the Self Certification are true and correct, no part of it is false and nothing has been concealed there from.

For and on behalf of USP

Signature of the authorized signatory of the USP

Note:

A copy of the Self-Certification is also to be submitted to Administrator, USOF.




 रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एस.ओ.एफ.
 Director (T-1) USOF
 दूरसंचायन विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली/New Delhi

ANNEXURE-4: Format for Auditor's Report on Statement of Claim for Subsidy from USOF

To

The Board of Directors

.....

.....

We have examined the attached Statement(s) of claim for subsidy from USO Fund of (The name of the Universal Service Provider) for the quarter (s) ending _____. We understand that the aforesaid statement(s) is /are to be furnished to the Central Government for assessment of the subsidy payable to the Universal Service Provider by the Government, in terms of the Tender document No. _____ for Subsidy Disbursement for setting up and managing infrastructure sites and provision of 4G based mobile services in specified rural and remote areas in the country under Universal Service Obligation.

We report that:

1. We have examined all the record and obtained all the information and explanations, which to the best of our knowledge and belief were necessary for the purposes of our audit.
2. In our opinion and to the best of our knowledge and belief and according to the explanations given to us, the Statements have been prepared in accordance with the conditions contained in the said Agreement and instructions/guidelines issued there under and clarification thereon in this behalf and gives a true and correct view of the subsidy claimed for the period computed on the basis of the aforesaid conditions.
3. In our opinion and to the best of information, record of the disruption of 4G based mobile services is kept in such a manner as to reflect the correct position, for the purpose of claiming subsidy.

(Name and Signature of the Auditor signing)

FOR AND ON BEHALF OF (NAME OF THE AUDITOR FIRM)




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
निदेशक (टी-1) यू.एस.ओ.एफ.
Director (T-1) USOF
दूरसंचार विभाग, भारत सरकार
Deptt. of Telecom, Govt. of India
नई दिल्ली/New Delhi

ANNEXURE-5: Monthly Statement

NAME OF THE UNIVERSAL SERVICE PROVIDER:

NAME OF THE IMPLEMENTATION UNIT: <e.g. Arunachal Pradesh>

A. FOR THE MONTH ENDING:

Sl. No	Location of Site (Village name)	District & Block	Details of Tower			Deployed eNodeB Type, Configuration & Backhaul	Date of Commissioning of the Mobile Service Site (i.e. eNodeB) i.e. commencement of 4G based mobile services	Peak latched customers to the eNodeB	Total traffic generated during the month
			Tower ID	Lat.	Long.				

SIGNATURE OF THE AUTHORIZED SIGNATORY FOR OR ON BEHALF OF USP

B. CUMULATIVE:

For Sites in uncovered villages -

Sl. No.	State	District	Total Number of 4G based Sites (eNodeB) to be commissioned as per Agreement	Number of 4G based Sites commissioned prior to the current month	Number of Mobile Services Sites commissioned during the month	Cumulative Number of Mobile Services Sites commissioned
Total						

SIGNATURE OF THE AUTHORIZED SIGNATORY FOR OR ON BEHALF OF USP




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एस.जी.एफ.
 Director (T-1) USOF
 दूरसंचार विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली, New Delhi

ANNEXURE-6: Format for the Certification for Continuation of the Services Status

This is to certify that the eNodeB situated at Tower: <Tower ID> in the village <Village Name>, Sub district <Ward/Block/Tehsil Name> and District <District Name> ; which is owned and operated by <Service Provider Name>, has been providing 4G based mobile services complaint to the requirements of the agreement to the subscribers during the above stated period. The following parameters are indicative of the same.

Sl. No.	Tower ID	Tower Location	Config. of eNode B	Radiated Power	Traffic handled in erlangs	Details of Interruption in Services	Total Down time			Total Up time
		State/Dist./Block/Village and NH no. if applicable					From Date (HH-MM-SS)	To Date (HH-MM-SS)	(DD-HH-MM-SS)	

Enclosures:

- Link-Status Report:** giving details of the total number of times the links failed along with the duration and reasons thereof.
- A detailed note by the Universal Service Provider** citing causes for the down time e.g. unavailability of Electrical Power (Primary and Secondary), Backhaul (Media Problem) etc.




रामेश्वर धारीवाल
RAMESHWAR DHARIWAL
 निदेशक (टी-1) यू.एस.ओ.एफ.
 Director (T-1) USOF
 दूरसंचार विभाग, भारत सरकार
 Deptt. of Telecom, Govt. of India
 नई दिल्ली, New Delhi

ANNEXURE-7: Format for Installation of Towers in Addition/Deletion of Proposed Towers

Tower ID as per the Agreement signed	Proposed Tower Location of the additional tower	Name of Villages planned to be covered including additional villages, if any	Population of Villages Planned to be covered	Lat	Long	Type of terrain	Distance from the existing tower	Purpose for installation of additional tower	Coverage specifications of the additional tower	No. of USPs and their consent	Justification

e.g. Proper justification may be given for Addition of the towers:

1. Proper Coverage not available for the targeted area/ villages/ population/ household
2. Possibility of improved coverage by addition of the tower due to terrain/ clutter
3. Required population getting served by addition of the tower
4. Any other reason




RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

ANNEXURE-8: Format for Request for Shifting of Towers

(PROPOSAL TO BE SUBMITTED ALONG WITH THE RF PLAN AND COMPARATIVE BENEFITS)

Existing Tower ID as per the Agreement signed	Proposed Tower Location after shifting	Name of the Villages planned to be covered including additional villages, if any	Population of the Villages Planned to be covered	Lat	Long	Type of terrain	Distance from the existing tower	Purpose for shifting tower	Coverage specifications of proposed tower	No. of USPs and their consent	Justification

Proper justification may be given for Shifting of the towers:

1. Coverage already available
 - a) Name of the Service provider
 - b) Lat-Long of the corresponding tower
2. Possibility of improved coverage by relocation of the tower due to terrain
3. More population getting served by relocation of the tower
4. Difficulty in tower construction due to soil and geographical conditions
5. Any other reason



विकास सहकार
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Government of India
 Deptt. of Telecom, Govt. of India
 New Delhi

ANNEXURE-9: Monthly Statement of Progress of Project Implementation

NAME OF THE UNIVERSAL SERVICE PROVIDER:

Implementation Unit : < e.g. Arunachal Pradesh >

Report for the month of -.....

S. No.	District Name	Total No. of villages	Site Survey		Total No. of Tower locations finalized	Site Acquired	Site Preparation / Foundation		Receipt of Tower Material at site	Tower Installation		Receipt of Material, power + electronics + backhaul	Installation of equipment		Testing and Commissioning of Tower sites		Total No. of villages covered	
			Progress during the	Cumulative Progress			Progress during the	Cumulative Progress		Progress during the	Cumulative Progress		Progress during the	Cumulative Progress	Progress during the	Cumulative Progress		
1.																		
2.																		
3.																		
	Total																	




RAMESHWAR DHARIWAL
 Director (T-1) USOP
 Deptt. of Telecom, Govt. of India
 New Delhi

APPENDIX-1: Site Locations and Details

Sr. No	State Name	District Name	Sub-District Name	CD Block Name	Village Code	Village Name	Total Population of Village	LONG	LAT	Cluster No	Effective Pop	Site Type	Tower Location
1	Arunachal Pradesh	Tawang	Zemithang	Zemithang-Dudunghar	261392	Sirdi	73	91.726855	27.65613	A13	81	B	Sirdi
2	Arunachal Pradesh	Tawang	Zemithang	Zemithang-Dudunghar	261389	Tobo	8	91.720292	27.644729	A13		NIL	
3	Arunachal Pradesh	Tawang	Dudunghar	Zemithang-Dudunghar	261425	Zhamanang	88	91.654395	27.533697	A30	128	B	Zhamanang
4	Arunachal Pradesh	Tawang	Dudunghar	Zemithang-Dudunghar	261418	Snerimang	3	91.648938	27.504263	A30		NIL	
5	Arunachal Pradesh	Tawang	Dudunghar	Zemithang-Dudunghar	261433	Miling	37	91.673414	27.509706	A30		NIL	
6	Arunachal Pradesh	Tawang	Bongkhar	Mukto-Bongkhar	261597	Doonra	86	91.747461	27.497097	A35	163	B	Doonra
7	Arunachal Pradesh	Tawang	Bongkhar	Mukto-Bongkhar	261594	Rishetechachen	77	91.746691	27.503246	A35		NIL	
8	Arunachal Pradesh	Tawang	Bongkhar	Mukto-Bongkhar	261596	Rigiba	77	91.748872	27.507284	A38	132	B	Rigiba
9	Arunachal Pradesh	Tawang	Bongkhar	Mukto-Bongkhar	261595	Zanciniba	55	91.746095	27.509647	A38		NIL	
10	Arunachal Pradesh	Tawang	Tawang	Tawang	261479	Node	12	91.848107	27.554464	A53	14	B	Node
11	Arunachal Pradesh	Tawang	Tawang	Tawang	261491	Yessa Gonpa	2	91.854317	27.580899	A53		NIL	
12	Arunachal Pradesh	West Kameng	Kalakrang	Kalakrang	261750	Sanditung	114	92.060339	27.139213	A61	223	B	Sanditung
13	Arunachal Pradesh	West Kameng	Kalakrang	Kalakrang	261749	Warangam	109	92.076134	27.119341	A61		NIL	
14	Arunachal Pradesh	West Kameng	Dirang	Dirang	261697	Dungmaiabaha	285	92.245648	27.251335	A62	305	B	Dungmaiabaha
15	Arunachal Pradesh	West Kameng	Dirang	Dirang	261696	Bachuda	20	92.237726	27.258905	A62		NIL	
16	Arunachal Pradesh	West Kameng	Rupa	Kalakrang	261792	Zekmasu Thekan	155	92.289073	27.215915	A70	307	B	Zekmasu Thekan
17	Arunachal Pradesh	West Kameng	Rupa	Kalakrang	261793	Chhikrimu (Amar Basti)	152	92.290531	27.222938	A70		NIL	
18	Arunachal Pradesh	West Kameng	Rupa	Kalakrang	261791	Garbow	144	92.305606	27.2157	A71	254	B	Garbow
19	Arunachal Pradesh	West Kameng	Rupa	Kalakrang	261798	Garbambo	110	92.341995	27.217865	A71		NIL	
20	Arunachal Pradesh	West Kameng	Rupa	Kalakrang	261795	Khangam (Chota Bapur)	74	92.398237	27.149671	A75	103	B	Khangam (Chota Bapur)
21	Arunachal Pradesh	West Kameng	Rupa	Kalakrang	261784	Daxang (Dangabang)	29	92.39667	27.172925	A75		NIL	




RAMESHWAR DHARIWAL
 (Director (C-1) USOC)
 Director (C-1) USOC
 Deptt. of Telecom, Govt. of India
 New Delhi

Sr. No.	State Name	District Name	Sub District Name	CD Block Name	Village Code	Village Name	Total Population of Village	LONG	LAT.	Cluster No.	Efficiency in Pop	Site Type	Tower Location
22	Assam	West Kameng	Rupa	Karajang	261796	Zonole	346	92.412139	27.150532	A78	623	B	Zonole
23	Assam	West Kameng	Rupa	Karajang	261794	Jungam	277	92.415961	27.126158	A78		NIL	
24	Assam	West Kameng	Dirang	Dirang	261666	Nishabang	22	92.175281	27.413447	A79	35	B	Nishabang
25	Assam	West Kameng	Dirang	Dirang	261665	Phomdong	14	92.17491	27.42018	A79		NIL	
26	Assam	West Kameng	Dirang	Dirang	261674	Ditine	3	92.156668	27.441436	A80	5	B	Ditine
27	Assam	West Kameng	Dirang	Dirang	261683	Bongshingam	2	92.2946	27.404547	A80		NIL	
28	Assam	West Kameng	Dirang	Dirang	261687	Buchupam	186	92.364936	27.312091	A90	281	B	Buchupam
29	Assam	West Kameng	Dirang	Dirang	261623	Mekamru	7	92.31577	27.306136	A90		NIL	
30	Assam	West Kameng	Dirang	Dirang	261622	Dowangba	88	92.320936	27.313814	A90		NIL	
31	Assam	West Kameng	Thembaing	Dirang	261706	Pangtra	69	92.373974	27.384622	A93	161	B	Pangtra
32	Assam	West Kameng	Thembaing	Dirang	261708	Semnak	50	92.378836	27.392528	A93		NIL	
33	Assam	West Kameng	Thembaing	Dirang	261707	Gonhang	42	92.382986	27.380678	A93		NIL	
34	Assam	Upper Subansiri	Chetam (Peer Yapa)	Giba	265070	Raji	92	93.993503	28.0041	APR011	157	B	Raji
35	Assam	Upper Subansiri	Chetam (Peer Yapa)	Giba	265087	Unglang	65	93.992634	28.01881	APR011		NIL	
36	Assam	Lower Subansiri	Kamponjo	Tamen-Raga	265059	Sarin	78	93.916196	27.772082	AR001	96	B	Sarin
37	Assam	Lower Subansiri	Kamponjo	Tamen-Raga	265053	Dabi Hapo	18	93.92784	27.792548	AR001		NIL	
38	Assam	Lower Subansiri	Kamponjo	Tamen-Raga	265085	Tahak Pada	70	93.947502	27.809385	AR002	95	B	Tahak Pada
39	Assam	Lower Subansiri	Kamponjo	Tamen-Raga	265086	Dirgo	25	93.964183	27.80031	AR002		NIL	
40	Assam	Lower Subansiri	Kamponjo	Tamen-Raga	265081	Sam	138	93.944071	27.826363	AR003	221	B	Sam
41	Assam	Lower Subansiri	Kamponjo	Tamen-Raga	265082	Yokam	103	93.934544	27.814424	AR003		NIL	
42	Assam	Tawang	Dudunghar	Zemthang Dudunghar	261420	Lunchang	98	91.553376	27.527186	AR10	115	B	Lunchang
43	Assam	Tawang	Dudunghar	Zemthang Dudunghar	261438	Namsalang	17	91.560006	27.517096	AR10		NIL	
44	Assam	Tawang	Bonghar	Mukto-Bonghar	261593	Bonglingmet	78	91.752131	27.517559	AR11	96	B	Bonglingmet
45	Assam	Tawang	Bonghar	Mukto-Bonghar	261602	Kharungmet	18	91.786147	27.520416	AR11		NIL	
46	Assam	Tawang	Tawang	Tawang	261468	Blenseng	13	91.843179	27.576861	AR12	20	B	Blenseng




RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70.

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------|--------------|-------------------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|----------------|
| 47 | Arunachal Pradesh | Tawang | Tawang | Tawang | 261495 | Nyang Gongma Gongpa | 7 | 93.654075 | 27.571702 | AR12 | | NIL | |
| 48 | Arunachal Pradesh | East Kameng | Seppa | Seppa | 262049 | Moghtio | 262 | 93.033203 | 27.427188 | AR15 | 420 | B | Moghtia |
| 49 | Arunachal Pradesh | East Kameng | Seppa | Seppa | 262061 | Selbok | 358 | 93.054585 | 27.423675 | AR15 | | NIL | |
| 50 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262277 | Yaki Suliang | 107 | 93.019585 | 27.724095 | AR20 | 179 | B | Yaki Suliang |
| 51 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262242 | Mara Tassar Suliang | 22 | 93.1071 | 27.791678 | AR20 | | NIL | |
| 52 | Arunachal Pradesh | East Kameng | Piobang Veo | Pakke-Kessang | 261973 | Nangzyu | 316 | 93.169755 | 27.29851 | AR21 | 151 | B | Nangzyu |
| 53 | Arunachal Pradesh | East Kameng | Piobang Veo | Pakke-Kessang | 261965 | Kasi | 35 | 93.19825 | 27.301236 | AR21 | | NIL | |
| 54 | Arunachal Pradesh | East Kameng | Dising-Passo | Sejosa | 261922 | Dhalamukh | 82 | 93.19633 | 26.951466 | AR23 | 89 | B | Dhalamukh |
| 55 | Arunachal Pradesh | East Kameng | Dising-Passo | Sejosa | 261923 | Dikal Muckh Forest Beat | 7 | 93.180722 | 26.961182 | AR23 | | NIL | |
| 56 | Arunachal Pradesh | Papum Pare | Leporung | Sagalee | 262651 | Birek-Hapa | 81 | 93.373212 | 27.204981 | AR26 | 109 | B | Birek-Hapa |
| 57 | Arunachal Pradesh | Papum Pare | Leporung | Sagalee | 262656 | Upper Rupsirih | 28 | 93.342732 | 27.224726 | AR26 | | NIL | |
| 58 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262612 | Tuhuro | 83 | 93.459472 | 27.235801 | AR27 | 158 | B | Tuhuro |
| 59 | Arunachal Pradesh | Papum Pare | Leporung | Sagalee | 262643 | Burje | 75 | 93.44372 | 27.260942 | AR27 | | NIL | |
| 60 | Arunachal Pradesh | Upper Subansiri | Puyang | Talaha | 262986 | Kagar | 99 | 94.176167 | 28.243588 | AR001 | 153 | B | Kagar |
| 61 | Arunachal Pradesh | Upper Subansiri | Talaha | Talaha | 262948 | Budamangur | 54 | 94.173488 | 28.232006 | AR001 | | NIL | |
| 62 | Arunachal Pradesh | Lower Subansiri | Kareporjo | Tamen-Rago | 265047 | Pamuk | 213 | 93.917733 | 27.668978 | AR004 | 216 | B | Pamuk |
| 63 | Arunachal Pradesh | Lower Subansiri | Old Ziro | Ziro-I | 264787 | Kile Fakho | 3 | 93.882538 | 27.618471 | AR004 | | NIL | |
| 64 | Arunachal Pradesh | Lower Subansiri | Kareporjo | Tamen-Rago | 265049 | Riyari | 148 | 93.921622 | 27.681247 | AR005 | 177 | B | Riyari |
| 65 | Arunachal Pradesh | Lower Subansiri | Kamporjo | Tamen-Rago | 265048 | Ayi Post Bejo | 29 | 93.961008 | 27.701512 | AR005 | | NIL | |
| 66 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264624 | Tiwa | 34 | 93.944128 | 27.573548 | AR006 | 40 | B | Tiwa |
| 67 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264620 | Taru | 6 | 93.938483 | 27.570019 | AR006 | | NIL | |
| 68 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264633 | Tukung | 10 | 93.914469 | 27.575312 | AR007 | 11 | B | Tukung |
| 69 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264637 | Yo Daboi | 1 | 93.93437 | 27.583416 | AR007 | | NIL | |
| 70 | Arunachal Pradesh | Lower Subansiri | Dollungmukh | Tamen-Rago | 265104 | Lumi(Sipo) | 94 | 94.059242 | 27.581662 | AR008 | 96 | B | Lumi(Sipo) |





रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Ministry of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|--------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 71 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264643 | Taro More | 3 | 94.001059 | 27.579248 | ARP008 | | NIL | |
| 72 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265051 | Deed-Rakhe | 149 | 94.008996 | 27.810896 | ARP009 | 195 | B | Deed-Rakhe |
| 73 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265010 | Tobuso Rijo | 45 | 94.025168 | 27.795429 | ARP009 | | NIL | |
| 74 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265129 | Pelmilli | 226 | 94.047953 | 27.790354 | ARP010 | 281 | B | Pelmilli |
| 75 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265139 | Kenny# | 55 | 94.048299 | 27.805965 | ARP010 | | NIL | |
| 76 | Arunachal Pradesh | Tirap | Wakka | Wakka | 264571 | Kampong | 99 | 94.044495 | 28.392853 | ARP012 | 178 | B | Kampong |
| 77 | Arunachal Pradesh | Upper Subansiri | Syrim | Syrim | 262869 | Boga Syrim | 79 | 94.045833 | 28.375353 | ARP012 | | NIL | |
| 78 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262908 | Bogte | 143 | 94.136028 | 28.152923 | ARP013 | 217 | B | Bogte |
| 79 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262922 | Tainampomara | 74 | 94.14263 | 28.153631 | ARP013 | | NIL | |
| 80 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262914 | Delingmara | 154 | 94.154737 | 28.155398 | ARP015 | 301 | B | Delingmara |
| 81 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumponjo | 263216 | Gyankuk Rijo | 147 | 94.158562 | 28.136791 | ARP015 | | NIL | |
| 82 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 263202 | Ningtemuri | 245 | 94.126489 | 28.120344 | ARP016 | 296 | B | Ningtemuri |
| 83 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262903 | Bagi | 51 | 94.129052 | 28.106775 | ARP016 | | NIL | |
| 84 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumponjo | 263222 | Tikry | 88 | 94.182556 | 28.112797 | ARP017 | 140 | B | Tikry |
| 85 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumponjo | 263224 | Lebi | 51 | 94.172676 | 28.099624 | ARP017 | | NIL | |
| 86 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263053 | Namba-Soki | 211 | 94.09884 | 28.060347 | ARP018 | 223 | B | Namba-Soki |
| 87 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263054 | Kran-Ramme | 17 | 94.104289 | 28.085795 | ARP018 | | NIL | |
| 88 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263059 | Siga | 136 | 94.102668 | 28.089141 | ARP019 | 215 | B | Siga |
| 89 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263052 | Maji-Rijo | 79 | 94.102636 | 28.085092 | ARP019 | | NIL | |
| 90 | Arunachal Pradesh | Lower Subansiri | Pistana | Ziro-II | 264971 | Toni | 159 | 93.643949 | 27.599735 | ARP02 | 239 | B | Toni |




RAMESHWAR DHARIWAL
 Director (C-1) & Gen. Secy.
 Director (C-3) USOF
 Dept. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG. | LAT. | Cluster No. | Effectiv e Pop | Site Type | Tower Location |
|---------|----------------|-----------------|---------------------|---------------|--------------|--------------------|-----------------------------|-----------|-----------|-------------|----------------|-----------|--------------------|
| 91 | Andhra Pradesh | Lower Subansiri | Pistana | Ziro-II | 264988 | Dapo Geka | 100 | 93.673853 | 27.598147 | ARP02 | | MIL | |
| 92 | Andhra Pradesh | Upper Subansiri | Chetani (Peer Yapu) | Gilba | 263041 | Batum | 143 | 94.16071 | 28.07079 | ARP020 | 233 | B | Batum |
| 93 | Andhra Pradesh | Upper Subansiri | Chetani (Peer Yapu) | Gilba | 263043 | Meya | 90 | 94.145252 | 28.066732 | ARP020 | | MIL | |
| 94 | Andhra Pradesh | Upper Subansiri | Gite-Ripa | Dumponjo | 263256 | Lieneni | 33 | 94.285484 | 28.072755 | ARP021 | 71 | B | Lieneni |
| 95 | Andhra Pradesh | Upper Subansiri | Dumponjo | Dumponjo | 263157 | Nirpelle | 38 | 94.258772 | 28.049284 | ARP021 | | MIL | |
| 96 | Andhra Pradesh | Upper Subansiri | Gite-Ripa | Dumponjo | 263251 | Yajpu | 63 | 94.334884 | 28.09769 | ARP022 | 131 | B | Yajpu |
| 97 | Andhra Pradesh | Upper Subansiri | Gite-Ripa | Dumponjo | 263273 | Beak Ripu | 68 | 94.316065 | 28.089271 | ARP022 | 259 | B | Beak Ripu |
| 98 | Andhra Pradesh | Upper Subansiri | Gite-Ripa | Dumponjo | 263267 | Pakimen (New Hane) | 92 | 94.345881 | 28.075431 | ARP023 | 149 | B | Pakimen (New Hane) |
| 99 | Andhra Pradesh | Upper Subansiri | Dumponjo | Dumponjo | 263213 | Jiriba | 57 | 94.325908 | 28.057217 | ARP023 | | MIL | |
| 100 | Andhra Pradesh | West Siang | Lireniba | Lireniba | 263540 | Logi | 135 | 94.472238 | 28.077733 | ARP025 | 255 | B | Logi |
| 101 | Andhra Pradesh | West Siang | Lireniba | Lireniba | 263538 | Kapen | 120 | 94.489019 | 28.081255 | ARP025 | | MIL | |
| 102 | Andhra Pradesh | West Siang | Tirbin | Tirbin | 263638 | Rarak Gamin | 282 | 94.522005 | 28.016559 | ARP026 | 463 | B | Batak Gamin |
| 103 | Andhra Pradesh | West Siang | Tirbin | Tirbin | 263636 | Essi Yagi | 181 | 94.529746 | 28.013979 | ARP026 | | MIL | |
| 104 | Andhra Pradesh | West Siang | Tirbin | Tirbin | 263623 | Jirig (New Takam) | 115 | 94.581728 | 28.017068 | ARP028 | 194 | B | Jirig (New Takam) |
| 105 | Andhra Pradesh | West Siang | Tirbin | Tirbin | 263624 | Lama Dore | 79 | 94.582547 | 28.005703 | ARP028 | | MIL | |
| 106 | Andhra Pradesh | West Siang | Yomcha | Lireniba | 263552 | Akker yomgam | 141 | 94.567884 | 28.115556 | ARP029 | 216 | B | Akker yomgam |
| 107 | Andhra Pradesh | West Siang | Yomcha | Lireniba | 263553 | Daba Gamin | 75 | 94.575992 | 28.100581 | ARP029 | | MIL | |
| 108 | Andhra Pradesh | Lower Subansiri | Pistana | Ziro-II | 264966 | Miya | 91 | 93.651353 | 27.544875 | ARP03 | 361 | B | Miya |
| 109 | Andhra Pradesh | Lower Subansiri | Pistana | Ziro-II | 264977 | Sarak | 70 | 93.671639 | 27.546764 | ARP03 | | MIL | |
| 110 | Andhra Pradesh | West Siang | Yomcha | Lireniba | 263559 | Kadai | 106 | 94.621361 | 28.0981 | ARP030 | 244 | B | Kadai |
| 111 | Andhra Pradesh | West Siang | Aulo | Aulo East | 263589 | Hijam Rame | 38 | 94.639701 | 28.087904 | ARP030 | | MIL | |
| 112 | Andhra Pradesh | West Siang | Kamba | Darak | 263478 | Karbak Geyi | 236 | 94.623735 | 28.160064 | ARP031 | 288 | B | Karbak Geyi |
| 113 | Andhra Pradesh | West Siang | Kamba | Darak | 263481 | Karbak Boyar | 52 | 94.634321 | 28.16408 | ARP031 | | MIL | |
| 114 | Andhra Pradesh | West Siang | Kamba | Darak | 263501 | Balak Gok | 103 | 94.632402 | 28.352788 | ARP032 | 153 | B | Balak Gok |
| 115 | Andhra Pradesh | West Siang | Kamba | Darak | 263500 | Keni Tal(Balak) | 50 | 94.642154 | 28.357293 | ARP032 | 161 | B | Keni Tal(Balak) |
| 116 | Andhra Pradesh | West Siang | Mechuka | Mechuka | 263340 | Hiri | 53 | 94.268792 | 28.504439 | ARP033 | 130 | B | Hiri |



| Sl. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop. | Site Type | Tower Location |
|---------|-------------------|---------------------|---------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|-------------|----------------|-----------|----------------|
| 117 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263342 | Upoti | 26 | 94.281444 | 28.509403 | ARP033 | | NIL | |
| 118 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263343 | Pachua | 51 | 94.291319 | 28.500236 | ARP033 | | NIL | |
| 119 | Arunachal Pradesh | West Siang | Miongiong | Miongiong | 263357 | Puning | 66 | 94.305353 | 28.749047 | ARP035 | 109 | B | Puning |
| 120 | Arunachal Pradesh | West Siang | Miongiong | Miongiong | 263392 | Pongte | 43 | 94.280775 | 28.735343 | ARP035 | | NIL | |
| 121 | Arunachal Pradesh | West Siang | Pidi | Mechuka | 263397 | Hingte | 118 | 94.397493 | 28.575316 | ARP037 | 119 | B | Hingte |
| 122 | Arunachal Pradesh | West Siang | Pidi | Mechuka | 263403 | Kangte | 1 | 94.376897 | 28.596394 | ARP037 | | NIL | |
| 123 | Arunachal Pradesh | West Siang | Jomilo Mobuk | Rumgong | 263518 | Model | 82 | 94.878433 | 28.212988 | ARP039 | 137 | B | Model |
| 124 | Arunachal Pradesh | West Siang | Jomilo Mobuk | Rumgong | 263516 | Old Lenging | 55 | 94.854517 | 28.210183 | ARP039 | | NIL | |
| 125 | Arunachal Pradesh | West Siang | Aajo | Aajo East | 263583 | Tadin | 705 | 94.844576 | 28.061651 | ARP040 | 843 | B | Tadin |
| 126 | Arunachal Pradesh | West Siang | Bagra | Aajo West | 263771 | Bigra Jeyi | 105 | 94.703387 | 28.080966 | ARP040 | | NIL | |
| 127 | Arunachal Pradesh | West Siang | Aajo | Aajo East | 263582 | Kanen | 32 | 94.837166 | 28.0913 | ARP040 | | NIL | |
| 128 | Arunachal Pradesh | West Siang | Aajo | Aajo East | 263584 | Pushi Nyorak | 147 | 94.681831 | 28.077242 | ARP041 | 147 | B | Pushi Nyorak |
| 129 | Arunachal Pradesh | East Siang | Koyu | Ramin-Bango | 263870 | Tabi Ripu | 253 | 94.935598 | 27.901732 | ARP043 | 408 | B | Tabi Ripu |
| 130 | Arunachal Pradesh | East Siang | Koyu | Ramin-Bango | 263822 | Logu Village | 155 | 94.919601 | 27.919877 | ARP043 | | NIL | |
| 131 | Arunachal Pradesh | East Siang | Kora | Ramin-Bango | 263832 | Sido | 167 | 95.035007 | 27.988033 | ARP044 | 289 | B | Sido |
| 132 | Arunachal Pradesh | East Siang | Koyu | Ramin-Bango | 263830 | Sipu Village | 122 | 95.024943 | 27.991465 | ARP044 | | NIL | |
| 133 | Arunachal Pradesh | Upper Siang | Singa | Singa-Gelling | 263957 | Manikofa | 177 | 95.050761 | 28.856983 | ARP048 | 183 | B | Manikofa |
| 134 | Arunachal Pradesh | Upper Siang | Singa | Singa-Gelling | 263968 | Deokote | 6 | 95.039419 | 28.848959 | ARP048 | | NIL | |
| 135 | Arunachal Pradesh | Lower Subansiri | Piscana | Ziro-II | 264995 | Yogu | 117 | 93.711037 | 27.516111 | ARP05 | 155 | B | Yogu |
| 136 | Arunachal Pradesh | Lower Subansiri | Piscana | Ziro-II | 264952 | Yedin | 38 | 93.710638 | 27.508964 | ARP05 | | NIL | |
| 137 | Arunachal Pradesh | Dibang Valley | Kroyi (Azoo circle) | Aneith-Azru | 266022 | Ainey | 79 | 95.884908 | 28.396232 | ARP050 | 94 | B | Ainey |
| 138 | Arunachal Pradesh | Dibang Valley | Kroyi (Azoo circle) | Aneith-Azru | 266021 | Akaya | 35 | 95.885849 | 28.41411 | ARP050 | | NIL | |
| 139 | Arunachal Pradesh | Lower Dibang Valley | Korona | Rong-Korona | 266348 | Ithim | 6 | 95.975144 | 28.072894 | ARP051 | | NIL | |
| 140 | Arunachal Pradesh | Lower Dibang Valley | Korona | Rong-Korona | 266360 | Koliya | 814 | 95.947075 | 28.075544 | ARP051 | 820 | B | Koliya |
| 141 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266831 | Chipra | 35 | 96.548103 | 28.271061 | ARP061 | 67 | B | Chipra |
| 142 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266830 | Tamadu | 32 | 96.572747 | 28.259488 | ARP061 | | NIL | |
| 143 | Arunachal Pradesh | Anjaw | Mitenglang | Chaglagam | 266862 | Tiang | 34 | 96.550389 | 28.129422 | ARP062 | 40 | B | Tiang |
| 144 | Arunachal Pradesh | Anjaw | Mitenglang | Chaglagam | 266863 | Chigam | 6 | 96.560006 | 28.158403 | ARP062 | | NIL | |
| 145 | Arunachal Pradesh | Lower Subansiri | Piscana | Ziro-II | 265095 | Pistana H.O. | 338 | 93.675169 | 27.464431 | ARP07 | 434 | B | Pistana H.O. |
| 146 | Arunachal Pradesh | Lower Subansiri | Piscana | Ziro-II | 264553 | Sally | 96 | 93.695659 | 27.470597 | ARP07 | | NIL | |
| 147 | Arunachal Pradesh | Lower Subansiri | Yezil | Ziro-II | 264948 | Tesur | 114 | 93.687947 | 27.446753 | ARP08 | 169 | B | Tesur |



रामेश्वर धरिवाल
RAMESHWAR DHARWAL
 (Director (T-1) USOF)
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub-District Name | CD Block Name | Village Code | Village Name | Total Population of village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------|--------------|-------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 148 | Arunachal Pradesh | Lower Subansiri | Vazali | Ziro-II | 264946 | Rhompu | 55 | 93.20253 | 27.454957 | ARP08 | | NIL | |
| 149 | Arunachal Pradesh | Changiang | Changiang | Changiang | 264121 | Chungaa | 82 | 95.761672 | 27.07578 | ARP081 | 145 | B | Chungaa |
| 150 | Arunachal Pradesh | Changiang | Changiang | Changiang | 264120 | New Sober-Laklong | 63 | 95.761695 | 27.059103 | ARP081 | | NIL | |
| 151 | Arunachal Pradesh | Lower Subansiri | Pistana | Ziro-II | 264894 | New Panjya | 157 | 93.676425 | 27.520992 | ARP090 | 307 | B | New Panjya |
| 152 | Arunachal Pradesh | Lower Subansiri | Pistana | Ziro-II | 264991 | Panjya | 150 | 93.676475 | 27.520992 | ARP090 | | NIL | |
| 153 | Arunachal Pradesh | Papum Pare | Mengio | Mengio | 262723 | Sotung | 144 | 93.485727 | 27.531356 | ARP10 | 271 | B | Sotung |
| 154 | Arunachal Pradesh | Papum Pare | Mengio | Mengio | 262708 | Tamlo Poi | 127 | 93.495259 | 27.515259 | ARP10 | | NIL | |
| 155 | Arunachal Pradesh | Papum Pare | Sigalee | Sigalee | 262597 | Sangri | 129 | 93.570978 | 27.253116 | ARP15 | 164 | B | Sangri |
| 156 | Arunachal Pradesh | Papum Pare | Sogalee | Sogalee | 262585 | Migiang | 35 | 93.574189 | 27.236937 | ARP15 | | NIL | |
| 157 | Arunachal Pradesh | Papum Pare | Maharajgun | Domukh | 262483 | Duchi | 62 | 93.615946 | 27.11434 | ARP20 | 107 | B | Duchi |
| 158 | Arunachal Pradesh | Papum Pare | Maharajgun | Domukh | 262485 | Buk | 45 | 93.618556 | 27.103842 | ARP20 | | NIL | |
| 159 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265728 | Serai | 265 | 93.540208 | 27.918186 | ARP31 | 439 | B | Serai |
| 160 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265734 | Lumdang | 174 | 93.548772 | 27.933217 | ARP31 | | NIL | |
| 161 | Arunachal Pradesh | Lower Subansiri | Vazali | Ziro-II | 264912 | Purmaar | 105 | 93.763811 | 27.431509 | ARP33 | 192 | B | Purmaar |
| 162 | Arunachal Pradesh | Lower Subansiri | Vachuli | Ziro-II | 264880 | Laj | 87 | 93.750704 | 27.437316 | ARP33 | | NIL | |
| 163 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265756 | Hanglik | 142 | 93.459291 | 27.938985 | ARP35 | 271 | B | Hanglik |
| 164 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265758 | Miangdo | 129 | 93.475355 | 27.972072 | ARP35 | | NIL | |
| 165 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265739 | Tungbia | 203 | 93.538776 | 28.000545 | ARP40 | 291 | B | Tungbia |
| 166 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265750 | Yalaha | 88 | 93.63235 | 28.005538 | ARP40 | | NIL | |
| 167 | Arunachal Pradesh | Karung Kumey | Damin | Damin | 265815 | Sarang | 111 | 93.381622 | 28.092194 | ARP46 | 172 | B | Sarang |
| 168 | Arunachal Pradesh | Karung Kumey | Damin | Damin | 265781 | Borak | 61 | 93.391574 | 28.097676 | ARP46 | | NIL | |
| 169 | Arunachal Pradesh | Upper Subansiri | Taksang | Limeking | 262776 | Takung H.O. | 324 | 93.326724 | 28.409994 | ARP50 | 359 | B | Takung H.O. |
| 170 | Arunachal Pradesh | Upper Subansiri | Taksang | Limeking | 262769 | Thungbi (Tungba) | 35 | 93.368857 | 28.403033 | ARP50 | | NIL | |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (E-1) & Project Director
 Director (E-1) USOF
 Executive Engineer, Project Services
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|----------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 171 | Arunachal Pradesh | Karung Kumei | Chambang | Chambang | 265510 | Debe | 72 | 93.681381 | 27.795317 | ARP03 | 137 | B | Debe |
| 172 | Arunachal Pradesh | Karung Kumei | Palin | Palin | 265215 | Goppo | 65 | 93.696601 | 27.726946 | ARP03 | | NIL | |
| 173 | Arunachal Pradesh | Changlang | Changlang | Changlang | 264111 | New Jongroen | 53 | 95.667472 | 27.091452 | AX3 | 88 | B | New Jongroen |
| 174 | Arunachal Pradesh | Changlang | Yoddam | Changlang | 264071 | Nakang | 35 | 95.667610 | 27.084702 | AX3 | | NIL | |
| 175 | Arunachal Pradesh | Karung Kumei | Parsi-Parlo | Parsi-Parlo | 265741 | Ranli | 88 | 93.523837 | 27.969812 | AY1 | 282 | B | Ranli |
| 176 | Arunachal Pradesh | Karung Kumei | Parsi-Parlo | Parsi-Parlo | 265711 | Taxam | 131 | 93.524852 | 27.967731 | AY1 | 282 | B | Taxam |
| 177 | Arunachal Pradesh | Karung Kumei | Parsi-Parlo | Parsi-Parlo | 265740 | Nyokunang | 63 | 93.514755 | 27.961113 | AY1 | | NIL | |
| 178 | Arunachal Pradesh | Upper Siang | Singa | Singa-Gelling | 263972 | Simuge | 20 | 95.116607 | 28.814559 | AY4 | 26 | B | Simuge |
| 179 | Arunachal Pradesh | Upper Siang | Singa | Singa-Gelling | 263976 | Silage | 6 | 95.109081 | 28.807693 | AY4 | | NIL | |
| 180 | Arunachal Pradesh | Changlang | Tibhak Rima Patok | Nampong | 264221 | Longcheng-II | 95 | 96.357696 | 27.413444 | AY5 | 133 | B | Longcheng-II |
| 181 | Arunachal Pradesh | Changlang | Tibhak Rima Patok | Nampong | 264210 | Longcheng-I | 38 | 96.344360 | 27.412734 | AY5 | | NIL | |
| 182 | Arunachal Pradesh | Changlang | Changlang | Changlang | 264096 | Jungmaising-II | 125 | 95.815280 | 27.196966 | AY8 | 209 | B | Jungmaising-II |
| 183 | Arunachal Pradesh | Changlang | Changlang | Changlang | 264108 | Chinru | 84 | 95.824145 | 27.184023 | AY8 | | NIL | |
| 184 | Arunachal Pradesh | Changlang | Changlang | Changlang | 264102 | Rangan-I | 162 | 95.810915 | 27.132079 | AY9 | 244 | B | Rangan-I |
| 185 | Arunachal Pradesh | Changlang | Changlang | Changlang | 264103 | Rangan-II | 82 | 95.814956 | 27.118855 | AY9 | | NIL | |
| 186 | Arunachal Pradesh | East Khasi | Pipu Dipu | Pipu | 262149 | Kotte Camp | 99 | 93.08565 | 27.449987 | AZ1 | 145 | B | Kotte Camp |
| 187 | Arunachal Pradesh | East Khasi | Pipu-Dipu | Pipu | 262148 | Kawa Dada | 46 | 93.059696 | 27.458378 | AZ1 | | NIL | |
| 188 | Arunachal Pradesh | Karung Kumei | Phassang | Nyopin | 265405 | Najuring | 100 | 93.243125 | 27.716855 | AZ2 | 192 | B | Najuring |
| 189 | Arunachal Pradesh | Karung Kumei | Phassang | Nyopin | 265397 | Longsa | 92 | 93.251846 | 27.702898 | AZ2 | | NIL | |
| 190 | Arunachal Pradesh | Karung Kumei | Phassang | Nyopin | 265408 | Neechilangli | 333 | 93.288085 | 27.715601 | AZ3 | 447 | B | Neechilangli |
| 191 | Arunachal Pradesh | Karung Kumei | Phassang | Nyopin | 265406 | Youndo | 16 | 93.271777 | 27.742462 | AZ3 | | NIL | |
| 192 | Arunachal Pradesh | Karung Kumei | Nyopin | Nyopin | 265396 | Taka | 98 | 93.302454 | 27.726229 | AZ3 | | NIL | |
| 193 | Arunachal Pradesh | Karung Kumei | Nyopin | Nyopin | 265385 | Pwji(Bocobang) | 239 | 93.478409 | 27.745023 | AZ4 | 524 | B | Pwji(Bocobang) |
| 194 | Arunachal Pradesh | Karung Kumei | Sangram | Sangram | 265313 | Pvet | 285 | 93.475358 | 27.733003 | AZ4 | | NIL | |




RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|---------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|----------------|
| 195 | Arunachal Pradesh | Karung Kumey | Paini | Paini | 265290 | Tiou | 104 | 93.693247 | 27.846971 | A25 | 118 | R | Taiou |
| 196 | Arunachal Pradesh | Karung Kumey | Chambang | Chambang | 265558 | Sonia | 14 | 93.712146 | 27.853941 | A25 | | ML | |
| 197 | Arunachal Pradesh | Karung Kumey | Koloriang | Koloriang | 265499 | Kush(Lama) | 65 | 93.451128 | 27.852222 | A26 | 82 | W | KUSH(Lama) |
| 198 | Arunachal Pradesh | Karung Kumey | Koloriang | Koloriang | 265498 | Dilang New | 17 | 93.455127 | 27.856958 | A26 | | ML | |
| 199 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265747 | Parlang | 122 | 93.493339 | 27.9976 | A28 | 198 | B | Parlang |
| 200 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265752 | Kongrup-Pokap | 77 | 93.483729 | 27.968041 | A28 | | ML | |
| 201 | Arunachal Pradesh | West Kameng | Mafra | Mafra | 263716 | West Sachung | 144 | 92.633111 | 27.375348 | B10 | 258 | W | West Sachung |
| 202 | Arunachal Pradesh | West Kameng | Mafra | Mafra | 263726 | Khaborang | 9 | 92.584964 | 27.406057 | B10 | | ML | |
| 203 | Arunachal Pradesh | West Kameng | Mafra | Mafra | 263719 | Najanpong | 105 | 92.642896 | 27.396233 | B10 | | ML | |
| 204 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262070 | Piplang | 42 | 92.718528 | 27.664092 | B12 | 64 | B | Piplang |
| 205 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262074 | Welling Tawe | 22 | 92.699894 | 27.661017 | B12 | | ML | |
| 206 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262073 | Tawe | 203 | 92.723561 | 27.637183 | B15 | 392 | B | Tawe |
| 207 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262071 | Nissanglang | 54 | 92.729697 | 27.627936 | B15 | | ML | |
| 208 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262075 | Dongsha | 45 | 92.730228 | 27.627432 | B15 | | ML | |
| 209 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262072 | Sachung | 165 | 92.736698 | 27.616457 | B18 | 244 | B | Sachung |
| 210 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262078 | Pha | 79 | 92.744312 | 27.620932 | B18 | | ML | |
| 211 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262084 | Wablang | 82 | 92.733478 | 27.576547 | B20 | 222 | B | Wablang |
| 212 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262087 | Walke | 70 | 92.713978 | 27.564587 | B20 | | ML | |
| 213 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262086 | Ganjang | 70 | 92.737812 | 27.584097 | B20 | | ML | |
| 214 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262088 | Drakshi | 198 | 92.749729 | 27.547263 | B25 | 262 | B | Drakshi |
| 215 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262077 | Kampa - N.V. | 64 | 92.769692 | 27.579608 | B25 | | ML | |
| 216 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262082 | Lada H.C. | 251 | 92.807647 | 27.542156 | B40 | 306 | B | Lada H.C. |
| 217 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262079 | Ghung | 55 | 92.805764 | 27.570326 | B40 | | ML | |
| 218 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262080 | Satus (Panda) | 55 | 92.823478 | 27.539836 | B40 | 84 | B | Satus (Panda) |
| 219 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262081 | Prat | 29 | 92.8192 | 27.542169 | B40 | | ML | |
| 220 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262093 | Rajang | 185 | 92.760563 | 27.538012 | B60 | 332 | B | Rajang |
| 221 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262093 | Kolo | 147 | 92.790812 | 27.503928 | B60 | | ML | |
| 222 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262091 | Rojo | 110 | 92.751896 | 27.490928 | B65 | 366 | B | Rojo |
| 223 | Arunachal Pradesh | East Kameng | Lada | Khenewa | 262094 | Jakam | 56 | 92.741662 | 27.480094 | B65 | | ML | |
| 224 | Arunachal Pradesh | East Kameng | Sena | Chayangajo | 262271 | Sana Takhang | 148 | 92.9504 | 27.728676 | B67 | 264 | B | Sana Takhang |





रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (C-1) & Gen. Mgr.
 Director (T-1) USOP
 Genent. Mgmt. & Gen. Mgmt.
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|-----------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 225 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262270 | Warriam Sullung | 39 | 92.936688 | 27.72959 | 867 | | NIL | |
| 226 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262252 | Lancho Sullung | 77 | 92.941716 | 27.745129 | 867 | | NIL | |
| 227 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262218 | Jayang Bagang | 659 | 93.160561 | 27.738978 | 869 | 958 | B | Jayang Bagang |
| 228 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262213 | Kaple Sullung | 44 | 93.152737 | 27.727814 | 869 | | NIL | |
| 229 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262219 | Kesse Bagang | 255 | 93.162872 | 27.751811 | 869 | | NIL | |
| 230 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262212 | Wada Bagang | 442 | 93.142986 | 27.708922 | 870 | 545 | B | Wada Bagang |
| 231 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262221 | Nara Yanglo | 103 | 93.129447 | 27.710225 | 870 | | NIL | |
| 232 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262217 | Sawa Yanglo | 148 | 93.116782 | 27.75158 | 871 | 245 | B | Sawa Yanglo |
| 233 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262215 | Sangriwa | 57 | 93.128361 | 27.738783 | 871 | | NIL | |
| 234 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262223 | Tarawa Yanglo | 196 | 93.107032 | 27.728423 | 872 | 209 | B | Tarawa Yanglo |
| 235 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262254 | Kowe Sullung | 13 | 93.102042 | 27.736897 | 872 | | NIL | |
| 236 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262220 | Jarom Sullung | 135 | 93.111298 | 27.72111 | 873 | 247 | B | Jarom Sullung |
| 237 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262255 | Loto Yanglo | 117 | 93.113328 | 27.720614 | 873 | | NIL | |
| 238 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262248 | Byale Sullung | 98 | 93.094003 | 27.705994 | 875 | 283 | B | Byale Sullung |
| 239 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262227 | Tambang Yanglo | 88 | 93.095094 | 27.707704 | 875 | | NIL | |
| 240 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262226 | Tagimpu Sullung | 97 | 93.089968 | 27.717454 | 875 | | NIL | |
| 241 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262226 | Venle | 77 | 93.045637 | 27.733303 | 876 | 117 | B | Venle |
| 242 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262249 | Weigung Sullung | 40 | 93.04638 | 27.72659 | 876 | | NIL | |
| 243 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262265 | Nampe | 207 | 93.018323 | 27.690331 | 878 | 377 | B | Nampe |
| 244 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262223 | Nampe Bagang | 170 | 93.018214 | 27.713765 | 878 | | NIL | |
| 245 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262257 | Lamno | 440 | 93.074547 | 27.6911 | 879 | 506 | B | Lamno |
| 246 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262258 | Dara Yanglo | 66 | 93.066781 | 27.701413 | 879 | | NIL | |
| 247 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262262 | Tongi | 231 | 93.037239 | 27.680229 | 880 | 265 | B | Tongi |
| 248 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262272 | Sawa H.L. | 34 | 93.053117 | 27.677947 | 880 | | NIL | |
| 249 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262263 | Nanta Yanglo | 151 | 93.088983 | 27.676878 | 881 | 197 | B | Nanta Yanglo |
| 250 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262231 | Rasu Camp | 46 | 93.087818 | 27.668275 | 881 | | NIL | |




रामेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (R-1) USOF
 Director, Telecom, Govt. of India
 New Delhi

| Sr No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|--------|-------------------|---------------|-------------------|---------------|--------------|-------------------|-----------------------------|------------|------------|------------|---------------|-----------|-------------------|
| 251 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262209 | Wallong | 113 | 92.5810988 | 27.6768906 | 882 | 173 | B | Wallong |
| 252 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262205 | Chaling | 60 | 92.5972208 | 27.670981 | 882 | | NIL | |
| 253 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262208 | Kawarang | 60 | 92.593958 | 27.652128 | 883 | 103 | B | Kawarang |
| 254 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262206 | Rapa | 43 | 92.579041 | 27.665839 | 883 | | NIL | |
| 255 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262224 | Upper Lyak Donia | 173 | 92.845526 | 27.545277 | 884 | 241 | B | Upper Lyak Donia |
| 256 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262125 | Upper Lyak Doncha | 130 | 92.843088 | 27.533902 | SINGLE | 130 | A | Upper Lyak Doncha |
| 257 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262123 | Tafro | 68 | 92.859939 | 27.538777 | 884 | | NIL | |
| 258 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262126 | Bobby Camp | 30 | 92.844713 | 27.520089 | 885 | 59 | B | Bobby Camp |
| 259 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262115 | Laja Silliang | 29 | 92.859139 | 27.514839 | 885 | | NIL | |
| 260 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262121 | Rengte-Wah | 212 | 92.894194 | 27.535372 | 885 | 410 | B | Rengte-Wah |
| 261 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262127 | Pocbe-Sullang | 128 | 92.891083 | 27.548811 | 886 | | NIL | |
| 262 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262119 | Rassong | 70 | 92.907892 | 27.556392 | 886 | | NIL | |
| 263 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 262010 | Mongrang | 86 | 92.836295 | 27.407856 | 888 | 245 | B | Mongrang |
| 264 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261993 | Pankar | 79 | 92.827442 | 27.420938 | 888 | | NIL | |
| 265 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261994 | Hojeppa | 81 | 92.827997 | 27.431117 | 888 | | NIL | |
| 266 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261998 | Talomsana | 191 | 92.84334 | 27.373113 | 890 | 340 | B | Talomsana |
| 267 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261999 | Chamduk Leyak | 149 | 92.834503 | 27.3963 | 890 | | NIL | |
| 268 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261988 | Chyang | 85 | 92.84477 | 27.310128 | 891 | 222 | B | Chyang |
| 269 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261987 | Pitchang | 72 | 92.833015 | 27.323217 | 891 | | NIL | |
| 270 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261988 | Kajung | 65 | 92.843052 | 27.331581 | 891 | | NIL | |
| 271 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261991 | Kadewa Kitchang | 206 | 92.86388 | 27.326563 | 892 | 320 | B | Kadewa Kitchang |
| 272 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261997 | Afatsang | 114 | 92.878625 | 27.317598 | 892 | | NIL | |
| 273 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 262007 | New Saponig | 242 | 92.871391 | 27.310364 | 893 | 341 | B | New Saponig |
| 274 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 262005 | Wote | 33 | 92.876098 | 27.245076 | 893 | | NIL | |
| 275 | Arunachal Pradesh | East Kameng | Richukrong | Bana | 261990 | Xitchang | 66 | 92.886956 | 27.293542 | 893 | | NIL | |
| 276 | Arunachal Pradesh | East Kameng | Sejosa | Sejosa | 261909 | Monai | 43 | 93.031653 | 26.925092 | 897 | 44 | B | Monai |
| 277 | Arunachal Pradesh | East Kameng | Sejosa | Sejosa | 261911 | Diring | 3 | 93.056854 | 26.947845 | 897 | | NIL | |
| 278 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261945 | Pelvo | 108 | 93.158278 | 27.133475 | 899 | 175 | B | Pelvo |
| 279 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261941 | Suchiang | 67 | 93.139204 | 27.129739 | 899 | | NIL | |
| 280 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263366 | Sinungong | 107 | 94.292335 | 28.875701 | 8886 | 181 | B | Sinungong |
| 281 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263368 | Seyngong | 74 | 94.306135 | 28.893265 | 8886 | | NIL | |
| 282 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263367 | Lubukar | 82 | 94.330382 | 28.874446 | 8887 | 122 | B | Lubukar |
| 283 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263354 | Lusing Yangor | 40 | 94.350716 | 28.868222 | 8887 | | NIL | |
| 284 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263370 | Pullom | 70 | 94.296997 | 28.803908 | 8888 | 111 | B | Pullom |



रामेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sl. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop. | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|-------------------------|-----------------------------|-----------|-----------|-------------|----------------|-----------|-----------------------|
| 285 | Arunachal Pradesh | West Siang | Moungong | Moungong | 263371 | Kote Sohang(Remaang-II) | 41 | 94.299235 | 28.801053 | BB88 | | NIL | |
| 286 | Arunachal Pradesh | West Siang | Moungong | Moungong | 263372 | Kambe Doh (Puilom-II) | 96 | 94.314917 | 28.810462 | BB89 | 136 | B | Kambe Doh (Puilom-II) |
| 287 | Arunachal Pradesh | West Siang | Moungong | Moungong | 263355 | Papu Nutei(Remaang-II) | 40 | 94.312491 | 28.78892 | BB89 | | NIL | |
| 288 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261940 | Riloh | 331 | 93.162528 | 27.189975 | C13 | 385 | B | Riloh |
| 289 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261948 | Doh | 54 | 93.152389 | 27.201403 | C13 | | NIL | |
| 290 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261947 | Ngoieka | 305 | 93.135675 | 27.173845 | C15 | 345 | B | Ngoieka |
| 291 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261936 | Lodoso | 40 | 93.135031 | 27.161333 | C15 | | NIL | |
| 292 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261977 | Mado | 126 | 93.103522 | 27.212653 | C16 | 284 | B | Mado |
| 293 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261955 | Didero | 70 | 93.109711 | 27.206872 | C16 | | NIL | |
| 294 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261954 | Chungong (New) | 88 | 93.112578 | 27.204686 | C16 | | NIL | |
| 295 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261957 | Latuwa | 152 | 93.099439 | 27.234938 | C17 | 156 | B | Latuwa |
| 296 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261963 | Varte Pobe | 44 | 93.082502 | 27.219883 | C17 | | NIL | |
| 297 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261978 | Ningsho | 273 | 93.032089 | 27.247419 | C19 | 355 | B | Ningsho |
| 298 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261981 | Kamou Soba | 82 | 93.038043 | 27.25109 | C19 | | NIL | |
| 299 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261971 | Taroyar | 292 | 93.083659 | 27.26346 | C20 | 517 | B | Taroyar |
| 300 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261970 | Baigota | 225 | 93.100694 | 27.253756 | C20 | | NIL | |
| 301 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261974 | Sede | 501 | 93.110099 | 27.294958 | C21 | 568 | B | Sede |
| 302 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261980 | Patha | 67 | 93.10099 | 27.324277 | C21 | | NIL | |
| 303 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261957 | Devegolo | 123 | 93.233568 | 27.366042 | C24 | 171 | B | Devegolo |
| 304 | Arunachal Pradesh | East Kameng | Pirang(Veo) | Pakke-Kessang | 261962 | Tengri | 48 | 93.211725 | 27.374196 | C24 | | NIL | |
| 305 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262130 | Sepfaliang | 128 | 92.939864 | 27.588325 | C26 | 143 | B | Sepfaliang |
| 306 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262107 | Lori Camp | 15 | 92.977155 | 27.576153 | C26 | | NIL | |
| 307 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262131 | Tayang | 99 | 92.934904 | 27.513589 | C28 | 213 | B | Tayang |
| 308 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262118 | Liya Myarung | 25 | 92.968317 | 27.508714 | C28 | | NIL | |
| 309 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262116 | Lengouliang | 89 | 92.968675 | 27.48956 | C28 | | NIL | |
| 310 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262104 | Honkia Camp | 85 | 93.011281 | 27.502213 | C29 | 172 | B | Honkia Camp |
| 311 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262105 | Tajeyar Camp | 85 | 93.006406 | 27.511151 | C29 | | NIL | |
| 312 | Arunachal Pradesh | East Kameng | Pipu-Dipu | Pipu | 262144 | Tabri | 188 | 93.048658 | 27.526589 | C30 | 304 | B | Tabri |
| 313 | Arunachal Pradesh | East Kameng | Pipu-Dipu | Pipu | 262146 | Tadowapi | 116 | 93.040532 | 27.504651 | C30 | | NIL | |
| 314 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262194 | Pabu Pabing | 177 | 93.015719 | 27.613736 | C31 | 202 | B | Pabu Pabing |
| 315 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262187 | Wagruing | 25 | 93.014348 | 27.589911 | C31 | | NIL | |
| 316 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262196 | Langri L.A.Y Village | 85 | 93.00475 | 27.606195 | C310 | 121 | B | Langri L.A.Y Village |



रामेश्वर धरिवर
RAMESHWAR DHARIVAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 110 001 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective PoP | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|-------------------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|-------------------------------|
| 317 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262201 | Sefew | 38 | 93.005917 | 27.608636 | C310 | | NIL | |
| 318 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262190 | Paffa | 239 | 93.086733 | 27.574035 | C32 | 265 | B | Paffa |
| 319 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262188 | Sangbia Camp | 26 | 93.061456 | 27.578608 | C32 | | NIL | |
| 320 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262195 | Pordung | 340 | 93.039033 | 27.580719 | C33 | 415 | B | Pordung |
| 321 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262198 | Pordung Sullung | 25 | 93.026894 | 27.584414 | C33 | | NIL | |
| 322 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262186 | Yacho | 50 | 93.048969 | 27.587685 | C33 | | NIL | |
| 323 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262188 | Latum I.A.V Village (Sangbia) | 239 | 93.041028 | 27.600025 | C34 | 264 | B | Latum I.A.V Village (Sangbia) |
| 324 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262193 | Pasing | 25 | 93.049353 | 27.601061 | C34 | | NIL | |
| 325 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262246 | Boke | 215 | 93.067619 | 27.651919 | C35 | 257 | B | Boke |
| 326 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262261 | Mangth Mangam | 42 | 93.055978 | 27.554634 | C35 | | NIL | |
| 327 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262275 | Yeo | 219 | 93.076487 | 27.542123 | C36 | 283 | B | Yeo |
| 328 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262251 | Dao | 64 | 93.076581 | 27.630725 | C36 | | NIL | |
| 329 | Arunachal Pradesh | East Kameng | Khenewa | Khenewa | 262191 | Sangbia | 281 | 93.081153 | 27.601066 | C37 | 299 | B | Sangbia |
| 330 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262266 | Diya Sullung | 18 | 93.090278 | 27.614453 | C37 | | NIL | |
| 331 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262269 | Sano | 56 | 93.103728 | 27.659697 | C39 | 158 | B | Sario |
| 332 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262267 | Perre | 47 | 93.096208 | 27.647867 | C39 | | NIL | |
| 333 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262268 | Raro Sullung | 55 | 93.101508 | 27.653567 | C38 | | NIL | |
| 334 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262235 | Soshi Bagang | 128 | 93.125996 | 27.638774 | C40 | 143 | B | Soshi Bagang |
| 335 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262233 | Langrak Tajo | 15 | 93.123756 | 27.624458 | C40 | | NIL | |
| 336 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262211 | Sangbia Sullung | 181 | 93.163878 | 27.66078 | C42 | 324 | B | Sangbia Sullung |
| 337 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262244 | Dache Sullung | 32 | 93.166051 | 27.67001 | C42 | | NIL | |
| 338 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262239 | Tamak Sullung | 111 | 93.17902 | 27.652657 | C42 | | NIL | |
| 339 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262254 | Kemchar Bagang | 127 | 93.153497 | 27.614022 | C43 | 238 | B | Kemchar Bagang |
| 340 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262237 | Dorpu Bagang | 111 | 93.159575 | 27.593625 | C43 | | NIL | |
| 341 | Arunachal Pradesh | East Kameng | Pipu Dipu | Pipu | 262155 | Wotte Cheda | 253 | 93.122162 | 27.54934 | C44 | 276 | B | Wotte Cheda |
| 342 | Arunachal Pradesh | East Kameng | Pipu Dipu | Pipu | 262156 | Longk Sullung | 17 | 93.189225 | 27.54934 | C44 | | NIL | |
| 343 | Arunachal Pradesh | East Kameng | Pipu Dipu | Pipu | 262156 | Sogru Sullung | 7 | 93.198163 | 27.559903 | C44 | | NIL | |
| 344 | Arunachal Pradesh | East Kameng | Pipu Dipu | Pipu | 262141 | Chege | 194 | 93.12935 | 27.544117 | C45 | 315 | B | Chege |
| 345 | Arunachal Pradesh | East Kameng | Pipu Dipu | Pipu | 262135 | Hari Nabilem | 121 | 93.119347 | 27.542215 | C45 | | NIL | |





RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deputy Director, State Agency
 Dept. of Telecom, Govt. of India
 New Delhi

| Sr No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|--------|-------------------|---------------|-------------------|---------------|--------------|-------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 346 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262173 | Ligwa Gyadi | 156 | 93.146034 | 27.501088 | C47 | 337 | B | Ligwa Gyadi |
| 347 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262172 | Dipu Lamgu | 141 | 93.1345 | 27.49455 | C47 | | NIL | |
| 348 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262175 | Mini Sollung | 134 | 93.179398 | 27.493318 | C48 | 174 | B | Mini Sollung |
| 349 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262177 | Mechinary Sollung | 40 | 93.187525 | 27.497433 | C48 | | NIL | |
| 350 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262178 | Leongo Gollo | 40 | 93.206364 | 27.497888 | C480 | 44 | B | Lungo Gollo |
| 351 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262176 | Anuk Sollung | 4 | 93.18991 | 27.482349 | C480 | | NIL | |
| 352 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262174 | Dokre Gyadi | 161 | 93.167515 | 27.476407 | C48 | 334 | B | Dokre Gyadi |
| 353 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262181 | Gyawa Purang (H) | 133 | 93.158978 | 27.483406 | C49 | | NIL | |
| 354 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262183 | Hisa Plangta | 40 | 93.163886 | 27.470029 | C49 | | NIL | |
| 355 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262183 | Richi Lamgu | 285 | 93.112026 | 27.458975 | C50 | 314 | B | Richi Lamgu |
| 356 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262184 | Papawa Sollung | 39 | 93.171356 | 27.441392 | C50 | | NIL | |
| 357 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265703 | Milli | 121 | 93.055444 | 27.931706 | C51 | 151 | B | Milli |
| 358 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265702 | Gene | 30 | 93.037789 | 27.936211 | C51 | | NIL | |
| 359 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265709 | Wawa | 122 | 93.083407 | 27.884913 | C52 | 221 | B | Wawa |
| 360 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265701 | Machane | 99 | 93.074808 | 27.897897 | C52 | | NIL | |
| 361 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265706 | Sahrea | 64 | 93.089036 | 27.882869 | C520 | 116 | B | Sahria |
| 362 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265707 | Vatalin | 52 | 93.096712 | 27.883757 | C520 | | NIL | |
| 363 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265711 | Chulu | 66 | 93.066817 | 27.8536 | C53 | 80 | B | Chulu |
| 364 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265710 | Riya | 15 | 93.079292 | 27.858711 | C53 | | NIL | |
| 365 | Arunachal Pradesh | Kurung Kumey | Phassang | Nyapin | 265418 | Malo | 117 | 93.113608 | 27.890128 | C54 | 241 | B | Malo |
| 366 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265678 | Haraho | 29 | 93.120894 | 27.940415 | C54 | | NIL | |
| 367 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265699 | Wobia | 96 | 93.13156 | 27.941455 | C54 | | NIL | |
| 368 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265700 | Pale | 62 | 93.122603 | 27.899117 | C56 | 113 | B | Pale |
| 369 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265698 | Nampo | 51 | 93.149697 | 27.906931 | C56 | | NIL | |



वित्त मंत्रालय
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Ministry of Finance, Government of India
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LDNG | LAT | Cluster No. | Effectiv
ie Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|---------------|-----------------------------|-----------|-----------|-------------|--------------------|-----------|----------------|
| 370 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265697 | Sope | 65 | 93.168168 | 27.93989 | C57 | 138 | R | Sope |
| 371 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265699 | Walu | 47 | 93.151799 | 27.928253 | C57 | | NIL | |
| 372 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265679 | Bairbaying | 26 | 93.1568 | 27.941258 | C57 | | NIL | |
| 373 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265682 | Lower Lichila | 842 | 93.175322 | 27.924503 | C58 | 224 | B | Lower Lichila |
| 374 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265675 | Sewaring | 82 | 93.184456 | 27.916147 | C58 | | NIL | |
| 375 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265683 | Lee | 123 | 93.195983 | 27.932775 | C59 | 146 | B | Lee |
| 376 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265687 | Rerung | 23 | 93.209494 | 27.946669 | C59 | | NIL | |
| 377 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265695 | Kodola | 77 | 93.223647 | 27.93045 | C59 | 98 | B | Kodola |
| 378 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265692 | Lentexo | 21 | 93.216888 | 27.936085 | C59 | | NIL | |
| 379 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265686 | Ruktepu | 89 | 93.223664 | 27.910155 | C60 | 118 | B | Ruktepu |
| 380 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265689 | Holela | 29 | 93.206536 | 27.903014 | C60 | | NIL | |
| 381 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265686 | Nade | 122 | 93.193362 | 27.963193 | C61 | 177 | B | Nade |
| 382 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265684 | Furung | 55 | 93.194603 | 27.968664 | C61 | | NIL | |
| 383 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265680 | Upper Lichila | 109 | 93.1879 | 27.965947 | C610 | 158 | B | Upper Lichila |
| 384 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265685 | Korouu | 49 | 93.190089 | 27.95965 | C610 | | NIL | |
| 385 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265691 | Tal | 139 | 93.228703 | 27.963663 | C62 | 223 | B | Tal |
| 386 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265690 | Topak | 22 | 93.236416 | 27.94368 | C62 | | NIL | |
| 387 | Arunachal Pradesh | Kurung Kumey | Sarli | Sarli | 265694 | Kanay | 62 | 93.236787 | 27.959951 | C62 | | NIL | |
| 388 | Arunachal Pradesh | Kurung Kumey | Koloriang | Koloriang | 265488 | Tate | 99 | 93.27027 | 27.959141 | C63 | 231 | B | Tate |
| 389 | Arunachal Pradesh | Kurung Kumey | Koloriang | Koloriang | 265486 | Chom | 57 | 93.261708 | 27.953079 | C63 | | NIL | |



भारतीय संचार
RAMESHWAR DHARWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster - No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|--------------|---------------|-----------|----------------|
| 390 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265487 | Katell | 75 | 93.269722 | 27.953911 | C63 | | NIL | |
| 391 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265477 | Buyang-II | 149 | 93.301898 | 27.946177 | C64 | 170 | B | Buyang-II |
| 392 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265479 | Dome | 21 | 93.291698 | 27.946395 | C64 | | NIL | |
| 393 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265483 | Deeging II | 98 | 93.26715 | 27.925182 | C65 | 111 | B | Deeging II |
| 394 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265481 | Rakte | 13 | 93.273592 | 27.929955 | C65 | | NIL | |
| 395 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265497 | Purok | 45 | 93.315632 | 27.930241 | C66 | 61 | B | Purok |
| 396 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265475 | Tamli | 18 | 93.307121 | 27.927786 | C66 | | NIL | |
| 397 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265469 | Nyelin | 75 | 93.309564 | 27.900493 | C67 | 143 | B | Nyolin |
| 398 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265467 | Buhan | 12 | 93.299902 | 27.895523 | C67 | | NIL | |
| 399 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265468 | Johat | 56 | 93.309752 | 27.899154 | C67 | | NIL | |
| 400 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265465 | Nyobia | 52 | 93.282867 | 27.907311 | C68 | 78 | B | Nyobia |
| 401 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265466 | Deyang | 26 | 93.269106 | 27.900744 | C68 | | NIL | |
| 402 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265472 | Naji Bibok | 86 | 93.271456 | 27.872651 | C69 | 143 | B | Naji Bibok |
| 403 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265471 | Kokpu Nyobin | 57 | 93.264031 | 27.869727 | C69 | | NIL | |
| 404 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265464 | Chello | 93 | 93.294114 | 27.86945 | C70 | 157 | B | Chello |
| 405 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265482 | Deeging I | 49 | 93.280136 | 27.889178 | C70 | | NIL | |
| 406 | Arunachal Pradesh | Karung Kumey | Koloniaing | Koloniaing | 265462 | Sangchu | 16 | 93.281948 | 27.880396 | C70 | | NIL | |
| 407 | Arunachal Pradesh | Karung Kumey | Phassang | Nyapin | 265403 | Lamgris | 33 | 93.297969 | 27.720729 | C71 | 61 | B | Lamgris |
| 408 | Arunachal Pradesh | Karung Kumey | Phassang | Nyapin | 265424 | Kajer Solong | 28 | 93.25367 | 27.739011 | C71 | | NIL | |
| 409 | Arunachal Pradesh | Karung Kumey | Phassang | Nyapin | 265388 | Sangripo | 29 | 93.271246 | 27.716985 | C71 | 53 | B | Sangripo |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (IT-1) USOF
 Director (IT-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sl. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effectiv. # pop | Site Type | Tower Location |
|---------|----------------|---------------|-------------------|---------------|--------------|-------------------|-----------------------------|-----------|-----------|------------|-----------------|-----------|----------------|
| 410 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265402 | Favu | 24 | 93.255896 | 27.739912 | C710 | | NIL | |
| 411 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265413 | Ranis | 96 | 93.304897 | 27.772263 | C72 | 154 | B | Ranis |
| 412 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265404 | Sangla | 48 | 93.287497 | 27.759688 | C72 | | NIL | |
| 413 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265423 | Diba Koyla | 123 | 93.318884 | 27.741176 | C73 | 208 | B | Diba Koyla |
| 414 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265417 | Taris | 86 | 93.314732 | 27.732802 | C73 | | NIL | |
| 415 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265420 | Sango | 109 | 93.329758 | 27.735844 | C730 | 137 | B | Sango |
| 416 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265407 | Rugutha | 28 | 93.308687 | 27.752306 | C730 | | NIL | |
| 417 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265412 | Solo | 160 | 93.327746 | 27.769003 | C74 | 315 | B | Solo |
| 418 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265410 | Jugraji | 129 | 93.32691 | 27.772915 | C74 | | NIL | |
| 419 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265411 | Saenlangi(Sulung) | 26 | 93.325067 | 27.762086 | C74 | | NIL | |
| 420 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265416 | Gutha | 113 | 93.337786 | 27.733464 | C75 | 163 | B | Gutha |
| 421 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265419 | Siley | 23 | 93.352246 | 27.747473 | C75 | | NIL | |
| 422 | Andhra Pradesh | Kurung Kurney | Phassang | Nyabin | 265422 | Pincis Solung | 37 | 93.355197 | 27.73858 | C75 | | NIL | |
| 423 | Andhra Pradesh | Kurung Kurney | Nyabin | Nyabin | 265372 | longlefoth | 372 | 93.417953 | 27.744069 | C77 | 408 | B | longlefoth |
| 424 | Andhra Pradesh | Kurung Kurney | Nyabin | Nyabin | 265394 | Gutha | 20 | 93.413778 | 27.735394 | C77 | | NIL | |
| 425 | Andhra Pradesh | Kurung Kurney | Nyabin | Nyabin | 265376 | Aeyer | 16 | 93.437812 | 27.715816 | C77 | | NIL | |
| 426 | Andhra Pradesh | Kurung Kurney | Nyabin | Nyabin | 265373 | Dilanggang | 119 | 93.414423 | 27.777414 | C78 | 157 | B | Dilanggang |
| 427 | Andhra Pradesh | Kurung Kurney | Nyabin | Nyabin | 265380 | Hurga Jarung | 8 | 93.40588 | 27.761985 | C78 | | NIL | |
| 428 | Andhra Pradesh | Kurung Kurney | Nyabin | Nyabin | 265359 | Jangdo | 30 | 93.409134 | 27.748751 | C78 | | NIL | |
| 429 | Andhra Pradesh | Kurung Kurney | Nyabin | Nyabin | 265371 | Tapuk | 170 | 93.429938 | 27.768696 | C78 | 181 | B | Tapuk |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 110 001, New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop. | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|-------------|----------------|-----------|----------------|
| 430 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265367 | Lower Guha | 7 | 93.43942 | 27.762934 | C79 | | NIL | |
| 431 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265369 | Lower Lorio | 4 | 93.43972 | 27.757272 | C79 | | NIL | |
| 432 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265382 | Yarda | 433 | 93.446644 | 27.77631 | C80 | 469 | B | Yarda |
| 433 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265388 | Kish | 36 | 93.458684 | 27.764143 | C80 | | NIL | |
| 434 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265383 | Changlung | 232 | 93.453184 | 27.734239 | C81 | 310 | B | Changlung |
| 435 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265391 | Pach | 57 | 93.457193 | 27.749345 | C81 | | NIL | |
| 436 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265386 | Suria | 21 | 93.463111 | 27.739437 | C81 | | NIL | |
| 437 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265807 | Ruba | 204 | 93.201111 | 28.086764 | C82 | 250 | B | Ruba |
| 438 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265805 | Katuk | 46 | 93.225833 | 28.086711 | C82 | | NIL | |
| 439 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265793 | Kopila | 118 | 93.256814 | 28.074786 | C83 | 233 | B | Kopila |
| 440 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265804 | Loak | 75 | 93.265336 | 28.088333 | C83 | | NIL | |
| 441 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265803 | Figa | 40 | 93.266542 | 28.087336 | C83 | | NIL | |
| 442 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265796 | Chate | 84 | 93.317765 | 28.129802 | C84 | 204 | B | Chate |
| 443 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265795 | Sibia | 61 | 93.290994 | 28.130608 | C84 | | NIL | |
| 444 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265797 | Tikla | 59 | 93.30011 | 28.138948 | C84 | | NIL | |
| 445 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265800 | Senamianji | 60 | 93.290581 | 28.086778 | C85 | 107 | B | Senamianji |
| 446 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265806 | Rawok | 47 | 93.3031 | 28.085086 | C85 | | NIL | |
| 447 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265808 | Fuba | 504 | 93.312539 | 28.074333 | C86 | 372 | B | Fuba |
| 448 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265815 | Namsar | 26 | 93.326855 | 28.071862 | C86 | | NIL | |
| 449 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265812 | Chera | 42 | 93.331258 | 28.080509 | C86 | | NIL | |



॥ वाणिज्य विभाग ॥
RAMESHWAR DHARIVAL
 Director (T-1) USOF
 ॥ वाणिज्य विभाग, अंतर-राज्य ॥
 Deptt. of Telecom, Govt. of India
 New Delhi

1. The information is for reference only and should not be used for any purpose without the prior approval of the Government of India.

| Sr. No. | State Name | District Name | Sub-District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 450 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265784 | Yaso | 43 | 93.327942 | 28.088427 | C87 | 73 | B | Yaso |
| 451 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265802 | Rane | 30 | 93.319358 | 28.099925 | C87 | | NIL | |
| 452 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265814 | Goe | 37 | 93.321383 | 28.044408 | C89 | 66 | B | Goe |
| 453 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265811 | Digok | 28 | 93.326272 | 28.039039 | C89 | | NIL | |
| 454 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265783 | Dubupa | 242 | 93.33997 | 28.046839 | C90 | 323 | B | Dubupa |
| 455 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265785 | Saltan | 81 | 93.338425 | 28.0416 | C90 | | NIL | |
| 456 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265788 | Marangula | 85 | 93.351044 | 28.033378 | C91 | 200 | B | Marangula |
| 457 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265815 | Baino | 48 | 93.348603 | 28.055181 | C91 | | NIL | |
| 458 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265787 | Pipu | 67 | 93.352997 | 28.040147 | C91 | | NIL | |
| 459 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265824 | Kelohng | 89 | 93.425266 | 28.188448 | C92 | 158 | B | Kelohng |
| 460 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265822 | Sutpak | 69 | 93.392053 | 28.193635 | C92 | | NIL | |
| 461 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265809 | Tarla | 64 | 93.367533 | 28.146535 | C93 | 120 | B | Tarla |
| 462 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265803 | Tarik | 56 | 93.362716 | 28.165642 | C93 | | NIL | |
| 463 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265821 | Hark | 64 | 93.383272 | 28.135872 | C93 | 118 | B | Hark |
| 464 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265810 | Nayepuk | 54 | 93.389297 | 28.146282 | C93 | | NIL | |
| 465 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265778 | Tokrang | 150 | 93.36533 | 28.107525 | C94 | 274 | B | Tokrang |
| 466 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265779 | Putong | 124 | 93.346393 | 28.103859 | C94 | | NIL | |
| 467 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265789 | Omia | 118 | 93.384915 | 28.071124 | C95 | 224 | B | Omia |
| 468 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265826 | Chuiba | 106 | 93.378269 | 28.080547 | C95 | | NIL | |
| 469 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265776 | Taba | 73 | 93.411395 | 28.055462 | C97 | 118 | B | Taba |



भारतीय विमान
RAMESHWAR DHARWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sl. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population on of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|----------------|--------------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 470 | Arunachal Pradesh | Karung Kumey | Koloriang | Koloriang | 265484 | Taba | 45 | 93.411195 | 28.055462 | C97 | | NIL | |
| 471 | Arunachal Pradesh | Karung Kumey | Chambang | Chambang | 265541 | Miching | 53 | 93.401059 | 28.072387 | C98 | 102 | B | Miching |
| 472 | Arunachal Pradesh | Karung Kumey | Damin | Damin | 265794 | Huri | 49 | 93.401929 | 28.074609 | C98 | | NIL | |
| 473 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263356 | Seijong | 138 | 94.301597 | 28.767478 | CCC1 | 197 | B | Seijong |
| 474 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263368 | Damsong | 39 | 94.239608 | 28.75526 | CCC1 | | NIL | |
| 475 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263361 | Papie Irong | 138 | 94.234283 | 28.807986 | CCC2 | 175 | B | Papie Irong |
| 476 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263362 | Changrang | 37 | 94.216488 | 28.810142 | CCC2 | | NIL | |
| 477 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263373 | Dipu | 132 | 94.223451 | 28.773452 | CCC4 | 147 | B | Dipu |
| 478 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263365 | Tasum | 15 | 94.225842 | 28.755888 | CCC4 | | NIL | |
| 479 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263390 | Singbu | 51 | 94.29108 | 28.66744 | CCC7 | 76 | B | Singbu |
| 480 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263387 | Sjak | 15 | 94.286062 | 28.674967 | CCC7 | | NIL | |
| 481 | Arunachal Pradesh | West Siang | Pidi | Mechuka | 263404 | Karo | 63 | 94.327339 | 28.627292 | CCC8 | 94 | B | Karo |
| 482 | Arunachal Pradesh | West Siang | Pidi | Mechuka | 263405 | Taryang | 31 | 94.324327 | 28.647993 | CCC8 | | NIL | |
| 483 | Arunachal Pradesh | West Siang | Pidi | Mechuka | 263402 | Lamak | 71 | 94.329972 | 28.621647 | CCC9 | 104 | B | Lamak |
| 484 | Arunachal Pradesh | West Siang | Pidi | Mechuka | 263401 | Tarik Karo III | 33 | 94.333109 | 28.617883 | CCC9 | | NIL | |
| 485 | Arunachal Pradesh | Karung Kumey | Koloriang | Kobadang | 265442 | Sangpor | 55 | 93.41981 | 27.911822 | D10 | 150 | B | Sangpor |
| 486 | Arunachal Pradesh | Karung Kumey | Koloriang | Kobadang | 265443 | Tapin | 51 | 93.436936 | 27.923358 | D10 | | NIL | |
| 487 | Arunachal Pradesh | Karung Kumey | Koloriang | Kobadang | 265444 | Yarpi | 44 | 93.431269 | 27.902566 | D10 | | NIL | |
| 488 | Arunachal Pradesh | Karung Kumey | Damin | Damin | 265790 | Jali | 113 | 93.442182 | 28.046006 | D14 | 161 | B | Jali |
| 489 | Arunachal Pradesh | Karung Kumey | Parsi-Pario | Parsi-Pario | 265775 | Tanuk | 48 | 93.439286 | 28.048578 | D14 | | NIL | |
| 490 | Arunachal Pradesh | Karung Kumey | Parsi-Pario | Parsi-Pario | 265769 | Chete | 99 | 93.452753 | 28.055042 | D140 | 167 | B | Chete |
| 491 | Arunachal Pradesh | Karung Kumey | Koloriang | Kobadang | 265485 | Chete | 13 | 93.452753 | 28.055042 | D140 | | NIL | |
| 492 | Arunachal Pradesh | Karung Kumey | Parsi-Pario | Parsi-Pario | 265766 | Pugim | 55 | 93.45074 | 28.040353 | D140 | | NIL | |
| 493 | Arunachal Pradesh | Karung Kumey | Parsi-Pario | Parsi-Pario | 265764 | Mangio | 123 | 93.453331 | 28.004344 | D15 | 165 | B | Mangio |
| 494 | Arunachal Pradesh | Karung Kumey | Parsi-Pario | Parsi-Pario | 265768 | Dare | 42 | 93.441812 | 28.018317 | D15 | | NIL | |
| 495 | Arunachal Pradesh | Karung Kumey | Parsi-Pario | Parsi-Pario | 265762 | Puchang | 161 | 93.473867 | 28.01437 | D16 | 297 | B | Puchang |




RAMESHWAR DHARIWAL
 Director (C-1) JSCOF
 Greater Kharak, West Sector
 Dept. of Telecom, Govt. of India
 New Delhi

| Sr No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|--------|-------------------|---------------|------------------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|----------------|
| 496 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265761 | Dabang | 136 | 93.472028 | 28.024781 | D16 | | NIL | |
| 497 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265763 | Hishi | 263 | 93.483673 | 28.01105 | D17 | 515 | B | Kachi |
| 498 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265760 | Paruk | 123 | 93.490846 | 28.012293 | D17 | | NIL | |
| 499 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265765 | Pape | 129 | 93.494561 | 28.015853 | D17 | | NIL | |
| 500 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265771 | Malla | 218 | 93.484908 | 28.023913 | D18 | 450 | B | Mala |
| 501 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265770 | Lamma | 86 | 93.483569 | 28.037484 | D18 | | NIL | |
| 502 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265772 | Paohi | 146 | 93.492279 | 28.024778 | D18 | | NIL | |
| 503 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265774 | Geyang | 167 | 93.515669 | 28.017496 | D19 | 322 | B | Geyang |
| 504 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265767 | Topurang | 155 | 93.509472 | 28.027454 | D19 | | NIL | |
| 505 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265759 | Joku | 140 | 93.502486 | 28.006994 | D20 | 388 | B | Joku |
| 506 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265715 | Mangdol | 134 | 93.4937 | 27.996803 | D20 | | NIL | |
| 507 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265751 | Pilop | 114 | 93.513606 | 27.996772 | D20 | | NIL | |
| 508 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265819 | Dogwa | 173 | 93.420918 | 28.121151 | D21 | 239 | B | Dogwa |
| 509 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265828 | Hume | 66 | 93.43421 | 28.11887 | D21 | | NIL | |
| 510 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265827 | Dana | 135 | 93.436826 | 28.14253 | D22 | 247 | B | Dana |
| 511 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265820 | Nisak | 35 | 93.432746 | 28.131713 | D22 | | NIL | |
| 512 | Arunachal Pradesh | Kurung Kumey | Damin | Damin | 265829 | Chedam | 77 | 93.448921 | 28.1339 | D22 | | NIL | |
| 513 | Arunachal Pradesh | Kurung Kumey | Longding Kelling (Pisporang) | Pisporang | 265860 | Raha | 173 | 93.502372 | 28.101431 | D23 | 241 | B | Raha |
| 514 | Arunachal Pradesh | Kurung Kumey | Longding Kelling (Pisporang) | Pisporang | 265861 | Chome | 68 | 93.520682 | 28.111525 | D23 | | NIL | |
| 515 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265729 | Solang | 100 | 93.546586 | 28.026877 | D24 | 156 | B | Solang |




रामेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective POP | Site Type | Tower Location |
|---------|-------------------|---------------|----------------------------|---------------|--------------|----------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|----------------|
| 516 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265746 | Lemnang | 55 | 93.540291 | 28.035341 | D24 | | NIL | |
| 517 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265755 | Yank | 133 | 93.568141 | 28.008645 | D25 | 381 | B | YANK |
| 518 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265745 | Hssang | 48 | 93.572486 | 28.010729 | D25 | | NIL | |
| 519 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Piporang) | Piporang | 265856 | Biya | 217 | 93.564981 | 28.049311 | D26 | 266 | B | Biya |
| 520 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Piporang) | Piporang | 265858 | Habak | 49 | 93.580961 | 28.066592 | D26 | | NIL | |
| 521 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Piporang) | Piporang | 265854 | Pija | 88 | 93.618308 | 28.036725 | D27 | 208 | B | Pija |
| 522 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Piporang) | Piporang | 265857 | Cutam | 34 | 93.597633 | 28.049164 | D27 | | NIL | |
| 523 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Piporang) | Piporang | 265855 | Hajuk (1) | 86 | 93.615775 | 28.052138 | D27 | | NIL | |
| 524 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265716 | Gonang | 365 | 93.525341 | 27.981533 | D30 | 590 | B | Gonang |
| 525 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265722 | Bampung Hema | 72 | 93.51446 | 27.976903 | D30 | | NIL | |
| 526 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265749 | Mado | 153 | 93.552964 | 27.982503 | D30 | | NIL | |
| 527 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265720 | Rierdiporang-1 | 165 | 93.540972 | 27.984826 | D31 | 239 | B | Rierdiporang-1 |
| 528 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265744 | Barbit | 74 | 93.534544 | 27.990947 | D31 | | NIL | |
| 529 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265757 | Kellin | 96 | 93.545417 | 27.961866 | D33 | 186 | B | Kellin |
| 530 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265742 | Rashab-1 | 90 | 93.541389 | 27.969814 | D33 | | NIL | |
| 531 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Piporang) | Piporang | 265852 | Sanga | 239 | 93.606728 | 27.989239 | D34 | 272 | B | Sanga |
| 532 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Piporang) | Piporang | 265851 | Rubak | 33 | 93.606625 | 27.98195 | D34 | | NIL | |
| 533 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265730 | Yerba | 185 | 93.566267 | 27.957456 | D35 | 460 | B | Yerba |
| 534 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265731 | Yarbit | 142 | 93.577332 | 27.963971 | D35 | | NIL | |
| 535 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265733 | Paolo | 133 | 93.579623 | 27.980035 | D35 | | NIL | |




रमेश्वर धारिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Street, New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|------------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|------------------|
| 536 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265735 | Segrang | 157 | 93.555458 | 27.953617 | 036 | 249 | B | Segrang |
| 537 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265736 | Marna | 92 | 93.571375 | 27.948853 | 036 | | NIL | |
| 538 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265712 | Parsi-Parlo H.Q. | 234 | 93.495517 | 27.926281 | 038 | 320 | B | Parsi-Parlo H.Q. |
| 539 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265725 | Bigo | 86 | 93.512414 | 27.932239 | 038 | | NIL | |
| 540 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265309 | Pixepa | 68 | 93.489053 | 27.776609 | 040 | 119 | B | Pixepa |
| 541 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265308 | Tagam | 51 | 93.492001 | 27.787408 | 040 | | NIL | |
| 542 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265287 | Dangu | 101 | 93.510545 | 27.852843 | 043 | 186 | B | Dangu |
| 543 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265294 | Gernepuji | 36 | 93.565889 | 27.868529 | 043 | | NIL | |
| 544 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265295 | Sara | 49 | 93.507625 | 27.860449 | 043 | | NIL | |
| 545 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265284 | Pogga | 219 | 93.560651 | 27.860937 | 044 | 449 | B | Pogga |
| 546 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265285 | Naggar | 112 | 93.540037 | 27.849912 | 044 | | NIL | |
| 547 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265327 | Hyoti | 118 | 93.573973 | 27.849345 | 044 | | NIL | |
| 548 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265382 | Renup | 192 | 93.582737 | 27.875104 | 045 | 294 | B | Renup |
| 549 | Arunachal Pradesh | Kurung Kumey | Sangram | Sangram | 265283 | Kagang | 102 | 93.579709 | 27.860733 | 045 | | NIL | |
| 550 | Arunachal Pradesh | Kurung Kumey | Yangte | Yangte | 265267 | Homi | 257 | 93.676131 | 27.927288 | 046 | 406 | B | Homi |
| 551 | Arunachal Pradesh | Kurung Kumey | Yangte | Yangte | 265270 | Barta Camp | 45 | 93.661968 | 27.931138 | 046 | | NIL | |
| 552 | Arunachal Pradesh | Kurung Kumey | Yangte | Yangte | 265255 | Sangluh Langi | 104 | 93.662033 | 27.908686 | 046 | | NIL | |
| 553 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265897 | Pichu | 160 | 93.760497 | 27.979036 | 047 | 278 | B | Pichu |
| 554 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265896 | Kiwa | 118 | 93.750503 | 27.994015 | 047 | | NIL | |
| 555 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265872 | Tanuk | 385 | 93.773552 | 28.021646 | 048 | 405 | B | Tanuk |




RAMESHWAR DHARIWAL
 Director (B-T) & Gen. Mgr. Secy.
 Bharti Telecom Limited
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 556 | Arunachal Pradesh | Karung Kumey | Tali | Tali | 265867 | Tali | 120 | 93.760616 | 28.005401 | D48 | | NIL | |
| 557 | Arunachal Pradesh | Karung Kumey | Yangte | Sangrai | 265258 | Ringte | 123 | 93.664354 | 27.758496 | D49 | 210 | B | Ringte |
| 558 | Arunachal Pradesh | Karung Kumey | Chamrang | Chamrang | 265515 | Sengching | 87 | 93.673333 | 27.76155 | D49 | | NIL | |
| 559 | Arunachal Pradesh | Karung Kumey | Yangte | Sangrai | 265269 | Magney | 155 | 93.613517 | 27.753647 | D53 | 248 | B | Magney |
| 560 | Arunachal Pradesh | Karung Kumey | Chamrang | Chamrang | 265542 | Tapaha | 59 | 93.611465 | 27.749476 | D53 | | NIL | |
| 561 | Arunachal Pradesh | Karung Kumey | Chamrang | Chamrang | 265556 | Tapaha | 34 | 93.611465 | 27.749476 | D53 | | NIL | |
| 562 | Arunachal Pradesh | Karung Kumey | Yangte | Sangrai | 265266 | Dudo | 168 | 93.616097 | 27.742054 | D54 | 422 | B | Dudo |
| 563 | Arunachal Pradesh | Karung Kumey | Palin | Palin | 265235 | Jaming Happa | 254 | 93.608263 | 27.744156 | D54 | | NIL | |
| 564 | Arunachal Pradesh | Karung Kumey | Palin | Palin | 265229 | Lungburi | 218 | 93.541188 | 27.709836 | D55 | 369 | B | Langdung |
| 565 | Arunachal Pradesh | Karung Kumey | Palin | Palin | 265184 | Eichang | 151 | 93.540316 | 27.701413 | D55 | | NIL | |
| 566 | Arunachal Pradesh | Karung Kumey | Palin | Palin | 265182 | Sanglum | 256 | 93.639819 | 27.693631 | D57 | 391 | B | Sanglum |
| 567 | Arunachal Pradesh | Karung Kumey | Saib | Saib | 265681 | New Saib | 26 | 93.632947 | 27.694403 | D57 | | NIL | |
| 568 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265748 | Cheba | 109 | 93.641 | 27.672719 | D57 | | NIL | |
| 569 | Arunachal Pradesh | Karung Kumey | Palin | Palin | 265226 | Pungmi | 85 | 93.695271 | 27.694475 | D58 | 708 | B | Pungmi |
| 570 | Arunachal Pradesh | Karung Kumey | Palin | Palin | 265224 | Serak | 26 | 93.700015 | 27.688544 | D58 | | NIL | |
| 571 | Arunachal Pradesh | Karung Kumey | Palin | Palin | 265222 | Tegdo | 97 | 93.709157 | 27.705562 | D58 | | NIL | |
| 572 | Arunachal Pradesh | Papum Pare | Singdopota (Besar Nebo) | Baijan | 262397 | Palap | 40 | 93.334205 | 27.675323 | D59 | 60 | B | Phalap |
| 573 | Arunachal Pradesh | Papum Pare | Singdopota (Besar Nebo) | Baijan | 262403 | Ragla | 20 | 93.330725 | 27.108822 | D59 | | NIL | |
| 574 | Arunachal Pradesh | Papum Pare | Singdopota (Besar Nebo) | Baijan | 262386 | Yasurso | 94 | 93.372239 | 27.072044 | D60 | 136 | B | Yasurso |
| 575 | Arunachal Pradesh | Papum Pare | Singdopota (Besar Nebo) | Baijan | 262400 | Myong | 42 | 93.351674 | 27.061203 | D60 | | NIL | |




रमेश्वर धरवाल
RAMESHWAR DHARWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Director (T-1) USOF
 Dept. of Telecom, Govt. of India
 28 (Green)/New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effectively Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|-------------|-----------------|-----------|----------------|
| 576 | Arunachal Pradesh | Karung Kurney | Tarak Lengdi | Tak | 265656 | Lengding | 265 | 93.389932 | 27.24142 | 062 | 373 | B | Lengding |
| 577 | Arunachal Pradesh | Papum Pare | Leporing | Sagalee | 262657 | Landing | 51 | 93.37657 | 27.230252 | 062 | | NIL | |
| 578 | Arunachal Pradesh | Papum Pare | Leporing | Sagalee | 262653 | Raneso | 57 | 93.397355 | 27.232703 | 062 | | NIL | |
| 579 | Arunachal Pradesh | Papum Pare | Tarao | Babjen | 262428 | Papum | 69 | 93.7029 | 27.17903 | 071 | 135 | B | Papum |
| 580 | Arunachal Pradesh | Papum Pare | Nahidagun | Dornjali | 262488 | Hara Happa | 66 | 93.7195 | 27.161597 | 071 | | NIL | |
| 581 | Arunachal Pradesh | Papum Pare | Toru | Sagalee | 262544 | Papum | 100 | 93.674625 | 27.258557 | 072 | 227 | B | POPO |
| 582 | Arunachal Pradesh | Papum Pare | Toru | Sagalee | 262543 | Ompuli | 76 | 93.678086 | 27.256317 | 072 | | NIL | |
| 583 | Arunachal Pradesh | Papum Pare | Toru | Sagalee | 262541 | Kunglo | 51 | 93.680801 | 27.263183 | 072 | | NIL | |
| 584 | Arunachal Pradesh | Papum Pare | Toru | Sagalee | 262538 | Birup | 100 | 93.671872 | 27.271825 | 073 | 185 | B | Birup |
| 585 | Arunachal Pradesh | Papum Pare | Toru | Sagalee | 262551 | 47 K.M. Camp | 13 | 93.668444 | 27.276225 | 073 | | NIL | |
| 586 | Arunachal Pradesh | Papum Pare | Toru | Sagalee | 262540 | New Gaya | 72 | 93.678923 | 27.270835 | 073 | | NIL | |
| 587 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264904 | Sikhe | 88 | 93.624102 | 27.541484 | 080 | 169 | B | Sikhe |
| 588 | Arunachal Pradesh | Lower Subansiri | Potana | Ziro-II | 265001 | Tako | 78 | 93.607425 | 27.525572 | 080 | | NIL | |
| 589 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264918 | Roo | 183 | 93.763603 | 27.378956 | 084 | 331 | B | Bilo |
| 590 | Arunachal Pradesh | Karung Kurney | Damen | Damen | 265791 | Pam | 148 | 93.759262 | 27.356012 | 084 | | NIL | |
| 591 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264906 | Pogi Happa | 100 | 93.740213 | 27.381233 | 085 | 107 | B | Pogi Happa |
| 592 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264905 | Honu Happa | 7 | 93.726805 | 27.375235 | 085 | | NIL | |
| 593 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264895 | Komru | 62 | 93.726231 | 27.438373 | 088 | 95 | B | Komru |
| 594 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264903 | Desh | 33 | 93.738610 | 27.436267 | 088 | | NIL | |
| 595 | Arunachal Pradesh | Lower Subansiri | Pitana | Ziro-II | 264996 | Pochu | 235 | 93.799572 | 27.451502 | 088 | 280 | B | Pochu |
| 596 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264913 | Thowu | 45 | 93.813441 | 27.450557 | 089 | | NIL | |
| 597 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264917 | Swry Danga | 232 | 93.802524 | 27.432099 | 091 | 305 | B | Swry Danga |
| 598 | Arunachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264916 | Lichti Chh | 73 | 93.814433 | 27.435641 | 091 | | NIL | |
| 599 | Arunachal Pradesh | Lower Subansiri | Kamponjo | Tansen-Raga | 265030 | Chimur | 50 | 94.021893 | 27.752649 | 093 | 92 | B | Chimur |
| 600 | Arunachal Pradesh | Lower Subansiri | Kamponjo | Tansen-Raga | 265034 | Indra Awas | 42 | 94.032444 | 27.709489 | 093 | | NIL | |



| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------|--------------|----------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------------|
| 601 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265153 | Saddle | 107 | 94.16381 | 27.782942 | D85 | 127 | B | Saddle |
| 602 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265132 | Rite | 25 | 94.146093 | 27.762553 | D85 | | NIL | |
| 603 | Arunachal Pradesh | Upper Subansiri | Daporijo | | 263132 | Rite | 65 | 94.146093 | 27.762553 | D950 | 100 | B | Rite |
| 604 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265163 | Heba Kabak | 41 | 94.1398 | 27.784186 | D950 | | NIL | |
| 605 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262821 | Aki | 175 | 93.876273 | 28.395604 | D96 | 254 | B | Aki |
| 606 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262807 | Bosral | 79 | 93.904128 | 28.399442 | D96 | | NIL | |
| 607 | Arunachal Pradesh | Kurang Kumey | Parsi-Parlo | | 265773 | Dupe | 112 | 93.935208 | 28.371764 | D97 | 211 | B | Dupe |
| 608 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262804 | Dupe | 23 | 93.935208 | 28.371764 | D97 | | NIL | |
| 609 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262802 | Chakka | 76 | 93.944557 | 28.383981 | D97 | | NIL | |
| 610 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262800 | Gumung | 169 | 93.955696 | 28.360755 | D98 | 202 | B | Gumung |
| 611 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262842 | lingar | 33 | 93.974099 | 28.348628 | D98 | | NIL | |
| 612 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262936 | Arna | 95 | 94.183606 | 28.208578 | D99 | 176 | B | Arna |
| 613 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262969 | Siring | 81 | 94.168781 | 28.210122 | D99 | | NIL | |
| 614 | Arunachal Pradesh | West Siang | Ailo | Ailo East | 263594 | Hu Mobil(Estn Mobil) | 162 | 94.681653 | 28.133036 | D08 | 323 | B | Hu Mobil(Estn Mobil) |
| 615 | Arunachal Pradesh | West Siang | Ailo | Ailo East | 263593 | Nilke Camp | 161 | 94.670714 | 28.130286 | D08 | | NIL | |
| 616 | Arunachal Pradesh | West Siang | Pidi | Mechuka | 263400 | Besang (Karo IV) | 108 | 94.3375 | 28.612865 | D001 | 131 | B | Besang (Karo IV) |
| 617 | Arunachal Pradesh | West Siang | Pidi | Mechuka | 263406 | Rong | 23 | 94.318054 | 28.613497 | D001 | | NIL | |
| 618 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263441 | V.B. Camp | 96 | 94.343919 | 28.515032 | D006 | 171 | B | V.B. Camp |
| 619 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263428 | Upper Heryo | 75 | 94.343076 | 28.522814 | D006 | | NIL | |
| 620 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263427 | Karimo | 223 | 94.340567 | 28.493331 | D007 | 245 | B | Karimo |
| 621 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263426 | Karenging | 22 | 94.351231 | 28.49584 | D007 | | NIL | |
| 622 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263434 | Yapli | 246 | 94.463536 | 28.488568 | D008 | 287 | B | Yapli |
| 623 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263442 | Pibuying | 41 | 94.466987 | 28.495517 | D008 | | NIL | |
| 624 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263443 | Qomng | 145 | 94.413199 | 28.49396 | D009 | 194 | B | Qomng |





RAMESHWAR DHARIWAL
 Director (IT-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG. | LAT. | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|--------------------|---------------|--------------|----------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|-----------------|
| 625 | Arunachal Pradesh | West Siang | Teto | Mechuka | 263438 | Road Labour Camp (I) | 18 | 94.401675 | 28.500231 | DD09 | | NIL | |
| 626 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263094 | Raji | 149 | 94.070198 | 28.032134 | E11 | 279 | B | Raji |
| 627 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263000 | Sera/Tapapu | 80 | 94.063483 | 28.034717 | E11 | | NIL | |
| 628 | Arunachal Pradesh | Kunung Kurney | Parsi-Parlo | Parsi-Parlo | 265727 | Sera | 220 | 94.07705 | 28.059157 | E12 | 355 | B | Sera |
| 629 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263064 | Kikix | 65 | 94.070183 | 28.057722 | E12 | | NIL | |
| 630 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263096 | Sera | 70 | 94.07705 | 28.059157 | E12 | | NIL | |
| 631 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263063 | Meringia | 256 | 94.053175 | 28.064464 | E13 | 264 | B | Meringia |
| 632 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263062 | Molo | 8 | 94.061795 | 28.061859 | E13 | | NIL | |
| 633 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263182 | Rite Raja | 79 | 94.264808 | 27.905136 | E16 | 116 | B | Rite Raja |
| 634 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263183 | Sabila | 37 | 94.247644 | 27.915593 | E16 | | NIL | |
| 635 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263175 | Takes Bate | 101 | 94.250254 | 27.871341 | E17 | 190 | B | Takes Bate |
| 636 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263171 | Dak | 89 | 94.295684 | 27.869942 | E17 | | NIL | |
| 637 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263172 | Tape | 138 | 94.286965 | 27.879922 | E18 | 178 | B | Tape |
| 638 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263163 | Loimari | 40 | 94.27949 | 27.890421 | E18 | | NIL | |
| 639 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263173 | Depu | 122 | 94.28719 | 27.87266 | E180 | 192 | B | Depu |
| 640 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263174 | Temko | 70 | 94.28862 | 27.87461 | E180 | | NIL | |
| 641 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263154 | Puchi Geko H.C. | 408 | 94.245192 | 27.821819 | E19 | 479 | B | Puchi Geko H.C. |
| 642 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263149 | Gich Puta | 13 | 94.236079 | 27.830854 | E19 | | NIL | |
| 643 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263152 | Pega Kayo | 58 | 94.26332 | 27.840298 | E19 | | NIL | |
| 644 | Arunachal Pradesh | West Siang | Site | Gensi | 263099 | Taramoni | 134 | 94.517052 | 27.74708 | E22 | 161 | B | Taramoni |
| 645 | Arunachal Pradesh | West Siang | Site | Gensi | 263103 | Eiba | 37 | 94.500865 | 27.75203 | E22 | | NIL | |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-3) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop. | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|------------------|-----------------------------|-----------|-----------|------------|----------------|-----------|------------------|
| 646 | Arunachal Pradesh | West Siang | Gensi | Gensi | 263603 | Tarāhri | 161 | 94.479685 | 27.79695 | E23 | 388 | B | Taramari |
| 647 | Arunachal Pradesh | West Siang | Sibe | Gensi | 263701 | Pamori | 140 | 94.481278 | 27.793117 | E23 | | NIL | |
| 648 | Arunachal Pradesh | West Siang | Kanglu | Gensi | 263702 | Ring | 87 | 94.498147 | 27.777893 | E23 | | NIL | |
| 649 | Arunachal Pradesh | West Siang | Kanglu | Ukibali | 263754 | Ngepi | 153 | 94.617803 | 27.643183 | E24 | 211 | B | Ngepi |
| 650 | Arunachal Pradesh | West Siang | Kanglu | Ukibali | 263755 | New Ngepi | 58 | 94.621134 | 27.630669 | E24 | | NIL | |
| 651 | Arunachal Pradesh | West Siang | Kanglu | Ukibali | 263756 | Lilipuhar | 59 | 94.595699 | 27.636668 | E25 | 104 | B | Lalpuha |
| 652 | Arunachal Pradesh | West Siang | Kanglu | Ukibali | 263753 | Lower Barajan | 45 | 94.604093 | 27.62651 | E25 | | NIL | |
| 653 | Arunachal Pradesh | West Siang | Ukibali | Ukibali | 263720 | Magi | 110 | 94.678603 | 27.703044 | E26 | 145 | B | Magi |
| 654 | Arunachal Pradesh | West Siang | Ukibali | Ukibali | 263719 | Kane | 35 | 94.638501 | 27.722189 | E26 | | NIL | |
| 655 | Arunachal Pradesh | West Siang | Danang | Basar | 263683 | Jime | 91 | 94.887787 | 27.887814 | E28 | 116 | B | Jime |
| 656 | Arunachal Pradesh | East Siang | Koyu | Ramle-Bangd | 263828 | Jite | 25 | 94.900681 | 27.900314 | E28 | | NIL | |
| 657 | Arunachal Pradesh | West Siang | Basar | Basar | 263666 | Dip | 287 | 94.732367 | 27.924567 | E30 | 361 | B | Dip |
| 658 | Arunachal Pradesh | West Siang | Basar | Basar | 263663 | Taba (Everest) | 74 | 94.692465 | 27.937796 | E30 | | NIL | |
| 659 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263545 | Lurum | 145 | 94.482655 | 28.062662 | E34 | 205 | B | Lurum |
| 660 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263537 | Esse Tamen | 60 | 94.484933 | 28.06383 | E34 | | NIL | |
| 661 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263533 | Esse Albe | 123 | 94.493407 | 28.084296 | E36 | 222 | B | Esse-Albe |
| 662 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263535 | Esse Upe | 99 | 94.495872 | 28.079003 | E36 | | NIL | |
| 663 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263534 | Esse Kerte | 83 | 94.501517 | 28.082176 | E36 | 140 | B | Esse Kerte |
| 664 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263536 | Esse Tanih | 57 | 94.497636 | 28.099468 | E36 | | NIL | |
| 665 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263530 | Doko Pulu | 114 | 94.514573 | 28.117111 | E37 | 145 | B | Doko Pulu |
| 666 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263546 | Moya Ronyal | 31 | 94.523344 | 28.088767 | E37 | | NIL | |
| 667 | Arunachal Pradesh | West Siang | Lirumba | Lirumba | 263549 | Rikou Ronyal | 96 | 94.538684 | 28.137723 | E38 | 165 | B | Rikou Ronyal |
| 668 | Arunachal Pradesh | West Siang | Yoncha | Lirumba | 263561 | Demenisa | 69 | 94.547924 | 28.138844 | E38 | | NIL | |
| 669 | Arunachal Pradesh | West Siang | Darak | Darak | 263469 | Boje Ite | 148 | 94.590641 | 28.17436 | E39 | 347 | B | Boje Ite |
| 670 | Arunachal Pradesh | West Siang | Darak | Darak | 263466 | Sala Fomam | 169 | 94.586228 | 28.180767 | E39 | | NIL | |
| 671 | Arunachal Pradesh | West Siang | Darak | Darak | 263467 | Boje Kuj | 90 | 94.592463 | 28.168362 | E39 | | NIL | |
| 672 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263338 | Rego | 125 | 94.223637 | 28.556838 | E40 | 227 | B | Rego |
| 673 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263243 | Puyang | 107 | 94.217034 | 28.563389 | E40 | | NIL | |
| 674 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263335 | Ungdungloli | 42 | 94.192633 | 28.533936 | E41 | 82 | B | Ungdungloli |
| 675 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263347 | Chengrong | 8 | 94.175541 | 28.544989 | E41 | | NIL | |
| 676 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263334 | Karte | 32 | 94.180033 | 28.517881 | E41 | | NIL | |
| 677 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263336 | Dorjeeling | 191 | 94.155792 | 28.578078 | E42 | 399 | B | Dorjeeling |
| 678 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263337 | Sokar | 91 | 94.123359 | 28.569241 | E42 | | NIL | |
| 679 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263331 | Barangang | 117 | 94.136833 | 28.559125 | E42 | | NIL | |
| 680 | Arunachal Pradesh | West Siang | Monyong | Monyong | 263384 | Tanghak Yanglung | 155 | 94.340636 | 28.675594 | E47 | 212 | B | Tanghak Yanglung |
| 681 | Arunachal Pradesh | West Siang | Pwa | Mechuka | 263407 | Jerong | 57 | 94.328187 | 28.677887 | E47 | | NIL | |




RAMESHWAR DHARIWAL
 Director (H-1) BSNL
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-----------------------|----------------|--------------|------------------------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|-----------------------------|
| 682 | Arunachal Pradesh | West Siang | Mongong | Mongong | 263378 | Talinglak | 67 | 94.346909 | 28.700686 | E48 | 195 | B | Talinglak |
| 683 | Arunachal Pradesh | West Siang | Mongong | Mongong | 263380 | Plaming | 74 | 94.317427 | 28.705704 | E48 | | NIL | |
| 684 | Arunachal Pradesh | West Siang | Mongong | Mongong | 263379 | Ranno Sumi | 54 | 94.338127 | 28.691159 | E48 | | NIL | |
| 685 | Arunachal Pradesh | West Siang | Mongong | Mongong | 263381 | Henni | 144 | 94.338264 | 28.717286 | E49 | 287 | B | Henni |
| 686 | Arunachal Pradesh | West Siang | Mongong | Mongong | 263382 | Talamyng | 143 | 94.331109 | 28.716996 | E49 | | NIL | |
| 687 | Arunachal Pradesh | Upper Siang | Singa | Singa-Gelling | 263969 | Tashu Gaon | 117 | 95.101795 | 28.873464 | E55 | 137 | B | Tashu Gaon |
| 688 | Arunachal Pradesh | Upper Siang | Singa | Singa-Gelling | 263970 | Silipa | 20 | 95.129428 | 28.848442 | E55 | | NIL | |
| 689 | Arunachal Pradesh | Upper Siang | Mariyang | Mariyang | 264017 | Milang Karfoet | 240 | 95.252797 | 28.429619 | E57 | 339 | B | Milang Karfoet |
| 690 | Arunachal Pradesh | Upper Siang | Mariyang | Mariyang | 264018 | Milang Langdum-Langko(Siang) | 99 | 95.243781 | 28.505071 | E57 | | NIL | |
| 691 | Arunachal Pradesh | Upper Siang | Mariyang | Mariyang | 264020 | Dalang Gidum | 620 | 95.210239 | 28.527222 | E59 | 707 | B | Dalang Gidum |
| 692 | Arunachal Pradesh | Upper Siang | Mariyang | Mariyang | 264023 | Peh-Modi | 87 | 95.242156 | 28.564333 | E59 | | NIL | |
| 693 | Arunachal Pradesh | Lower Dibang Valley | Tenki (Paglam) | Dambuk | 266338 | Kaling II | 216 | 95.565401 | 27.973796 | E61 | 379 | B | Kaling II |
| 694 | Arunachal Pradesh | Lower Dibang Valley | Tenki (Paglam) | Dambuk | 266337 | Kaling I | 163 | 95.568629 | 27.979608 | E61 | | NIL | |
| 695 | Arunachal Pradesh | Dibang Valley | Anelth | Anelth-Arzu | 266019 | Wanth | 43 | 95.828943 | 28.535599 | E63 | 57 | B | Wanth |
| 696 | Arunachal Pradesh | Dibang Valley | Kronli (Arzoo circle) | Anelth-Arzu | 266031 | Endoih | 3 | 95.838744 | 28.526003 | E63 | | NIL | |
| 697 | Arunachal Pradesh | Dibang Valley | Kronli (Arzoo circle) | Anelth-Arzu | 266040 | Karo | 11 | 95.851342 | 28.525511 | E63 | | NIL | |
| 698 | Arunachal Pradesh | Dibang Valley | Kronli (Arzoo circle) | Anelth-Arzu | 266044 | 173 K.M. Point | 175 | 95.848918 | 28.502029 | E64 | 228 | B | 173 K.M. Point |
| 699 | Arunachal Pradesh | Dibang Valley | Etalsh | Etalsh-Malloye | 265969 | Ambolin | 25 | 95.856581 | 28.506514 | E64 | | NIL | |
| 700 | Arunachal Pradesh | Dibang Valley | Kronli (Arzoo circle) | Anelth-Arzu | 266035 | Schigo | 30 | 95.893317 | 28.496736 | E64 | | NIL | |
| 701 | Arunachal Pradesh | West Siang | Sibe | Sibe | 263710 | Tango | 94 | 94.386381 | 27.756649 | E65 | 131 | B | Tango |
| 702 | Arunachal Pradesh | West Siang | Sibe | Sibe | 263698 | Gengi | 37 | 94.379947 | 27.732719 | E65 | | NIL | |
| 703 | Arunachal Pradesh | West Siang | Tabin | Tabin | 263616 | Dedu Doka | 162 | 94.608864 | 28.006114 | E68 | 297 | B | Dedu Doka |
| 704 | Arunachal Pradesh | West Siang | Tabin | Tabin | 263617 | Molba Doka | 135 | 94.602547 | 28.004161 | E68 | | NIL | |
| 705 | Arunachal Pradesh | West Siang | Taro | Mechuka | 263445 | Hone | 140 | 94.537249 | 28.510036 | EE61 | 185 | B | Hone |
| 706 | Arunachal Pradesh | West Siang | Taro | Mechuka | 263446 | Pene | 45 | 94.517004 | 28.504479 | EE61 | | NIL | |
| 707 | Arunachal Pradesh | West Siang | Payum | Xaying-Payum | 263416 | Dupa(INCLUDING Cheyng Camp) | 149 | 94.609361 | 28.476429 | EE63 | 231 | B | Dupa(INCLUDING Cheyng Camp) |
| 708 | Arunachal Pradesh | West Siang | Payum | Xaying-Payum | 263421 | Cheyng | 82 | 94.674103 | 28.47263 | EE63 | | NIL | |




रामेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|------------|---------------|-----------|------------------------|
| 709 | Arunachal Pradesh | West Siang | Bagra | Aalo West | 26370 | Pipi Moll | 62 | 94.709342 | 28.079378 | EE7 | 112 | B | Pigi Moll |
| 710 | Arunachal Pradesh | West Siang | Bagra | Aalo West | 26372 | Doyor | 50 | 94.709389 | 28.078996 | EE7 | | NIL | |
| 711 | Arunachal Pradesh | Kurung Kumey | Damen | Damen | 265782 | Cheya | 135 | 95.831988 | 28.68152 | F10 | 166 | B | Cheya |
| 712 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265955 | Emiya | 9 | 95.831361 | 28.678789 | F10 | | NIL | |
| 713 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265954 | Cheya | 22 | 95.831988 | 28.68152 | F10 | | NIL | |
| 714 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265957 | Punli | 85 | 95.826885 | 28.661347 | F11 | 98 | B | Punli |
| 715 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265956 | Granli | 13 | 95.848686 | 28.665585 | F11 | | NIL | |
| 716 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265912 | Brango | 127 | 95.773351 | 28.952283 | F12 | 152 | B | Brango |
| 717 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265914 | Mibida | 25 | 95.764397 | 28.967897 | F12 | | NIL | |
| 718 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265917 | Beyanli | 47 | 95.772297 | 28.005172 | F13 | 66 | B | Beyanli |
| 719 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265920 | Miji H.O. | 19 | 95.7601 | 28.985625 | F13 | | NIL | |
| 720 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265940 | Echho | 22 | 95.92118 | 28.894673 | F14 | 43 | B | Echho |
| 721 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265939 | Ehamez | 20 | 95.969496 | 28.891329 | F14 | | NIL | |
| 722 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265938 | Maley | 1 | 95.976147 | 28.894482 | F14 | | NIL | |
| 723 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265941 | Etabe | 88 | 95.99763 | 28.838113 | F15 | 99 | B | Etabe |
| 724 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265928 | Arbax | 11 | 95.972531 | 28.837674 | F15 | | NIL | |
| 725 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265925 | Agaga | 84 | 95.951237 | 28.842398 | F17 | 115 | B | Agaga |
| 726 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265930 | Millye | 31 | 95.960575 | 28.845331 | F17 | | NIL | |
| 727 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265935 | Singo | 69 | 95.935089 | 28.834343 | F18 | 110 | B | Singo |
| 728 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265934 | Ayongbo | 41 | 95.932026 | 28.825336 | F18 | | NIL | |
| 729 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265953 | Eyonggo | 62 | 95.933171 | 28.743041 | F19 | 94 | B | Eyonggo |
| 730 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265945 | Larango | 32 | 95.929705 | 28.793265 | F19 | | NIL | |
| 731 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265927 | New Achuli | 13 | 96.008926 | 28.763429 | F20 | 35 | B | New Achuli |
| 732 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265944 | Ahuni | 11 | 95.982383 | 28.784639 | F20 | | NIL | |
| 733 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265929 | Tangpa-2 | 11 | 96.011793 | 28.798008 | F20 | | NIL | |
| 734 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265959 | Karu | 63 | 95.888076 | 28.794114 | F21 | 111 | B | Karu |
| 735 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265960 | Kyalumbo | 48 | 95.887299 | 28.799905 | F21 | | NIL | |
| 736 | Arunachal Pradesh | Lohit | Tezu | Tezu | 266402 | Jainko | 26 | 96.268655 | 27.935419 | F26 | 47 | B | Jainko |
| 737 | Arunachal Pradesh | Lohit | Tezu | Tezu | 266403 | Chetanguni | 21 | 96.301371 | 27.94575 | F26 | | NIL | |
| 738 | Arunachal Pradesh | Lohit | Pyiong | Manasai | 266603 | Wingseng | 244 | 95.948063 | 27.82284 | F30 | 252 | B | Wingseng
Nonetaw II |
| 739 | Arunachal Pradesh | Lohit | Pyiong | Manasai | 266596 | Mathingkung | 8 | 95.953228 | 27.652543 | F30 | | NIL | |
| 740 | Arunachal Pradesh | Lohit | Sungura | Tezu | 266375 | Lapsing Camp | 306 | 95.943825 | 27.871385 | F30 | 518 | B | Lapsing
Camp |
| 741 | Arunachal Pradesh | Lohit | Sungura | Tezu | 266374 | Dangju | 213 | 95.94899 | 27.889465 | F32 | | NIL | |
| 742 | Arunachal Pradesh | Lohit | Wakro | Wakro | 266463 | Chikrolang | 116 | 96.309981 | 27.587594 | F33 | 153 | B | Chikrolang |
| 743 | Arunachal Pradesh | Lohit | Wakro | Wakro | 266458 | Tapun | 37 | 96.334948 | 27.601369 | F31 | | NIL | |
| 744 | Arunachal Pradesh | Lohit | Wakro | Wakro | 266452 | Tahar | 59 | 96.357333 | 27.634085 | F35 | 200 | B | Tahar |




RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deputy Secy. (T-1) USOF
 Deptt. of Telecom, Govt. of India
 11 Street, New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|---------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 745 | Arunachal Pradesh | Lehli | Wakro | Wakro | 266448 | Tumba | 18 | 96.319451 | 27.658192 | F35 | | NIL | |
| 746 | Arunachal Pradesh | Lehli | Wakro | Wakro | 266459 | Chiksepit | 163 | 96.348723 | 27.675811 | F35 | | NIL | |
| 747 | Arunachal Pradesh | Changlang | Miao | Khagam | 264285 | M'Pen II | 551 | 96.305275 | 27.530414 | F37 | 267 | B | M'Pen II |
| 748 | Arunachal Pradesh | Changlang | Miao | Khagam | 264296 | Brakop | 216 | 96.322746 | 27.52133 | F37 | | NIL | |
| 749 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266830 | Maliang | 81 | 96.560579 | 28.291264 | F40 | 360 | B | Maliang |
| 750 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266821 | Khalaga, Ndenogaang | 53 | 96.569206 | 28.2804 | F40 | | NIL | |
| 751 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266820 | Khalaga | 26 | 96.571769 | 28.290325 | F40 | | NIL | |
| 752 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266823 | Tabliao | 23 | 96.580683 | 28.300554 | F41 | 44 | B | Tabliao |
| 753 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266822 | Kalamoi | 21 | 96.577178 | 28.294492 | F41 | | NIL | |
| 754 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266828 | Taffagam | 148 | 96.63855 | 28.35061 | F50 | 248 | B | Taffagam |
| 755 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266827 | Tarampa | 47 | 96.51279 | 28.334528 | F50 | | NIL | |
| 756 | Arunachal Pradesh | Anjaw | Chaglagam | Chaglagam | 266829 | Upper Taffagam | 53 | 96.500123 | 28.362528 | F50 | | NIL | |
| 757 | Arunachal Pradesh | Anjaw | Hayuliang | Hayuliang | 266702 | Maha | 12 | 96.518038 | 28.027972 | F55 | 15 | B | Maha |
| 758 | Arunachal Pradesh | Anjaw | Hayuliang | Hayuliang | 266705 | Mullim | 3 | 96.485733 | 28.024411 | F55 | | NIL | |
| 759 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266945 | Bhaw | 27 | 96.945166 | 27.876311 | F56 | 79 | B | Bhaw |
| 760 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266960 | 9th K.M. Camp | 2 | 96.928544 | 27.906127 | F56 | | NIL | |
| 761 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266841 | Flu Lang | 65 | 96.871039 | 27.87614 | F57 | 71 | B | Flu Lang |
| 762 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266940 | Pratija | 6 | 96.882391 | 27.877601 | F57 | | NIL | |
| 763 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266948 | Mongkhong | 32 | 96.851967 | 27.911436 | F58 | 52 | B | Mongkhong |
| 764 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266966 | Pratija L/Camp | 20 | 96.853086 | 27.882347 | F58 | | NIL | |
| 765 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266965 | Chenginty | 16 | 96.856708 | 27.886161 | F58 | 11 | B | Chenginty |
| 766 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266938 | Lamkung | 15 | 96.858218 | 27.881839 | F58 | | NIL | |
| 767 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266936 | Halaikong | 148 | 96.835127 | 27.866647 | F59 | 186 | B | Halaikong |
| 768 | Arunachal Pradesh | Anjaw | Hawai | Walong | 266939 | Praklung | 38 | 96.841836 | 27.854902 | F59 | | NIL | |
| 769 | Arunachal Pradesh | Changlang | Tiknuk Rima Putok | Nampong | 264223 | Kenyam | 78 | 96.14927 | 27.287347 | F60 | 150 | B | Kenyam |
| 770 | Arunachal Pradesh | Changlang | Tiknuk Rima Putok | Nampong | 264218 | Lungang | 71 | 96.143965 | 27.257911 | F60 | | NIL | |
| 771 | Arunachal Pradesh | Changlang | Tiknuk Rima Putok | Nampong | 264211 | New Putok | 93 | 96.109434 | 27.248874 | F61 | 116 | B | New Putok |
| 772 | Arunachal Pradesh | Changlang | Tiknuk Rima Putok | Nampong | 264212 | Tiknuk Putak | 23 | 96.120317 | 27.266329 | F61 | | NIL | |
| 773 | Arunachal Pradesh | Changlang | Lyngok-Longtoi | Manmab | 264181 | Phinbro - I | 272 | 95.821322 | 27.270839 | F63 | 377 | B | Phinbro - I |
| 774 | Arunachal Pradesh | Changlang | Lyngok-Longtoi | Manmab | 264182 | Phinbro - II | 105 | 95.822036 | 27.274514 | F63 | | NIL | |
| 775 | Arunachal Pradesh | Changlang | Renuk | Manmab | 264175 | Hetman | 116 | 95.982725 | 27.130578 | F64 | 227 | B | Hetman |
| 776 | Arunachal Pradesh | Changlang | Changlang | Changlang | 264107 | Hadap | 111 | 95.980993 | 27.16083 | F64 | | NIL | |




RAMESHWAR DHARIWAL
 Director (E-I) & Gen. Mgt. Off.
 Director (T-I) USOF
 Government of India, New Delhi
 Deptt. of Telecom, Govt. of India
 (New Delhi)

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop. | Site Type | Tower Location |
|---------|----------------|---------------|-------------------|---------------|--------------|-----------------------------|-----------------------------|-----------|-----------|-------------|----------------|-----------|----------------|
| 808 | Andhra Pradesh | Changlang | Vijayanagar | Khagam | 264241 | Gehrigaon | 57 | 97.009008 | 27.208822 | 610 | | NIL | |
| 809 | Andhra Pradesh | Changlang | Vijayanagar | Khagam | 264248 | Topfali | 242 | 96.978167 | 27.219486 | 611 | 863 | B | Topfali |
| 810 | Andhra Pradesh | Changlang | Vijayanagar | Khagam | 264246 | Mazgaon | 239 | 96.966548 | 27.224948 | 611 | | NIL | |
| 811 | Andhra Pradesh | Changlang | Vijayanagar | Khagam | 264242 | Harelo | 182 | 96.97145 | 27.227464 | 611 | | NIL | |
| 812 | Andhra Pradesh | Anjaw | Kibithoo | Walong | 266876 | Kibithoo H.O. | 723 | 97.004586 | 28.281136 | 613 | 788 | B | Kibithoo H.O. |
| 813 | Andhra Pradesh | Anjaw | Kibithoo | Walong | 266868 | Kahu | 65 | 97.024978 | 28.303597 | 613 | | NIL | |
| 814 | Andhra Pradesh | Anjaw | Kibithoo | Walong | 266875 | Yakung | 64 | 97.050472 | 28.238576 | 614 | 59 | B | Yakung |
| 815 | Andhra Pradesh | Anjaw | Kibithoo | Walong | 266874 | Krowti Labour Camp | 29 | 97.045113 | 28.22213 | 614 | | NIL | |
| 816 | Andhra Pradesh | Anjaw | Kibithoo | Walong | 266873 | Krowti | 27 | 97.022961 | 28.227697 | 615 | 31 | B | Anjwoti |
| 817 | Andhra Pradesh | Anjaw | Walong | Walong | 266894 | Gorempani L/Camp | 4 | 97.025347 | 28.170656 | 615 | | NIL | |
| 818 | Andhra Pradesh | Anjaw | Kibithoo | Walong | 266871 | Kundin | 24 | 96.998306 | 28.236303 | 6150 | 28 | B | Kundin |
| 819 | Andhra Pradesh | Anjaw | Kibithoo | Walong | 266879 | Hot Spring | 4 | 97.013267 | 28.20556 | 6150 | | NIL | |
| 820 | Andhra Pradesh | Anjaw | Hawai | Walong | 266910 | Tamalu | 172 | 96.786748 | 27.963749 | 618 | 276 | B | Tamalu |
| 821 | Andhra Pradesh | Anjaw | Hawai | Walong | 266954 | Khering Camp | 107 | 96.793053 | 27.949431 | 618 | | NIL | |
| 822 | Andhra Pradesh | Anjaw | Hawai | Walong | 266921 | Bhong | 112 | 96.77483 | 27.941183 | 618 | 175 | B | Bhong |
| 823 | Andhra Pradesh | Anjaw | Hawai | Walong | 266914 | Kanjar | 63 | 96.772358 | 27.94167 | 618 | | NIL | |
| 824 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266769 | Kharibiglat | 161 | 96.684814 | 27.960714 | 620 | 299 | B | Kharibiglat |
| 825 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266777 | Manjilang | 138 | 96.695367 | 27.977683 | 620 | | NIL | |
| 826 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266766 | Phanglonglat | 138 | 96.669511 | 27.978603 | 622 | 166 | B | Phanglonglat |
| 827 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266765 | Geliang II | 17 | 96.641197 | 27.955136 | 622 | | NIL | |
| 828 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266786 | Kanthurang(1h KM GREP Camp) | 11 | 96.65587 | 27.983621 | 622 | | NIL | |
| 829 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266762 | Manchal | 108 | 96.652442 | 27.997533 | 623 | 112 | B | Manchal |
| 830 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266763 | Geliang | 4 | 96.647896 | 28.019131 | 623 | | NIL | |
| 831 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266772 | Yitong - II | 31 | 96.65669 | 28.054338 | 624 | 54 | B | Yitong - II |
| 832 | Andhra Pradesh | Anjaw | Manchal | Manchal | 266733 | Misatong | 23 | 96.632333 | 28.053058 | 624 | | NIL | |
| 833 | Andhra Pradesh | Anjaw | Hayalang | Hayalang | 266723 | Supurung | 171 | 96.616485 | 28.052548 | 625 | 215 | B | Supurung |
| 834 | Andhra Pradesh | Anjaw | Hayalang | Hayalang | 266722 | Khandang | 16 | 96.601005 | 28.046954 | 625 | | NIL | |
| 835 | Andhra Pradesh | Anjaw | Hayalang | Hayalang | 266696 | Khyolung/Sagnola | 27 | 96.610365 | 28.090385 | 625 | | NIL | |
| 836 | Andhra Pradesh | Anjaw | Hayalang | Hayalang | 266661 | Tumula | 49 | 96.587677 | 28.04966 | 626 | 57 | B | Tumula |
| 837 | Andhra Pradesh | Anjaw | Hayalang | Hayalang | 266724 | Malama | 48 | 96.592269 | 28.058403 | 626 | | NIL | |
| 838 | Andhra Pradesh | Anjaw | Goliang | Hayalang | 266819 | Goliang H.O. | 140 | 96.643097 | 28.144833 | 627 | 265 | B | Goliang H.O. |
| 839 | Andhra Pradesh | Anjaw | Goliang | Hayalang | 266798 | Kasngal | 125 | 96.638725 | 28.1253 | 627 | | NIL | |
| 840 | Andhra Pradesh | Anjaw | Hayalang | Hayalang | 266675 | Adonla | 48 | 96.546802 | 28.103274 | 628 | 117 | B | Adonla |
| 841 | Andhra Pradesh | Anjaw | Hayalang | Hayalang | 266686 | Theromla | 23 | 96.55109 | 28.109173 | 628 | | NIL | |



| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|----------------|---------------|-------------------|----------------|--------------|---------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|---------------------|
| 842 | Andhra Pradesh | Anjaw | Hayaliang | Hayaliang | 26687 | Chamerna | 46 | 95.58098 | 28.105716 | G28 | | Nil | |
| 843 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266856 | Tassipurna | 45 | 95.5363 | 28.118654 | G29 | 60 | B | Tassipurana |
| 844 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266857 | Ka angro | 15 | 95.53794 | 28.113062 | G29 | | Nil | |
| 845 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266858 | Total | 36 | 95.529667 | 28.118258 | G30 | 30 | B | Total |
| 846 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266859 | Hamsingko | 3 | 95.519347 | 28.117703 | G30 | | Nil | |
| 847 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266860 | Hamsake | 38 | 95.511703 | 28.128528 | G31 | 48 | B | Hamsake |
| 848 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266861 | Taraliang | 11 | 95.515548 | 28.132061 | G31 | | Nil | |
| 849 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266862 | Chiru | 147 | 95.537485 | 28.149952 | G32 | 170 | B | Chiru |
| 850 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266864 | Hawaka | 28 | 95.530556 | 28.150028 | G32 | | Nil | |
| 851 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266839 | Bonna | 93 | 95.494504 | 28.151896 | G33 | 151 | B | Bonna |
| 852 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266845 | Taberong | 58 | 95.496786 | 28.149457 | G33 | | Nil | |
| 853 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266847 | Payaparap | 30 | 95.501485 | 28.158166 | G34 | 48 | B | Payaparap |
| 854 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266852 | Rikangi | 18 | 95.488608 | 28.165389 | G34 | | Nil | |
| 855 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266850 | Ganna | 60 | 95.510903 | 28.1689 | G35 | 115 | B | Ganna |
| 856 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266854 | Payagam | 55 | 95.509807 | 28.173229 | G35 | | Nil | |
| 857 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266844 | Paliang | 72 | 95.49765 | 28.189614 | G37 | 167 | B | Paliang |
| 858 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266845 | Doringko | 38 | 95.484306 | 28.189824 | G37 | | Nil | |
| 859 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266841 | Chipuliang | 57 | 95.500121 | 28.20846 | G37 | | Nil | |
| 860 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266840 | Kronna | 139 | 95.514878 | 28.224031 | G38 | 226 | B | Kronna |
| 861 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266843 | Khowegla | 31 | 95.487747 | 28.224892 | G38 | | Nil | |
| 862 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266842 | Tanna | 56 | 95.516937 | 28.211059 | G38 | | Nil | |
| 863 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266866 | Mithamma | 102 | 95.534967 | 28.253839 | G39 | 194 | B | Mithamma |
| 864 | Andhra Pradesh | Anjaw | Chagalam | Chagalam | 266836 | Teganna | 77 | 95.542976 | 28.245201 | G39 | | Nil | |
| 865 | Andhra Pradesh | Anjaw | Metengi | Chagalam | 266867 | Mithungkup | 15 | 95.544686 | 28.236097 | G39 | | Nil | |
| 866 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266017 | Cheppe | 40 | 95.467503 | 28.608133 | G40 | 59 | B | Cheppe |
| 867 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266016 | Jingjo | 19 | 95.510748 | 28.582402 | G40 | | Nil | |
| 868 | Andhra Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265970 | Endalin | 17 | 95.705056 | 28.618464 | G41 | 20 | B | Endalin |
| 869 | Andhra Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265968 | Akuli | 8 | 95.6285 | 28.637722 | G41 | | Nil | |
| 870 | Andhra Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 269000 | New Echarli | 58 | 95.872894 | 28.626747 | G42 | 78 | B | New Echarli |
| 871 | Andhra Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265972 | Eranli | 11 | 95.785461 | 28.602158 | G42 | | Nil | |
| 872 | Andhra Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265982 | New Arope | 9 | 95.859972 | 28.634633 | G42 | | Nil | |
| 873 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266013 | Yese Mojjet village | 27 | 95.681586 | 28.518707 | G44 | 33 | B | Yese Mojjet village |
| 874 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266010 | Achne | 6 | 95.654075 | 28.562489 | G44 | | Nil | |
| 875 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266012 | Engolin | 21 | 95.637664 | 28.517918 | G440 | 35 | B | Engolin |
| 876 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266011 | Asu | 14 | 95.609467 | 28.564394 | G440 | | Nil | |
| 877 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266007 | Akuli | 25 | 95.743064 | 28.532614 | G45 | 30 | B | Akuli |
| 878 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266018 | Girili | 1 | 95.743174 | 28.480353 | G45 | | Nil | |
| 879 | Andhra Pradesh | Dibang Valley | Anelli | Anelli-Aru | 266006 | Isu | 13 | 95.755417 | 28.530158 | G45 | | Nil | |




रमेश्वर धारिवाल
RAMESHWAR DHARIVAL
 Director (G-1) BHEL Ltd.
 Director (T-1) USOF
 Government of India
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub-District Name | CD-Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|---------------------|----------------|--------------|------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|------------------|
| 880 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265998 | New Arope(Hipau) | 55 | 95.944456 | 28.600699 | 647 | 117 | B | New Arope(Hipau) |
| 881 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265983 | Punih | 32 | 95.962042 | 28.594542 | 647 | | NIL | |
| 882 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265986 | Chupull | 29 | 95.966079 | 28.605177 | 647 | | NIL | |
| 883 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265990 | Edilin | 4 | 95.991955 | 28.627704 | 648 | 6 | B | Edilith |
| 884 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265991 | Masuali | 2 | 96.012321 | 28.620654 | 648 | | NIL | |
| 885 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265996 | Malinye | 127 | 96.141653 | 28.631737 | 649 | 139 | B | Malinye |
| 886 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265993 | Sinili | 10 | 96.082337 | 28.617479 | 649 | | NIL | |
| 887 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin-Malinye | 265994 | Gunil | 2 | 96.099328 | 28.600773 | 649 | | NIL | |
| 888 | Arunachal Pradesh | Upper Siang | Palling | Tutling | 263955 | Singing | 117 | 94.808894 | 28.878788 | 653 | 163 | B | Singing |
| 889 | Arunachal Pradesh | Upper Siang | Palling | Tutling | 263954 | Monging | 44 | 94.847063 | 28.881802 | 653 | | NIL | |
| 890 | Arunachal Pradesh | Upper Siang | Mingling | Tutling | 263948 | Moxing | 188 | 94.760161 | 28.774478 | 655 | 254 | B | Moxing |
| 891 | Arunachal Pradesh | Upper Siang | Mingling | Tutling | 263949 | Moxo | 66 | 94.750165 | 28.775941 | 655 | | NIL | |
| 892 | Arunachal Pradesh | East Siang | Rebo-Perjing | Pangin | 263813 | Jorsing | 178 | 95.046899 | 28.259101 | 657 | 224 | B | Jorsing |
| 893 | Arunachal Pradesh | East Siang | Rebo-Perjing | Pangin | 263819 | Rebo-Perjing | 46 | 95.007489 | 28.283903 | 657 | | NIL | |
| 894 | Arunachal Pradesh | East Siang | Koyu | Ramie-Bango | 263826 | Raxa | 199 | 94.920311 | 27.975018 | 659 | 224 | B | Raxa |
| 895 | Arunachal Pradesh | East Siang | Koyu | Ramie-Bango | 263827 | Sood(Hipo) | 75 | 94.954496 | 27.981603 | 659 | | NIL | |
| 896 | Arunachal Pradesh | Lower Dibang Valley | Dambuk | Dambuk | 266305 | Gandhi(Lusum) | 337 | 95.590049 | 28.139123 | 661 | 713 | B | Gandhi(Lusum) |
| 897 | Arunachal Pradesh | Lower Dibang Valley | Dambuk | Dambuk | 266309 | Gumyong | 302 | 95.591771 | 28.129652 | 661 | | NIL | |
| 898 | Arunachal Pradesh | Lower Dibang Valley | Dambuk | Dambuk | 266304 | Kyara-Ah(Chimo) | 74 | 95.596937 | 28.115877 | 661 | | NIL | |
| 899 | Arunachal Pradesh | Lower Dibang Valley | Dambuk | Dambuk | 266301 | Agam | 144 | 95.652899 | 28.237401 | 663 | 269 | B | Agam |
| 900 | Arunachal Pradesh | Lower Dibang Valley | Dambuk | Dambuk | 266307 | Ehli Brwa | 125 | 95.662360 | 28.161508 | 663 | | NIL | |
| 901 | Arunachal Pradesh | Dibang Valley | Krone(Arzo0 circle) | Anelli-Arzu | 266047 | Awali | 21 | 95.919075 | 28.424987 | 665 | 34 | B | Awali |
| 902 | Arunachal Pradesh | Dibang Valley | Krone(Arzo0 circle) | Anelli-Arzu | 266046 | Raril | 11 | 95.897904 | 28.455806 | 665 | | NIL | |
| 903 | Arunachal Pradesh | Dibang Valley | Krone(Arzo0 circle) | Anelli-Arzu | 266043 | New Anaya | 142 | 95.880615 | 28.432165 | 666 | 160 | B | New Anaya |
| 904 | Arunachal Pradesh | Dibang Valley | Krone(Arzo0 circle) | Anelli-Arzu | 266034 | Gumdo | 18 | 95.859443 | 28.449807 | 666 | | NIL | |
| 905 | Arunachal Pradesh | Dibang Valley | Krone(Arzo0 circle) | Anelli-Arzu | 266036 | Ichendo | 123 | 95.863678 | 28.420873 | 667 | 152 | B | Ichendo |
| 906 | Arunachal Pradesh | Dibang Valley | Krone(Arzo0 circle) | Anelli-Arzu | 266042 | Mrambe | 15 | 95.817454 | 28.394762 | 667 | | NIL | |




 भारतीय संचार विभाग
RAMESHWAR DHARIWAL
 Director (CI-1) JUSOF
 Director General, JUSOF
 Dept. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub-District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop. | Site Type | Tower Location |
|---------|--------------------|---------------------|-----------------------|---------------|--------------|-------------------------|-----------------------------|-----------|-----------|-------------|----------------|-----------|--------------------|
| 907 | Assamachal Pradesh | Dibang Valley | Kronli (Arzoo circle) | Aneilh-Arzu | 266023 | Amlil | 14 | 95.853386 | 28.40376 | 667 | | NIL | |
| 908 | Assamachal Pradesh | Dibang Valley | Kronli (Arzoo circle) | Aneilh-Arzu | 266039 | Kano | 24 | 95.90108 | 28.406053 | 668 | 50 | B | Kano |
| 909 | Assamachal Pradesh | Dibang Valley | Kronli (Arzoo circle) | Aneilh-Arzu | 266045 | 132 K.M. Point | 23 | 95.897199 | 28.401114 | 668 | | NIL | |
| 910 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266060 | Ebnali | 3 | 95.901681 | 28.404153 | 668 | | NIL | |
| 911 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266080 | New Elope | 191 | 95.872758 | 28.388911 | 669 | 204 | B | New Elope |
| 912 | Assamachal Pradesh | Dibang Valley | Kronli (Arzoo circle) | Aneilh-Arzu | 266033 | Ethore | 13 | 95.868285 | 28.381091 | 669 | | NIL | |
| 913 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266052 | Yuma (7 KM) | 21 | 95.893318 | 28.37577 | 670 | 25 | B | Yuma (7 KM) |
| 914 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266055 | Banglo | 4 | 95.89225 | 28.377547 | 670 | | NIL | |
| 915 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266050 | Abrango | 24 | 95.891953 | 28.352528 | 671 | 35 | B | Abrango |
| 916 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266081 | Akango | 5 | 95.870933 | 28.361994 | 671 | | NIL | |
| 917 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266082 | Treni | 7 | 95.893318 | 28.355968 | 671 | | NIL | |
| 918 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266067 | Eynali | 19 | 95.955169 | 28.346785 | 672 | 23 | B | Eynali |
| 919 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266069 | Esoli | 4 | 95.963568 | 28.348099 | 672 | | NIL | |
| 920 | Assamachal Pradesh | Lower Dibang Valley | Desali | Hunli-Desali | 266123 | Jambupani | 54 | 95.964158 | 28.331517 | 673 | 86 | B | Jambupani |
| 921 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266088 | Wini (13 K.M. Point) | 4 | 95.947558 | 28.332722 | 673 | | NIL | |
| 922 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266053 | Atrigo | 28 | 95.959611 | 28.320669 | 673 | | NIL | |
| 923 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266068 | Indiri (New Yanti) | 68 | 95.992328 | 28.317225 | 674 | 114 | B | Indiri (New Yanti) |
| 924 | Assamachal Pradesh | Lower Dibang Valley | Hunli | Hunli-Desali | 266078 | Hhanglo (17 K.M. Point) | 36 | 95.982857 | 28.306894 | 674 | | NIL | |
| 925 | Assamachal Pradesh | Lower Dibang Valley | Desali | Hunli-Desali | 266118 | Pi-Kha | 10 | 95.992767 | 28.312336 | 674 | | NIL | |
| 926 | Assamachal Pradesh | Lower Dibang Valley | Desali | Hunli-Desali | 266090 | Chanli | 45 | 96.004111 | 28.305489 | 675 | 73 | B | Chanli |



বিশ্বাস সীমিত
RAMESHWAR DHARWAL
 (সি-1) গ.সে.অ.সে.
 Director (C-1) USOF
 অর্থায়ন বিভাগ, সশস্ত্র বাহিনী
 Deptt. of Telecom, Govt. of India
 (সি-1) গ.সে.অ.সে./New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-------------------|---------------|--------------|---------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|---------------------|
| 927 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266091 | New Charli | 13 | 95.004111 | 28.309489 | 675 | | NIL | |
| 928 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266131 | Cheroni | 15 | 95.007964 | 28.322011 | 675 | | NIL | |
| 929 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266100 | Dumilina (Chipigul) | 41 | 95.036344 | 28.324005 | 676 | 70 | 8 | Dumilina (Chipigul) |
| 930 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266135 | Maringo | 14 | 95.020036 | 28.322403 | 676 | | NIL | |
| 931 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266132 | Marioo | 15 | 95.023739 | 28.313614 | 676 | | NIL | |
| 932 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266136 | Desali H.O. | 87 | 95.013069 | 28.292153 | 677 | 113 | 8 | Desali H.O. |
| 933 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266129 | Pka | 11 | 95.016035 | 28.29742 | 677 | | NIL | |
| 934 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266127 | New Chertam | 15 | 95.018264 | 28.299468 | 677 | | NIL | |
| 935 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266106 | Taloni | 59 | 95.148952 | 28.274931 | 678 | 78 | 8 | Taloni |
| 936 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266120 | Necha | 19 | 95.148952 | 28.303342 | 678 | | NIL | |
| 937 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266105 | Chumouku | 17 | 95.126098 | 28.272904 | 679 | 29 | 8 | Chumouku |
| 938 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266102 | Almango | 12 | 95.13643 | 28.265245 | 678 | | NIL | |
| 939 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266137 | Chuloni | 41 | 95.075987 | 28.293011 | 679 | 68 | 8 | Chuloni |
| 940 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266112 | Dopowa | 27 | 95.070558 | 28.297372 | 679 | | NIL | |
| 941 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266118 | Mitaka | 37 | 95.050964 | 28.314083 | 680 | 63 | 8 | Mitaka |
| 942 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266096 | Rungo | 26 | 95.047822 | 28.30495 | 680 | | NIL | |
| 943 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266099 | Duchuli | 30 | 95.062508 | 28.30605 | 680 | 48 | 8 | Duchuli |
| 944 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266093 | Sulungo | 18 | 95.052487 | 28.309154 | 680 | | NIL | |
| 945 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266092 | Akanda | 27 | 95.029887 | 28.294616 | 681 | 35 | 8 | Akanda |
| 946 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunti-Desali | 266128 | Theypra | 8 | 95.038281 | 28.294948 | 681 | | NIL | |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-3) USOF
 Director (T-3) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub-District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-------------------|---------------|--------------|--------------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|-----------------------|
| 947 | Arunachal Pradesh | Lower Dibang Valley | Humli | Humli-Desali | 266074 | Boongo (65 K.M.) | 85 | 95.94938 | 28.229408 | G82 | 117 | B | Boongo (65 K.M.) |
| 948 | Arunachal Pradesh | Lower Dibang Valley | Humli | Humli-Desali | 266072 | Chelaha (82 K.M.) | 19 | 95.961333 | 28.259541 | G82 | | NIL | |
| 949 | Arunachal Pradesh | Lower Dibang Valley | Humli | Humli-Desali | 266073 | Androhi (73 K.M.) | 13 | 95.96716 | 28.247488 | G82 | | NIL | |
| 950 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266258 | Meyopa | 42 | 95.909083 | 28.232781 | G83 | 48 | B | Meyopa |
| 951 | Arunachal Pradesh | Lower Dibang Valley | Humli | Humli-Desali | 266075 | Cherpaia (52 K.M. Point) | 6 | 95.891596 | 28.206162 | G83 | | NIL | |
| 952 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266242 | Gimbo (78 K.M. Point) | 61 | 95.851105 | 28.188294 | G84 | 103 | B | Gimbo (78 K.M. Point) |
| 953 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266279 | Mudiali | 42 | 95.852277 | 28.182153 | G84 | | NIL | |
| 954 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266256 | Ichi-Ano village | 52 | 95.883514 | 28.160316 | G85 | 107 | B | Ichi-Ano village |
| 955 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266255 | Khatru | 25 | 95.870075 | 28.155639 | G85 | | NIL | |
| 956 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266257 | Kesha | 30 | 95.896953 | 28.158544 | G85 | | NIL | |
| 957 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266260 | Nage | 36 | 95.822857 | 28.177431 | G86 | 43 | B | Nage |
| 958 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266261 | 5 K.M. Point | 7 | 95.823589 | 28.173103 | G86 | | NIL | |
| 959 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266247 | Lokhauw | 191 | 95.914024 | 27.980569 | G91 | 318 | B | Lokhauw |
| 960 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266249 | Ajwaya | 127 | 95.901311 | 27.970036 | G91 | | NIL | |
| 961 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266253 | Asenga | 226 | 95.944897 | 28.0089 | G92 | 360 | B | Asenga |
| 962 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266252 | Chupuro | 134 | 95.941628 | 28.000183 | G92 | | NIL | |
| 963 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266250 | Mimi village | 67 | 95.937269 | 27.990013 | G93 | 116 | B | Mimi Village |
| 964 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266251 | Asame | 49 | 95.938722 | 27.995088 | G93 | | NIL | |
| 965 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266231 | Sanggo | 151 | 95.848282 | 28.01798 | G94 | 280 | B | Sanggo |
| 966 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong-Koromu | 266230 | Dolung | 129 | 95.847556 | 28.012805 | G94 | | NIL | |




राजेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (IT-1) USOP
 Director (Bumt, upper network)
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG. | LAT. | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-----------------------------|---------------|--------------|----------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 957 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koronu | 266295 | Bogong | 103 | 95.890474 | 28.06288 | G56 | 198 | B | Bogong |
| 958 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koronu | 266294 | Lyni Gife | 95 | 95.894192 | 28.066711 | G56 | | NIL | |
| 959 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koronu | 266165 | Balek-II | 95 | 95.87427 | 28.080379 | G57 | 132 | B | Balek-II |
| 970 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koronu | 266167 | Balingo | 37 | 95.872978 | 28.071339 | G57 | | NIL | |
| 971 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koronu | 266166 | Mela Kaku | 40 | 95.881372 | 28.087482 | G58 | 47 | B | Mela Kaku |
| 972 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koronu | 266168 | Lupong | 7 | 95.886538 | 28.079734 | G58 | | NIL | |
| 973 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Pipicrang) | Pipicrang | 265839 | Harmachu | 134 | 93.628442 | 28.171994 | G59 | 201 | B | Harmachu |
| 974 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Pipicrang) | Pipicrang | 265836 | Necum | 57 | 93.63485 | 28.146486 | G59 | | NIL | |
| 975 | Arunachal Pradesh | Upper Subansiri | Daporijo | Daporijo | 263137 | Pisa-II | 93 | 94.175115 | 28.019616 | G63 | 224 | B | Pisa-II |
| 976 | Arunachal Pradesh | Upper Subansiri | Daporijo | Daporijo | 263130 | Date-Rejo | 73 | 94.162857 | 28.036776 | G63 | | NIL | |
| 977 | Arunachal Pradesh | Upper Subansiri | Daporijo | Daporijo | 263143 | Pakdim | 58 | 94.175933 | 28.016347 | G63 | | NIL | |
| 978 | Arunachal Pradesh | Lower Subansiri | Pizaba | Ziro-I | 264975 | Dem-II | 226 | 93.667992 | 27.589414 | G68 | 359 | B | Dem-II |
| 979 | Arunachal Pradesh | Lower Subansiri | Pizaba | Ziro-II | 264978 | Seva | 133 | 93.696578 | 27.591756 | G68 | | NIL | |
| 980 | Arunachal Pradesh | West Siang | Tirbin | Tirbin | 262634 | Essi Begar | 82 | 94.516448 | 28.021521 | G69 | 244 | B | Essi Begar |
| 981 | Arunachal Pradesh | West Siang | Tirbin | Tirbin | 262635 | Essi Yordo | 62 | 94.518234 | 28.026682 | G69 | | NIL | |
| 982 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Pipicrang) | Pipicrang | 265833 | Samba Karsang | 228 | 93.650025 | 28.091747 | H10 | 316 | B | Samba Karsang |
| 983 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Pipicrang) | Pipicrang | 265835 | Raba Karsang | 88 | 93.635942 | 28.101092 | H10 | | NIL | |
| 984 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Pipicrang) | Pipicrang | 265850 | Pilua | 267 | 93.779264 | 28.121814 | H12 | 443 | B | Pilua |
| 985 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Pipicrang) | Pipicrang | 265848 | Tamv | 176 | 93.799689 | 28.115558 | H12 | | NIL | |
| 986 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Pipicrang) | Pipicrang | 265847 | Halna | 170 | 93.764717 | 28.053036 | H13 | 302 | B | Halna |
| 987 | Arunachal Pradesh | Kurung Kumey | Longding Koling (Pipicrang) | Pipicrang | 265842 | Baggam (Bajam) | 152 | 93.742242 | 28.056344 | H13 | | NIL | |




रमेश्वर धरमवाल
RAMESHWAR DHARWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|---------------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|---------------------|
| 988 | Arunachal Pradesh | West Siang | Tirbin | Tirbin | 263633 | Esst Riche | 74 | 94.520372 | 28.023506 | HHH1 | 136 | B | Esst Riche |
| 989 | Arunachal Pradesh | West Siang | Tirbin | Tirbin | 263637 | Esst Lite | 62 | 94.539074 | 28.023109 | HHH1 | | NIL | |
| 990 | Arunachal Pradesh | West Siang | Yomcha | Yomcha | 263566 | Tabor Gadl | 90 | 94.591517 | 28.054873 | HHH4 | 135 | B | Tabor Gadl |
| 991 | Arunachal Pradesh | West Siang | Yomcha | Yomcha | 263565 | Bopa Gadl | 45 | 94.588295 | 28.059339 | HHH4 | | NIL | |
| 992 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262667 | Bee | 119 | 93.306417 | 27.244593 | J10 | 206 | B | Bee |
| 993 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262669 | Rachi | 57 | 93.308286 | 27.233475 | J10 | | NIL | |
| 994 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262668 | Dhiso | 30 | 93.323779 | 27.237607 | J10 | | NIL | |
| 995 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262671 | Yarezo | 141 | 93.315029 | 27.258955 | J11 | 158 | B | Yarezo |
| 996 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262672 | Talheso | 17 | 93.306791 | 27.264314 | J11 | | NIL | |
| 997 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262681 | Sharik | 68 | 93.356574 | 27.250191 | J12 | 149 | B | Sharik |
| 998 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262683 | Alw Tuda | 52 | 93.352351 | 27.245842 | J12 | | NIL | |
| 999 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262682 | Pare Hapa | 29 | 93.368221 | 27.25655 | J12 | | NIL | |
| 1000 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262677 | Budhoo | 597 | 93.344981 | 27.273808 | J13 | 260 | B | Budhoo |
| 1001 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262675 | Bikur | 63 | 93.337982 | 27.275497 | J13 | | NIL | |
| 1002 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262663 | Leporlang H.O. | 186 | 93.330042 | 27.279125 | J14 | 269 | B | Leporlang H.O. |
| 1003 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262665 | Hellepald | 79 | 93.354483 | 27.292751 | J14 | | NIL | |
| 1004 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262665 | Upper Karori - I | 135 | 93.491257 | 27.206498 | J15 | 243 | B | Upper Karori - I |
| 1005 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262666 | Lower Karori - II | 108 | 93.49444 | 27.203227 | J15 | | NIL | |
| 1006 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262617 | Langchung - I | 94 | 93.425669 | 27.232922 | J16 | 162 | B | Langchung - I |
| 1007 | Arunachal Pradesh | Papum Pare | Leporlang | Sagalee | 262646 | Dolo-Hobe | 68 | 93.413022 | 27.225139 | J16 | | NIL | |
| 1008 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262608 | Kulubu | 91 | 93.447045 | 27.228867 | J17 | 143 | B | Kulubu |
| 1009 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262616 | Langchung - I | 52 | 93.435212 | 27.237121 | J17 | | NIL | |
| 1010 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262569 | Cherso | 49 | 93.460333 | 27.22725 | J19 | 91 | B | Cherso |
| 1011 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262568 | Bumbum | 42 | 93.454545 | 27.218565 | J19 | | NIL | |
| 1012 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262600 | Apop-Sango | 117 | 93.526736 | 27.497828 | J20 | 178 | B | Apop-Sango |
| 1013 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262599 | Apop - II | 61 | 93.533608 | 27.277574 | J20 | | NIL | |
| 1014 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262418 | Ranghat Forest Camp | 103 | 93.431086 | 26.965417 | J21 | 188 | B | Ranghat Forest Camp |
| 1015 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262476 | Yechum | 85 | 93.437741 | 26.957284 | J21 | | NIL | |
| 1016 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262419 | Dullang | 30 | 93.467866 | 27.000524 | J26 | 50 | B | Dullang |
| 1017 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262420 | Dur Rabig | 20 | 93.466217 | 27.015377 | J26 | | NIL | |
| 1018 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262431 | Lower Taraso | 334 | 93.409914 | 26.984792 | J27 | 599 | B | Lower Taraso |
| 1019 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262424 | Bormal | 126 | 93.383341 | 26.977495 | J27 | | NIL | |
| 1020 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262423 | Bormal Niah | 139 | 93.397794 | 26.992675 | J27 | | NIL | |
| 1021 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262414 | Jullang | 70 | 93.380665 | 26.985365 | J28 | 131 | B | Jullang |
| 1022 | Arunachal Pradesh | Papum Pare | Taraso | Buljian | 262415 | Pote | 61 | 93.381564 | 26.995538 | J28 | | NIL | |



| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONGS | LAT | Cluster No. | Effective Pop. | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|----------------------|-----------------------------|-----------|-----------|-------------|----------------|-----------|----------------|
| 1023 | Arunachal Pradesh | Papum Pare | Taraso | Balijan | 262417 | Diderso | 37 | 93.43394 | 27.008655 | 130 | 70 | B | Diderso |
| 1024 | Arunachal Pradesh | Papum Pare | Taraso | Balijan | 262430 | Lengso | 33 | 93.421016 | 27.007989 | 130 | | Nil | |
| 1025 | Arunachal Pradesh | Papum Pare | Taraso | Balijan | 262408 | Sengoi | 73 | 93.395049 | 27.008401 | 131 | 700 | B | Sengoi |
| 1026 | Arunachal Pradesh | Papum Pare | Taraso | Balijan | 262409 | Shingoso | 64 | 93.38536 | 27.013778 | 131 | | Nil | |
| 1027 | Arunachal Pradesh | Papum Pare | Taraso | Balijan | 262410 | Gera | 63 | 93.387946 | 27.021511 | 131 | | Nil | |
| 1028 | Arunachal Pradesh | Papum Pare | Taru | Sagalae | 262553 | Tashi | 91 | 93.648795 | 27.224471 | 139 | 211 | B | Tashi |
| 1029 | Arunachal Pradesh | Papum Pare | Taru | Sagalae | 262564 | Sangrak | 47 | 93.636323 | 27.239577 | 139 | | Nil | |
| 1030 | Arunachal Pradesh | Papum Pare | Taru | Sagalae | 262554 | Pach Hapa | 73 | 93.643659 | 27.229911 | 139 | | Nil | |
| 1031 | Arunachal Pradesh | Papum Pare | Sagalae | Sagalae | 262579 | Langler-II | 71 | 93.605429 | 27.232148 | 140 | 113 | B | Langler-II |
| 1032 | Arunachal Pradesh | Papum Pare | Sagalae | Sagalae | 262578 | Langler-I (Longpak) | 42 | 93.59465 | 27.236717 | 140 | | Nil | |
| 1033 | Arunachal Pradesh | Papum Pare | Sagalae | Sagalae | 262618 | Rigo | 82 | 93.575133 | 27.219719 | 142 | 147 | B | Rigo |
| 1034 | Arunachal Pradesh | Papum Pare | Sagalae | Sagalae | 262582 | Dabi | 65 | 93.572654 | 27.226747 | 142 | | Nil | |
| 1035 | Arunachal Pradesh | Papum Pare | Kakoi | Kimin | 262760 | Boginadi | 116 | 94.107381 | 27.448872 | 145 | 125 | B | Boginadi |
| 1036 | Arunachal Pradesh | Papum Pare | Kakoi | Kimin | 262759 | Boginadi Forest Beat | 9 | 94.107325 | 27.448869 | 145 | | Nil | |
| 1037 | Arunachal Pradesh | Papum Pare | Kimin | Kimin | 262742 | Nyoktuang | 31 | 93.932228 | 27.352591 | 146 | 33 | B | Nyoktuang |
| 1038 | Arunachal Pradesh | Papum Pare | Kimin | Kimin | 262745 | Bomchi-Bomte | 2 | 93.861174 | 27.361981 | 146 | | Nil | |
| 1039 | Arunachal Pradesh | Papum Pare | Mengoo | Mengoo | 262687 | Nikar (Nikarp) | 128 | 93.546253 | 27.393261 | 151 | 120 | B | Nikar (Nikarp) |
| 1040 | Arunachal Pradesh | Papum Pare | Mengoo | Mengoo | 262686 | Pilla-III | 151 | 93.549456 | 27.403658 | 151 | | Nil | |
| 1041 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265905 | Hapak | 167 | 93.722397 | 28.035833 | K10 | 293 | B | Hapak |
| 1042 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265882 | Sodak | 126 | 93.722133 | 28.00458 | K10 | | Nil | |
| 1043 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265871 | Hopki/Mogjang | 110 | 93.738022 | 27.999139 | K11 | 195 | B | Hopki/Mogjang |
| 1044 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265883 | Holpak | 85 | 93.736743 | 27.992537 | K11 | | Nil | |
| 1045 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265887 | Rong | 459 | 93.743544 | 27.968067 | K12 | 831 | B | Rong |
| 1046 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265866 | Loi | 372 | 93.735442 | 27.972425 | K12 | | Nil | |
| 1047 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265885 | Byar | 144 | 93.718383 | 27.960203 | K14 | 237 | R | Byar |
| 1048 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265886 | Chelo | 93 | 93.723484 | 27.965165 | K14 | | Nil | |
| 1049 | Arunachal Pradesh | Kurang Kumey | Tali | Tali | 265891 | Torda | 278 | 93.700051 | 27.94957 | K15 | 474 | B | Torda |



| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower location |
|---------|--------------------|---------------|-------------------|---------------|--------------|--------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|--------------------|
| 1050 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265893 | Pirayari | 196 | 93.693224 | 27.940243 | K15 | | NIL | |
| 1051 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265884 | Tagongruk | 264 | 93.71089 | 27.942731 | K16 | 399 | B | Tagongruk |
| 1052 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265895 | Jheme | 135 | 93.722053 | 27.943772 | K16 | | NIL | |
| 1053 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265894 | Lota | 265 | 93.7063 | 27.932915 | K17 | 407 | B | Lota |
| 1054 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265889 | Lengdi | 140 | 93.712447 | 27.927692 | K17 | | NIL | |
| 1055 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265890 | Kopin | 2 | 93.722594 | 27.919164 | K17 | | NIL | |
| 1056 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265532 | Sangching Nyingang | 84 | 93.715946 | 27.885447 | K18 | 205 | B | Sangching Nyingang |
| 1057 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265533 | Takeng | 42 | 93.724391 | 27.878047 | K18 | | NIL | |
| 1058 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265533 | Payel | 79 | 93.7325 | 27.884787 | K18 | | NIL | |
| 1059 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265888 | Lodokore | 501 | 93.752963 | 27.878186 | K19 | 645 | B | Lodokore |
| 1060 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265529 | Korayer-II | 64 | 93.74789 | 27.871234 | K19 | | NIL | |
| 1061 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265528 | Korayer-I | 80 | 93.75293 | 27.877198 | K19 | | NIL | |
| 1062 | Assamachal Pradesh | Kurung Kumey | Yangte | Sangram | 265272 | Malarang | 96 | 93.627372 | 27.760645 | K20 | 144 | B | Malarang |
| 1063 | Assamachal Pradesh | Kurung Kumey | Yangte | Sangram | 265273 | Nidley Happa | 48 | 93.644093 | 27.755051 | K20 | | NIL | |
| 1064 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265552 | Pirayari | 56 | 93.661186 | 27.7793 | K21 | 67 | B | Pirayari |
| 1065 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265554 | Riambang | 11 | 93.676156 | 27.794614 | K21 | | NIL | |
| 1066 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265507 | Pelap | 137 | 93.731186 | 27.743056 | K22 | 210 | B | Pelap |
| 1067 | Assamachal Pradesh | Kurung Kumey | Palin | Palin | 265219 | Yecia | 73 | 93.722915 | 27.738598 | K22 | | NIL | |
| 1068 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265511 | Sangto Putang | 79 | 93.690171 | 27.779305 | K25 | 145 | B | Sangto Putang |
| 1069 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265521 | Dugak | 72 | 93.701164 | 27.768806 | K25 | | NIL | |




RAMESHWAR DHARIMAL
 Director (T-1) USOF
 Director (T-1) USOF
 Deputy Telecom, Govt. of India
 1st Floor, New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|---------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 1070 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265509 | Tudh-Bath III | 145 | 93.708752 | 27.77484 | K26 | 258 | B | Tudh-Bath III |
| 1071 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265508 | Tudubath | 113 | 93.709758 | 27.768458 | K26 | | NIL | |
| 1072 | Arunachal Pradesh | Korung Kumey | Phassang | Phassang | 265421 | Pate | 105 | 93.742461 | 27.751631 | K27 | 198 | B | Pate |
| 1073 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265537 | Kamrong - I | 93 | 93.744528 | 27.745158 | K27 | | NIL | |
| 1074 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265517 | Delling | 107 | 93.700564 | 27.798265 | K28 | 189 | B | Delling |
| 1075 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265516 | Tangtanparang | 82 | 93.699928 | 27.793257 | K28 | | NIL | |
| 1076 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265518 | Rongterite | 121 | 93.726403 | 27.775117 | K29 | 225 | B | Rongterite |
| 1077 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265534 | Assupnja | 104 | 93.732553 | 27.788789 | K29 | | NIL | |
| 1078 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265506 | Shatey | 294 | 93.744235 | 27.784638 | K30 | 501 | B | Shatey |
| 1079 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265524 | Deringang | 118 | 93.742186 | 27.7783 | K30 | | NIL | |
| 1080 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265522 | Gai - 1 | 89 | 93.748131 | 27.784410 | K30 | | NIL | |
| 1081 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265512 | Tahu | 88 | 93.734329 | 27.816892 | K32 | 152 | B | Tahu |
| 1082 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265527 | Korayer | 64 | 93.726289 | 27.811489 | K32 | | NIL | |
| 1083 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265525 | Nyoya | 40 | 93.734536 | 27.820003 | K33 | 77 | B | Nyoya |
| 1084 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265519 | Sangha | 37 | 93.735883 | 27.823783 | K33 | | NIL | |
| 1085 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265513 | Padap | 114 | 93.739929 | 27.815211 | K34 | 257 | B | Padap |
| 1086 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265514 | Bodepa | 44 | 93.743768 | 27.812382 | K34 | | NIL | |
| 1087 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265520 | Paha | 99 | 93.747541 | 27.807947 | K34 | | NIL | |
| 1088 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265536 | Tirpu | 91 | 93.764936 | 27.817195 | K35 | 248 | B | Tirpu |
| 1089 | Arunachal Pradesh | Korung Kumey | Chambang | Chambang | 265503 | Roseng Hupa | 81 | 93.757917 | 27.80749 | K35 | | NIL | |




MR. RAMESHWAR DHARIMAL
 Director (H-1) (R&D),
 Director (T-1) (S&OE)
 Greater Kharak, New Arrang
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 1090 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265523 | Nyomi | 76 | 93.760288 | 27.818245 | K35 | | NIL | |
| 1091 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265900 | Nyado | 174 | 93.825797 | 27.943608 | K36 | 220 | B | Nyado |
| 1092 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265901 | Magnia | 46 | 93.833672 | 27.935256 | K36 | | NIL | |
| 1093 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265903 | Giba | 213 | 93.862542 | 27.916628 | K37 | 325 | B | Giba |
| 1094 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265902 | Neyomi | 117 | 93.84735 | 27.918861 | K37 | | NIL | |
| 1095 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265610 | Phattha | 64 | 93.866768 | 27.902932 | K39 | 186 | B | Phattha |
| 1096 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265607 | Sango II | 63 | 93.868427 | 27.898551 | K39 | | NIL | |
| 1097 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265609 | Boa II | 59 | 93.877335 | 27.90308 | K39 | | NIL | |
| 1098 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265606 | Sungpo | 105 | 93.889289 | 27.895337 | K41 | 174 | B | Sungpo |
| 1099 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265584 | Pha | 69 | 93.892721 | 27.891088 | K41 | | NIL | |
| 1100 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265669 | Korapu | 102 | 93.890781 | 27.835031 | K42 | 162 | B | Korapu |
| 1101 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265668 | Galangtong | 60 | 93.788636 | 27.834828 | K42 | | NIL | |
| 1102 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265557 | Pokca | 88 | 93.764222 | 27.761908 | K45 | 143 | B | Pokca |
| 1103 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265504 | Jakstara | 53 | 93.769281 | 27.769128 | K45 | | NIL | |
| 1104 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265501 | Chambang | 673 | 93.778747 | 27.776581 | K46 | 768 | B | Chambang |
| 1105 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265539 | Tabitlu | 95 | 93.774761 | 27.7758 | K46 | | NIL | |
| 1106 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265540 | Yerpu | 80 | 93.771098 | 27.781511 | K47 | 191 | B | Yerpu |
| 1107 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265535 | Cholo | 72 | 93.764853 | 27.784064 | K47 | | NIL | |
| 1108 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265502 | Sonyoketo | 39 | 93.779785 | 27.791349 | K47 | | NIL | |
| 1109 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265544 | Pujharak | 80 | 93.797164 | 27.764089 | K48 | 138 | B | Pujharak |




RAMESHWAR DHARIWAL
 Director (T-3) USOP
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|----------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|----------------|
| 1110 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265672 | Koti-Rait | 58 | 93.29575 | 27.759628 | K48 | | Nil | |
| 1111 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265651 | Rahang Chyee | 675 | 93.808244 | 27.764619 | K49 | 764 | B | Panang Chyee |
| 1112 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265560 | Huryung | 54 | 93.808625 | 27.768033 | K49 | | Nil | |
| 1113 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265629 | Mipam-Namching | 35 | 93.81369 | 27.760287 | K49 | | Nil | |
| 1114 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265653 | Puch-Pute | 117 | 93.831534 | 27.766614 | K50 | 230 | B | Puch-Pute |
| 1115 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265652 | Gachh | 88 | 93.820687 | 27.768669 | K50 | | Nil | |
| 1116 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265641 | Hepu-Hapa | 25 | 93.828385 | 27.772142 | K50 | | Nil | |
| 1117 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengti | Tali | 265671 | Tarak-Lengti | 222 | 93.825017 | 27.767003 | K51 | 842 | B | Tarak-Lengti |
| 1118 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265543 | Rombang | 120 | 93.820656 | 27.763464 | K51 | | Nil | |
| 1119 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265616 | Gali-III | 120 | 93.827172 | 27.820092 | K52 | 224 | B | Gali-III |
| 1120 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265545 | Harak II | 104 | 93.818904 | 27.826975 | K52 | | Nil | |
| 1121 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265613 | Pekpu | 120 | 93.849961 | 27.819106 | K53 | 205 | B | Pekpu |
| 1122 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265547 | Bonghang | 21 | 93.839147 | 27.817647 | K53 | | Nil | |
| 1123 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265561 | Tanjung-Koter | 64 | 93.857704 | 27.818399 | K53 | | Nil | |
| 1124 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265619 | Lengdi | 96 | 93.848248 | 27.85497 | K54 | 166 | B | Lengdi |
| 1125 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265621 | Tebyer | 70 | 93.839689 | 27.860205 | K54 | | Nil | |
| 1126 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265617 | Gali IV | 86 | 93.851834 | 27.820353 | K55 | 170 | B | Gali IV |
| 1127 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265618 | Taliyer | 84 | 93.854017 | 27.860738 | K55 | | Nil | |
| 1128 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265612 | Tagaraha | 90 | 93.866129 | 27.873345 | K56 | 137 | B | Tagaraha |
| 1129 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265626 | Korayer | 47 | 93.862718 | 27.878313 | K56 | | Nil | |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-I) USOF
 Director (T-I) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub-District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effectiv # PoP | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|------------|----------------|-----------|----------------|
| 1130 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265615 | Bunglung | 126 | 93.866716 | 27.865961 | K57 | 195 | B | Bunglung |
| 1131 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265623 | Yangte | 69 | 93.865872 | 27.861309 | K57 | | NIL | |
| 1132 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265622 | Phoi | 79 | 93.866881 | 27.856287 | K570 | 126 | B | Phoi |
| 1133 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265624 | Yangte II | 47 | 93.870858 | 27.859701 | K570 | | NIL | |
| 1134 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265602 | Rai | 144 | 93.892825 | 27.874249 | K58 | 344 | B | Rai |
| 1135 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265600 | Mencha | 80 | 93.883517 | 27.869867 | K58 | | NIL | |
| 1136 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265603 | Rai II | 120 | 93.892864 | 27.878978 | K58 | | NIL | |
| 1137 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265625 | Media | 55 | 93.879412 | 27.850762 | K59 | 95 | B | Media |
| 1138 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265595 | Lungchi | 40 | 93.873788 | 27.859344 | K59 | | NIL | |
| 1139 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265601 | Gongbang | 71 | 93.898296 | 27.872709 | K60 | 143 | B | Gongbang |
| 1140 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265596 | Raiga | 71 | 93.904094 | 27.870235 | K60 | | NIL | |
| 1141 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265597 | Raiga II | 84 | 93.906683 | 27.866456 | K61 | 150 | B | Raiga II |
| 1142 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265599 | Toya Rempa | 66 | 93.906983 | 27.862115 | K61 | | NIL | |
| 1143 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265587 | Gangte II | 101 | 93.922302 | 27.867683 | K62 | 180 | B | Gangte II |
| 1144 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265583 | Pulbe | 79 | 93.930091 | 27.860258 | K62 | | NIL | |
| 1145 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265591 | Tamak poring | 65 | 93.942103 | 27.869491 | K63 | 82 | B | Tamak poring |
| 1146 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265589 | Banja Katho | 17 | 93.935359 | 27.872833 | K63 | | NIL | |
| 1147 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265588 | Poring | 270 | 93.938851 | 27.856974 | K65 | 281 | B | Poring |
| 1148 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265598 | Genchi | 11 | 93.943011 | 27.862678 | K65 | | NIL | |
| 1149 | Arunachal Pradesh | Kurung Kumey | Gangte | Chambang | 265576 | Geit | 99 | 93.513775 | 27.841768 | K66 | 169 | B | Geit |




RAMESHWAR DHARIMAL
 Director (T-1) USOF
 wherever (Perry, West where Dept. of Telecom, Govt. of India
 and Birely/New Delhi)

| Sl. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | 10KG | LAT | Cluster No. | Effective Pop. | Site Type | Tower Location |
|---------|-------------------|---------------|-------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|-------------|----------------|-----------|----------------|
| 1150 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265580 | Yote | 70 | 93.924916 | 27.842559 | K66 | | NIL | |
| 1151 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265574 | Kamrung III | 72 | 93.919858 | 27.832204 | K67 | 104 | B | Kamrung III |
| 1152 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265585 | Dapam Hapa | 32 | 93.918244 | 27.825187 | K67 | | NIL | |
| 1153 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265581 | Ballo II | 114 | 93.918217 | 27.8176 | K68 | 160 | B | Ballo II |
| 1154 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265578 | Balbalo II | 46 | 93.917408 | 27.82161 | K68 | | NIL | |
| 1155 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265579 | Balbalo III | 100 | 93.907029 | 27.82538 | K69 | 154 | B | Balbalo III |
| 1156 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265572 | Borong | 39 | 93.899272 | 27.821251 | K69 | | NIL | |
| 1157 | Arunachal Pradesh | Korung Kumey | Sarli | Sarli | 265704 | Bala | 15 | 93.900716 | 27.813264 | K69 | | NIL | |
| 1158 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265593 | Pakung | 61 | 93.882204 | 27.833275 | K70 | 94 | B | Pakung |
| 1159 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265575 | Jomak Hapa | 33 | 93.895789 | 27.834497 | K70 | | NIL | |
| 1160 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265611 | Malin | 120 | 93.875758 | 27.828639 | K71 | 177 | B | Malin |
| 1161 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265584 | Tumhaming | 57 | 93.872429 | 27.828959 | K71 | | NIL | |
| 1162 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265568 | Techipu | 74 | 93.878946 | 27.804174 | K72 | 145 | B | Techipu |
| 1163 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265569 | Higo II | 71 | 93.873485 | 27.809821 | K72 | | NIL | |
| 1164 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265564 | Hitung Songo | 64 | 93.866467 | 27.805566 | K72 | 129 | B | Hitung Songo |
| 1165 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265567 | Tebum | 55 | 93.860864 | 27.810159 | K72 | | NIL | |
| 1166 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265570 | Techipu Koto | 100 | 93.871926 | 27.799561 | K73 | 151 | B | Techipu Koto |
| 1167 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265563 | Tarha | 51 | 93.862918 | 27.798304 | K73 | | NIL | |
| 1168 | Arunachal Pradesh | Korung Kumey | Tarak-Lengdi | Tarak-Lengdi | 265631 | Bump-Hapa | 56 | 93.842477 | 27.766975 | K74 | 104 | B | Bump-Hapa |
| 1169 | Arunachal Pradesh | Korung Kumey | Gangte | Chambang | 265562 | Higo | 46 | 93.843347 | 27.768039 | K74 | | NIL | |




RAMESHWAR DHARIMAL
 Director (T-1) USOF
 Deptt. of Telecom. Govt. of India
 New Staff/New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------|--------------|----------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|----------------|
| 1170 | Arunachal Pradesh | Kurang Kumey | Tarak-Lengdi | Tali | 265044 | Cvuthi | 154 | 93.85231 | 27.754896 | K75 | 235 | B | Cvuth |
| 1171 | Arunachal Pradesh | Kurang Kumey | Tarak-Lengdi | Tali | 265036 | Derduk (T-Tab) | 81 | 93.858819 | 27.763263 | K75 | | NIL | |
| 1172 | Arunachal Pradesh | Kurang Kumey | Tarak-Lengdi | Tali | 265034 | PKate | 96 | 93.862109 | 27.744613 | K76 | 127 | B | PKate |
| 1173 | Arunachal Pradesh | Kurang Kumey | Tarak-Lengdi | Tali | 265067 | Tingang | 31 | 93.875544 | 27.746152 | K76 | | NIL | |
| 1174 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265019 | Hill Poto | 61 | 93.900259 | 27.755552 | K77 | 119 | B | Hill Poto |
| 1175 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265058 | Gap Yonh | 58 | 93.903846 | 27.747735 | K77 | | NIL | |
| 1176 | Arunachal Pradesh | Kurang Kumey | Tarak-Lengdi | Tali | 265048 | Lolsee | 76 | 93.870441 | 27.769058 | K78 | 184 | B | Lolsee |
| 1177 | Arunachal Pradesh | Kurang Kumity | Gangte | Chambang | 265066 | Galli | 56 | 93.857289 | 27.778553 | K78 | | NIL | |
| 1178 | Arunachal Pradesh | Kurang Kumity | Tarak-Lengdi | Tali | 265033 | Tapa Poring | 52 | 93.869352 | 27.777718 | K78 | | NIL | |
| 1179 | Arunachal Pradesh | Kurang Kumey | Chambang | Chambang | 265046 | Lungchi | 123 | 93.860722 | 27.783594 | K79 | 157 | B | Lungchi |
| 1180 | Arunachal Pradesh | Kurang Kumey | Gangte | Chambang | 265071 | Bomahaga | 34 | 93.866681 | 27.789283 | K79 | | NIL | |
| 1181 | Arunachal Pradesh | Kurang Kumey | Gangte | Chambang | 265077 | Ralbako | 124 | 93.900117 | 27.7807 | K80 | 186 | B | Ralbako |
| 1182 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265052 | Putu | 62 | 93.911256 | 27.791256 | K80 | | NIL | |
| 1183 | Arunachal Pradesh | Kurang Kumey | Gangte | Chambang | 265073 | Kamrogi II | 54 | 93.893425 | 27.787636 | K81 | 104 | B | Kamrogi II |
| 1184 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265021 | Pah Rijo | 50 | 93.89179 | 27.794606 | K81 | | NIL | |
| 1185 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265064 | Setlu Pury | 81 | 93.93278 | 27.82748 | K82 | 159 | B | Setlu Pury |
| 1186 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265063 | Dea Hill Top | 78 | 93.93051 | 27.823598 | K82 | | NIL | |
| 1187 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265041 | Loktap | 82 | 93.945894 | 27.793665 | KXXXI | 124 | B | Loktap |
| 1188 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265040 | Bomel Hapa | 42 | 93.945424 | 27.78896 | KXXXI | | NIL | |
| 1189 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265077 | Mengo Katak II | 56 | 93.914322 | 27.795525 | KXXXI | 90 | B | Mengo Katak II |



| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------------|--------------|-----------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 1190 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265075 | Jop Hapa | 34 | 93.924123 | 27.797906 | KKKK6 | | NIL | |
| 1191 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265084 | Pompaulend | 107 | 93.913329 | 27.789173 | KKKK7 | 157 | B | Pompaulend |
| 1192 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265078 | Byan Byap | 50 | 93.911476 | 27.792614 | KKKK7 | | NIL | |
| 1193 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265054 | Tumporjo | 130 | 93.923958 | 27.769965 | LLLL1 | 165 | B | Tumporjo |
| 1194 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265055 | Ampar Rashe | 35 | 93.921841 | 27.765025 | LLLL1 | | NIL | |
| 1195 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265056 | Chudi Yem | 56 | 93.947747 | 27.768201 | LLLL2 | 93 | B | Chudi Yem |
| 1196 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265050 | Harakso | 37 | 93.946188 | 27.762555 | LLLL2 | | NIL | |
| 1197 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265102 | Ajo Phub | 15 | 93.938005 | 27.731426 | RRRR7 | 29 | B | Ajo Phub |
| 1198 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265035 | Subhal | 14 | 93.953897 | 27.732504 | RRRR7 | | NIL | |
| 1199 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265039 | Rago | 27 | 93.933544 | 27.6784 | RRRR8 | 146 | B | Ragi |
| 1200 | Arunachal Pradesh | Lower Subansiri | Kampongjo | Tamen-Raga | 265044 | Karni | 19 | 93.926024 | 27.693573 | RRRR8 | | NIL | |
| 1201 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263358 | Korle | 69 | 94.274275 | 28.772183 | 51 | 182 | B | Korle |
| 1202 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263316 | Monigong | 46 | 94.280761 | 28.781853 | 51 | | NIL | |
| 1203 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263353 | Rensang Village | 67 | 94.285106 | 28.78735 | 51 | | NIL | |
| 1204 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263375 | Rulu | 145 | 94.258324 | 28.743961 | 53 | 228 | B | Rulu |
| 1205 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263374 | Gapur | 83 | 94.260953 | 28.740272 | 53 | | NIL | |
| 1206 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263393 | Gahlong | 91 | 94.253467 | 28.717944 | 54 | 168 | B | Gahlong |
| 1207 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263395 | Sulhe | 77 | 94.251944 | 28.713503 | 54 | | NIL | |
| 1208 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263385 | Pangri | 62 | 94.283044 | 28.686777 | 55 | 87 | B | Pangri |
| 1209 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263391 | Gelak | 25 | 94.278947 | 28.692761 | 55 | | NIL | |
| 1210 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263386 | Korle | 51 | 94.271622 | 28.655919 | 56 | 97 | B | Korle |
| 1211 | Arunachal Pradesh | West Siang | Monigong | Monigong | 263351 | Tahla | 36 | 94.284735 | 28.658072 | 56 | | NIL | |
| 1212 | Arunachal Pradesh | West Siang | Talo | Mechuka | 263435 | Lipo | 119 | 94.469937 | 28.526922 | 59 | 157 | B | Lipo |
| 1213 | Arunachal Pradesh | West Siang | Talo | Mechuka | 263432 | Yapu | 38 | 94.449189 | 28.505906 | 59 | | NIL | |
| 1214 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro | 264645 | Zemra | 1 | Not Found | Not Found | SINGLE | 1 | A | Zemra |
| 1215 | Arunachal Pradesh | Tawang | Zemithang | Zemithang-Dudunghat | 261390 | Henggang | 4 | 91.668538 | 27.593124 | SINGLE | 4 | A | Henggang |




रमेश्वर धरिवाल
RAMESHWAR DHARIMAL
 Director (IT-I) USOF
 Director (IT-I) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-------------------|----------------|--------------|---------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|--------------------|
| 1216 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265937 | Achengo | 5 | Not Found | Not Found | SINGLE | 5 | A | Achengo |
| 1217 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunri-Desali | 266095 | Letongo | 7 | Not Found | Not Found | SINGLE | 7 | A | Letongo |
| 1218 | Arunachal Pradesh | Lower Dibang Valley | Koromu | Rong-Koromu | 266255 | Etungoo | 7 | Not Found | Not Found | SINGLE | 7 | A | Etungoo |
| 1219 | Arunachal Pradesh | West Siang | Tato | Meshuka | 263436 | Paum | 8 | 94.510864 | 28.519411 | SINGLE | 8 | A | Paum |
| 1220 | Arunachal Pradesh | East Kameng | Pitshing(Veo) | Palika-Messang | 261959 | Lumbe | 10 | 93.107994 | 27.140217 | SINGLE | 10 | A | Lumbe |
| 1221 | Arunachal Pradesh | Anjaw | Manchar | Manchar | 266744 | Long Jam | 11 | 96.687064 | 28.078647 | SINGLE | 11 | A | Long Jam |
| 1222 | Arunachal Pradesh | Papum Pare | Parang | Sagalee | 262627 | Quungo | 11 | Not Found | Not Found | SINGLE | 11 | A | Quungo |
| 1223 | Arunachal Pradesh | Lower Subansiri | Ziro (Sude) | Ziro-1 | 264592 | Tatin | 11 | 93.85402 | 27.52381 | SINGLE | 11 | A | Tatin |
| 1224 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265935 | Edwa | 11 | Not Found | Not Found | SINGLE | 11 | A | Edwa |
| 1225 | Arunachal Pradesh | Upper Subansiri | Dapostio | Dapostio | 263109 | Cheha-Ripo | 12 | 94.133198 | 27.920016 | SINGLE | 12 | A | Cheha-Ripo |
| 1226 | Arunachal Pradesh | Kurung Kumey | Koloriang | Koloriang | 265474 | Relung | 12 | 93.301318 | 27.93379 | SINGLE | 12 | A | Relung |
| 1227 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262625 | Poying | 13 | 93.784743 | 28.380107 | SINGLE | 13 | A | Poying |
| 1228 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265922 | Acoto | 13 | 95.989669 | 28.843042 | SINGLE | 13 | A | Acoto |
| 1229 | Arunachal Pradesh | Changlang | Namtoi | Changlang | 264742 | Namding(Namda ng-1) | 13 | 95.692733 | 27.234506 | SINGLE | 13 | A | Namding(Namding-1) |
| 1230 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265908 | Adoli | 14 | 95.813658 | 28.916949 | SINGLE | 14 | A | Adoli |
| 1231 | Arunachal Pradesh | Lohit | Chenggham | Chenggham | 266506 | Passing | 14 | 96.094953 | 27.733365 | SINGLE | 14 | A | Passing |
| 1232 | Arunachal Pradesh | Upper Subansiri | Umeking | Umeking | 262784 | Boobk | 14 | 93.554079 | 28.341951 | SINGLE | 14 | A | Boobk |
| 1233 | Arunachal Pradesh | West Siang | Gerdi | Gerdi | 263697 | Roma Village | 14 | 94.366022 | 27.712639 | SINGLE | 14 | A | Roma Village |
| 1234 | Arunachal Pradesh | Lower Dibang Valley | Hunri | Hunri-Desali | 266086 | Kebaboli | 14 | Not Found | Not Found | SINGLE | 14 | A | Kebaboli |
| 1235 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265932 | Manoli | 15 | 95.871936 | 28.779969 | SINGLE | 15 | A | Manoli |
| 1236 | Arunachal Pradesh | Anjaw | Chaglam | Chaglam | 266824 | Kasy Moko | 16 | 96.603456 | 28.295701 | SINGLE | 16 | A | Kasy Moko |
| 1237 | Arunachal Pradesh | Anjaw | Hayuliang | Hayuliang | 266693 | Blom | 16 | 96.579302 | 28.08226 | SINGLE | 16 | A | Blom |
| 1238 | Arunachal Pradesh | Lower Dibang Valley | Hunri | Hunri-Desali | 266056 | Punji | 17 | 95.923451 | 28.359412 | SINGLE | 17 | A | Punji |
| 1239 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265916 | Engolin | 17 | Not Found | Not Found | SINGLE | 17 | A | Engolin |
| 1240 | Arunachal Pradesh | Tawang | Bongbar | Mukto-Bongbar | 261604 | Kharungdang | 18 | 91.826882 | 27.539155 | SINGLE | 18 | A | Kharungdang |
| 1241 | Arunachal Pradesh | Dibang Valley | Etalin | Etalin | 265981 | Alney (Aloney 1) | 18 | 95.929938 | 28.549046 | SINGLE | 18 | A | Alney (Aloney 1) |
| 1242 | Arunachal Pradesh | Papum Pare | Parang | Sagalee | 262640 | Tapiu | 18 | Not Found | Not Found | SINGLE | 18 | A | Tapiu |
| 1243 | Arunachal Pradesh | Lohit | Tezu | Tezu | 266409 | Dabangam | 21 | 96.219581 | 28.032706 | SINGLE | 21 | A | Dabangam |



| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-------------------|---------------|--------------|----------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------------|
| 1244 | Arunachal Pradesh | West Kameng | Thibhho | Thibhho | 261850 | Dinpani | 22 | 92.684009 | 27.310635 | SINGLE | 22 | A | Dinpani |
| 1245 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264594 | Tiba | 22 | Not Found | Not Found | SINGLE | 22 | A | Tiba |
| 1246 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koroua | 264270 | Nakpi | 23 | 95.774913 | 28.169804 | SINGLE | 23 | A | Nakpi |
| 1247 | Arunachal Pradesh | Dibang Valley | Aneih | Aneih-Arua | 266004 | Berupo Model village | 23 | 95.812018 | 28.506169 | SINGLE | 23 | A | Berupo Model village |
| 1248 | Arunachal Pradesh | Lower Dibang Valley | Desali | Hunli-Desali | 266125 | Hukun-Pengp | 23 | 96.018264 | 28.355645 | SINGLE | 23 | A | Hukun-Pengp |
| 1249 | Arunachal Pradesh | Anjaw | Wabong | Watong | 266898 | Saro U/Camp | 23 | 96.972947 | 28.020603 | SINGLE | 23 | A | Saro U/Camp |
| 1250 | Arunachal Pradesh | West Siang | Kanglu | Likabali | 263748 | Richi - Rite | 23 | 94.478982 | 27.683001 | SINGLE | 23 | A | Richi - Rite |
| 1251 | Arunachal Pradesh | East Kameng | Sejosa | Sejosa | 263917 | Taro-Soso | 24 | 93.076153 | 27.005713 | SINGLE | 24 | A | Taro-Soso |
| 1252 | Arunachal Pradesh | West Siang | Mongong | Mongong | 263394 | Panglum | 24 | 94.242553 | 28.722269 | SINGLE | 24 | A | Panglum |
| 1253 | Arunachal Pradesh | Anjaw | Hayulung | Hayulung | 266704 | Kabragam | 24 | Not Found | Not Found | SINGLE | 24 | A | Kabragam |
| 1254 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264595 | Taru-Aiya | 25 | Not Found | Not Found | SINGLE | 25 | A | Taru-Aiya |
| 1255 | Arunachal Pradesh | Kurung Kumey | Kololing | Kololing | 265473 | Koathrang | 27 | 93.951486 | 27.898967 | SINGLE | 27 | A | Koathrang |
| 1256 | Arunachal Pradesh | Upper Subansiri | Nache | Nache | 262806 | Taro | 27 | 93.893707 | 28.340879 | SINGLE | 27 | A | Taro |
| 1257 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263327 | Chorling | 29 | 94.324195 | 28.601863 | SINGLE | 29 | A | Chorling |
| 1258 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koroua | 266267 | Elopa | 29 | 95.819225 | 28.214116 | SINGLE | 29 | A | Elopa |
| 1259 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265918 | Kamuyi | 29 | Not Found | Not Found | SINGLE | 29 | A | Kamuyi |
| 1260 | Arunachal Pradesh | Dibang Valley | Anini | Anini-Mipi | 265936 | Acheso | 31 | 95.97448 | 28.921822 | SINGLE | 31 | A | Acheso |
| 1261 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262583 | Pachin | 32 | 93.733617 | 27.139147 | SINGLE | 32 | A | Pachin |
| 1262 | Arunachal Pradesh | Upper Siang | Singa | Singa-Gelling | 263974 | Sinuing | 32 | 95.182993 | 28.890127 | SINGLE | 32 | A | Sinuing |
| 1263 | Arunachal Pradesh | Papum Pare | Taraso | Balijan | 262422 | Kampung Reng | 33 | 93.428554 | 28.984996 | SINGLE | 33 | A | Kampung Reng |
| 1264 | Arunachal Pradesh | East Kameng | Shenewa | Shenewa | 262197 | Payu | 33 | Not Found | Not Found | SINGLE | 33 | A | Payu |
| 1265 | Arunachal Pradesh | Changlang | Yabdam | Changlang | 264073 | Kanglah | 33 | Not Found | Not Found | SINGLE | 33 | A | Kanglah |
| 1266 | Arunachal Pradesh | Dibang Valley | Mipi | Anini-Mipi | 265911 | Jingoua | 35 | Not Found | Not Found | SINGLE | 35 | A | Jingoua |
| 1267 | Arunachal Pradesh | Lower Subansiri | Pistasa | Ziro-II | 265004 | Dora | 36 | 93.625689 | 27.503407 | SINGLE | 36 | A | Dora |
| 1268 | Arunachal Pradesh | Lower Subansiri | Kamponjo | Tamen-Buga | 265068 | Kunde | 36 | 94.00109 | 27.869127 | SINGLE | 36 | A | Kunde |
| 1269 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264625 | Taruahie | 36 | Not Found | Not Found | SINGLE | 36 | A | Taruahie |
| 1270 | Arunachal Pradesh | Kurung Kumey | Myapin | Myapin | 265592 | ipinE | 36 | 93.485934 | 27.688831 | SINGLE | 36 | A | ipinE |



RAMESHWAR DHARWAL
 Director (G-I) & Gen. Mgt.
 Director (T-I) USOF
 Deputy Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effectiv # Pop | Site Type | Tower Location |
|---------|--------------------|---------------------|----------------------------|---------------|--------------|----------------|-----------------------------|-----------|-----------|------------|----------------|-----------|----------------|
| 1271 | Assamachal Pradesh | West Kameng | Balemu | Kalaxiang | 263888 | Kharumani | 37 | 92.163265 | 26.966534 | SINGLE | 37 | A | Gharumali |
| 1272 | Assamachal Pradesh | Lohit | Wakre | Wakre | 265483 | Prohli | 37 | 92.331724 | 27.753932 | SINGLE | 37 | A | Prohli |
| 1273 | Assamachal Pradesh | West Kameng | Nafra | Nafra | 261715 | Sabang | 38 | 92.76989 | 27.495662 | SINGLE | 38 | A | Sabang |
| 1274 | Assamachal Pradesh | Upper Subansiri | Limeking | Limeking | 262797 | Redding Camp | 39 | 93.447528 | 28.440542 | SINGLE | 39 | A | Redding Camp |
| 1275 | Assamachal Pradesh | Changang | Changang | Changang | 264075 | Panikheti | 40 | 95.720236 | 27.189741 | SINGLE | 40 | A | Panikheti |
| 1276 | Assamachal Pradesh | Lower Dibang Valley | Hurai | Hurai-Desari | 266049 | Chulugu | 40 | 95.930339 | 28.308615 | SINGLE | 40 | A | Chulugu |
| 1277 | Assamachal Pradesh | East Siang | Riga | Riga | 263786 | Ujung | 43 | 95.094324 | 28.40524 | SINGLE | 43 | A | Ujung |
| 1278 | Assamachal Pradesh | Kurung Kumey | Sarli | Sarli | 265677 | Melo | 44 | 93.121013 | 27.958874 | SINGLE | 44 | A | Melo |
| 1279 | Assamachal Pradesh | East Kameng | Bumeng | Bumeng | 262114 | Gidi Sullung | 45 | 92.899152 | 27.477025 | SINGLE | 45 | A | Gidi Sullung |
| 1280 | Assamachal Pradesh | Papum Pare | Toru | Sagalee | 262537 | Tamang | 45 | 93.64985 | 27.263829 | SINGLE | 45 | A | Tamang |
| 1281 | Assamachal Pradesh | East Kameng | Chayangajo | Chayangajo | 262243 | Paje Tassar | 46 | 93.206497 | 27.793019 | SINGLE | 46 | A | Paje Tassar |
| 1282 | Assamachal Pradesh | West Kameng | Dirang | Dirang | 261673 | Bokhum Village | 46 | 93.323047 | 27.400325 | SINGLE | 46 | A | Bokhum Village |
| 1283 | Assamachal Pradesh | Anjaw | Hawai | Walong | 266959 | 7th K.M. Camp | 46 | Not Found | Not Found | SINGLE | 46 | A | 7th K.M. Camp |
| 1284 | Assamachal Pradesh | Anjaw | Hawai | Walong | 266961 | 12th K.M. Camp | 46 | 95.93449 | 27.90747 | SINGLE | 46 | A | 12th K.M. Camp |
| 1285 | Assamachal Pradesh | Lower Dibang Valley | Desari | Hurai-Desari | 266138 | Chimaro | 47 | 96.043447 | 28.262652 | SINGLE | 47 | A | Chimaro |
| 1286 | Assamachal Pradesh | Dibang Valley | Mipi | Amri-Mipi | 265909 | Eriyan | 47 | Not Found | Not Found | SINGLE | 47 | A | Eriyan |
| 1287 | Assamachal Pradesh | West Kameng | Nafra | Nafra | 261735 | Srimathung | 48 | 92.475703 | 27.40256 | SINGLE | 48 | A | Srimathung |
| 1288 | Assamachal Pradesh | West Siang | Kaying | Kaying-Payum | 263454 | Pagak | 48 | 94.694303 | 28.383194 | SINGLE | 48 | A | Pagak |
| 1289 | Assamachal Pradesh | Anjaw | Walong | Walong | 266897 | Sethi | 49 | 96.998933 | 28.07915 | SINGLE | 49 | A | Sethi |
| 1290 | Assamachal Pradesh | Dibang Valley | Mipi | Amri-Mipi | 265913 | Afango | 49 | Not Found | Not Found | SINGLE | 49 | A | Afango |
| 1291 | Assamachal Pradesh | Kurung Kumey | Dumin | Damin | 265780 | Damin Village | 50 | 93.323714 | 28.052411 | SINGLE | 50 | A | Damin Village |
| 1292 | Assamachal Pradesh | Kurung Kumey | Longing Koling (Pissorang) | Piporang | 265862 | Kokso | 50 | 95.5434 | 28.123525 | SINGLE | 50 | A | Kokso |
| 1293 | Assamachal Pradesh | Upper Siang | Tuling | Tuling | 263935 | Tengga | 50 | 94.915501 | 28.948825 | SINGLE | 50 | A | Tengga |
| 1294 | Assamachal Pradesh | West Siang | Pdi | Mechuka | 263405 | Nutin | 50 | Not Found | Not Found | SINGLE | 50 | A | Nutin |
| 1295 | Assamachal Pradesh | Kurung Kumey | Phissang | Nyaphin | 265415 | Yongang | 50 | Not Found | Not Found | SINGLE | 50 | A | Yongang |
| 1296 | Assamachal Pradesh | Kurung Kumey | Gangte | Chambang | 265580 | Ballo | 50 | Not Found | Not Found | SINGLE | 50 | A | Ballo |
| 1297 | Assamachal Pradesh | Papam Pare | Panang | Saplee | 262633 | Sanga Gyabe | 51 | Not Found | Not Found | SINGLE | 51 | A | Sanga Gyabe |
| 1298 | Assamachal Pradesh | Kurung Kumey | Koloriang | Koloriang | 265491 | Sebi | 51 | 93.461612 | 27.877346 | SINGLE | 51 | A | Sebi |



| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-------------------|----------------|--------------|----------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------------|
| 1299 | Arunachal Pradesh | Upper Subansiri | Umeking | Lumking | 262783 | Gang | 52 | 93.591752 | 28.322066 | SINGLE | 52 | A | Gang |
| 1300 | Arunachal Pradesh | Papum Pare | Minim | Kiram | 262729 | Bucka - II | 53 | 93.899942 | 27.264053 | SINGLE | 53 | A | Bucka - II |
| 1301 | Arunachal Pradesh | Lower Dibang Valley | Dambuk | Dambuk | 266321 | Rasing | 53 | 95.633958 | 28.252047 | SINGLE | 53 | A | Rasing |
| 1302 | Arunachal Pradesh | Upper Subansiri | Maro | Bulrjo | 263302 | Pani Muri | 55 | 94.314392 | 27.906114 | SINGLE | 55 | A | Pani Muri |
| 1303 | Arunachal Pradesh | East Siang | Kebang | Pangin | 263806 | Kaliek | 55 | 95.159522 | 28.095864 | SINGLE | 55 | A | Kaliek |
| 1304 | Arunachal Pradesh | Papum Pare | Taraso | Baijan | 262425 | Darabul | 56 | 93.464115 | 26.953258 | SINGLE | 56 | A | Darabul |
| 1305 | Arunachal Pradesh | Dibang Valley | Eralin | Eranin-Malinya | 265985 | Charik | 56 | 95.585302 | 28.557737 | SINGLE | 56 | A | Charik |
| 1306 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265387 | Ataching | 57 | 93.48744 | 27.484483 | SINGLE | 57 | A | Ataching |
| 1307 | Arunachal Pradesh | Tawang | Thingbu | Jang-Thingbu | 263611 | Luguthang | 58 | 92.187071 | 27.594777 | SINGLE | 58 | A | Luguthang |
| 1308 | Arunachal Pradesh | Dibang Valley | Aneith | Aneith-Azru | 266005 | Model Village | 58 | 93.043172 | 27.375815 | SINGLE | 58 | A | Model Village |
| 1309 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263346 | Sorangdem | 58 | 94.038883 | 28.592663 | SINGLE | 58 | A | Sorangdem |
| 1310 | Arunachal Pradesh | Upper Subansiri | Daporjo | Daporjo | 263105 | Degom | 58 | 94.155263 | 27.951888 | SINGLE | 58 | A | Degom |
| 1311 | Arunachal Pradesh | West Siang | Darait | Darait | 263463 | Sijr Saksep | 59 | 94.586759 | 28.23364 | SINGLE | 59 | A | Sijr Saksep |
| 1312 | Arunachal Pradesh | East Siang | Kora | Ramte-Bango | 263833 | Tene Camp | 59 | 95.02705 | 27.948645 | SINGLE | 59 | A | Tene Camp |
| 1313 | Arunachal Pradesh | West Siang | Kanglu | Lakabali | 263751 | Niji - Koche | 61 | 94.553322 | 27.621055 | SINGLE | 61 | A | Niji - Koche |
| 1314 | Arunachal Pradesh | West Siang | Kanglu | Lakabali | 263741 | Pompek | 61 | Not Found | Not Found | SINGLE | 61 | A | Pompek |
| 1315 | Arunachal Pradesh | Changlang | Changlang | Changlang | 264118 | Langchuk | 61 | 95.715555 | 27.097932 | SINGLE | 61 | A | Langchuk |
| 1316 | Arunachal Pradesh | Papum Pare | Kukoi | Kimin | 262758 | Dirga Forest Range | 62 | 94.079586 | 27.413817 | SINGLE | 62 | A | Dirga Forest Range |
| 1317 | Arunachal Pradesh | West Siang | Piyum | Kaying-Piyum | 263422 | Meying | 62 | 94.663623 | 28.485176 | SINGLE | 62 | A | Meying |
| 1318 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262811 | Mede | 63 | 93.727597 | 28.396088 | SINGLE | 63 | A | Mede |
| 1319 | Arunachal Pradesh | Lower Dibang Valley | Desai | Hunli-Desai | 266115 | Chuyum Model village | 63 | 96.093167 | 28.318525 | SINGLE | 63 | A | Chuyum Model village |
| 1320 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265526 | Hatey | 64 | 93.781787 | 27.891218 | SINGLE | 64 | A | Hatey |
| 1321 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263429 | Tagur | 64 | 94.598278 | 28.456321 | SINGLE | 64 | A | Tagur |
| 1322 | Arunachal Pradesh | Kurung Kumey | Tarak Lengti | Till | 265648 | Gangte (Genle) | 65 | 93.840406 | 27.715192 | SINGLE | 65 | A | Gangte (Genle) |
| 1323 | Arunachal Pradesh | West Siang | Daring | Basar | 263678 | Echi Saku/Eding | 65 | 94.788441 | 27.905334 | SINGLE | 65 | A | Echi Saku/Eding |
| 1324 | Arunachal Pradesh | Kurung Kumey | Chambang | Chambang | 265538 | Komrung II | 66 | 93.751712 | 27.77185 | SINGLE | 66 | A | Komrung II |





रमेश्वर धरिवाल
RAMESHWAR DHARIVAL
 Director (T-1) USOF
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|--------------------|-----------------|--------------------|---------------|--------------|------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|------------------|
| 1325 | Assamachal Pradesh | West Siang | Kangku | Usabali | 263736 | Changpak - chojo | 66 | 94.324317 | 27.596864 | SINGLE | 66 | A | Changpak - chojo |
| 1326 | Assamachal Pradesh | West Siang | Mongong | Mongong | 263369 | Sukudom | 67 | 94.363846 | 28.886364 | SINGLE | 67 | A | Sukudom |
| 1327 | Assamachal Pradesh | West Siang | Lironmba | Lironmba | 263526 | Biru | 67 | 94.836967 | 28.156606 | SINGLE | 67 | A | Biru |
| 1328 | Assamachal Pradesh | Papum Pare | Lepparing | Sagahet | 262678 | Lower Sango | 68 | 93.688439 | 27.103225 | SINGLE | 68 | A | Lower Sango |
| 1329 | Assamachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Ghat | 263944 | Shak | 68 | Not Found | Not Found | SINGLE | 68 | A | Shak |
| 1330 | Assamachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Ghat | 263051 | Machi- Rijo | 69 | 94.133346 | 28.049087 | SINGLE | 69 | A | Machi- Rijo |
| 1331 | Assamachal Pradesh | Upper Subansiri | Fuchi Geko | Puchi Geko | 263161 | Balekman | 70 | 94.261912 | 27.861887 | SINGLE | 70 | A | Balekman |
| 1332 | Assamachal Pradesh | Lohit | Sunpara | Tezu | 266372 | Tusigam | 71 | 96.137559 | 28.032168 | SINGLE | 71 | A | Tusigam |
| 1333 | Assamachal Pradesh | Kurung Kumey | Chambang | Chambang | 265559 | Haming | 71 | 93.74454 | 27.857325 | SINGLE | 71 | A | Haming |
| 1334 | Assamachal Pradesh | Upper Subansiri | Gleu | Gibi | 263010 | Puda | 72 | 94.040504 | 28.128423 | SINGLE | 72 | A | Puda |
| 1335 | Assamachal Pradesh | West Siang | Kyng | Kaving-Payum | 263449 | Tuying Village | 72 | 94.558836 | 28.403008 | SINGLE | 72 | A | Tuying Village |
| 1336 | Assamachal Pradesh | Dibang Valley | Anim | Anni-Mipi | 265924 | Awango | 72 | 95.958141 | 28.854463 | SINGLE | 72 | A | Awango |
| 1337 | Assamachal Pradesh | Lohit | Chongkham | Chongkham | 266510 | Emboing | 72 | 96.176211 | 27.770927 | SINGLE | 72 | A | Emboing |
| 1338 | Assamachal Pradesh | East Kameng | Dising-Passo | Sejosa | 261919 | New Dising | 72 | Not Found | Not Found | SINGLE | 72 | A | New Dising |
| 1339 | Assamachal Pradesh | Changlang | Munniao | Munniao | 264154 | Bima | 73 | 96.20735 | 27.312803 | SINGLE | 73 | A | Bima |
| 1340 | Assamachal Pradesh | Changlang | Changlang | Changlang | 264122 | Khithang - Tong | 74 | 95.81771 | 27.05121 | SINGLE | 74 | A | Khithang - Tong |
| 1341 | Assamachal Pradesh | West Kameng | Singchung | Singchung | 261831 | Sachida | 75 | 92.566667 | 27.283333 | SINGLE | 75 | A | Sachida |
| 1342 | Assamachal Pradesh | Kurung Kumey | Myapin | Myapin | 265895 | Kampui | 75 | 92.976913 | 27.282198 | SINGLE | 75 | A | Kampui |
| 1343 | Assamachal Pradesh | Kurung Kumey | Pabin | Pabin | 265239 | Choba (Jamni) | 75 | 93.609697 | 27.716886 | SINGLE | 75 | A | Choba (Jamni) |
| 1344 | Assamachal Pradesh | Lower Subansiri | Yazali | Ziro-II | 264921 | Phop | 75 | 93.749729 | 27.355089 | SINGLE | 75 | A | Phop |
| 1345 | Assamachal Pradesh | Lower Subansiri | Ziro (Sarda) | Ziro-I | 264617 | Siro Ago | 75 | 93.916607 | 27.519561 | SINGLE | 75 | A | Siro Ago |
| 1346 | Assamachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263156 | Pidilaa | 75 | 94.214286 | 27.890058 | SINGLE | 75 | A | Pidilaa |
| 1347 | Assamachal Pradesh | Lohit | Sumbra | Tezu | 266373 | Bedagan | 77 | 96.143996 | 28.085762 | SINGLE | 77 | A | Bedagan |
| 1348 | Assamachal Pradesh | Lower Subansiri | Kamponjo | Tamen-Ringa | 265067 | Paga Hepa | 78 | 93.960203 | 27.86099 | SINGLE | 78 | A | Paga Hepa |
| 1349 | Assamachal Pradesh | Changlang | Yeldam | Changlang | 264056 | Datkan | 78 | 95.66706 | 27.11051 | SINGLE | 78 | A | Datkan |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOP
 Director (T-1) USOP
 Deputy Director, New Delhi
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop. | Site Type | Tower Location |
|---------|-------------------|---------------------|--------------------|---------------|--------------|-------------------------|-----------------------------|-----------|-----------|------------|----------------|-----------|-------------------------|
| 1350 | Arunachal Pradesh | Lower Dibang Valley | Rong | Rong Korou | 266265 | Ipiangol (6 K.M. Point) | 78 | Not Found | Not Found | SINGLE | 78 | A | Ipiangol (6 K.M. Point) |
| 1351 | Arunachal Pradesh | West Siang | Sibe | Genol | 263706 | Yachung | 79 | 94.46436 | 27.728732 | SINGLE | 79 | A | Yachung |
| 1352 | Arunachal Pradesh | West Siang | Genol | Genol | 263694 | Iteneri | 80 | 94.557367 | 27.799906 | SINGLE | 80 | A | Iteneri |
| 1353 | Arunachal Pradesh | Changlang | Yadara | Changlang | 264057 | Motang | 80 | 95.676758 | 26.995681 | SINGLE | 80 | A | Motang |
| 1354 | Arunachal Pradesh | Papum Pare | Parang | Sagalee | 262832 | Dudik | 80 | Not Found | Not Found | SINGLE | 80 | A | Dudik |
| 1355 | Arunachal Pradesh | West Siang | Monjong | Momzong | 263359 | Chingo | 81 | 94.231872 | 28.785147 | SINGLE | 81 | A | Chingo |
| 1356 | Arunachal Pradesh | Upper Subansiri | Barrijo | Barrijo | 263275 | Riggi Haji | 81 | 94.362641 | 27.948081 | SINGLE | 81 | A | Riggi Haji |
| 1357 | Arunachal Pradesh | Tirap | Kanubari | Kanubari | 264510 | Ngamding | 81 | 95.37682 | 27.680183 | SINGLE | 81 | A | Ngamding |
| 1358 | Arunachal Pradesh | Kurung Kumey | Tarak-Lengli | Tali | 265660 | Tabu | 81 | Not Found | Not Found | SINGLE | 81 | A | Tabu |
| 1359 | Arunachal Pradesh | Changlang | Rehuk | Mianrao | 265177 | Ranghli | 82 | 96.912011 | 27.095862 | SINGLE | 82 | A | Ranghli |
| 1360 | Arunachal Pradesh | Papum Pare | Parang | Sagalee | 262632 | Tobonang | 83 | Not Found | Not Found | SINGLE | 83 | A | Tobonang |
| 1361 | Arunachal Pradesh | West Kameng | Kamengbas-Doinara | Thrimo | 261880 | Doinara | 83 | 92.403891 | 26.973547 | SINGLE | 83 | A | Doinara |
| 1362 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265737 | Sobu | 83 | 92.768719 | 27.305304 | SINGLE | 83 | A | Sobu |
| 1363 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265753 | Paspik | 83 | 93.508306 | 27.696778 | SINGLE | 83 | A | Paspik |
| 1364 | Arunachal Pradesh | Upper Subansiri | Daperijo | Daperijo | 263145 | Ade | 83 | 94.190525 | 27.922286 | SINGLE | 83 | A | Ade |
| 1365 | Arunachal Pradesh | Lower Dibang Valley | Desali | Huili-Desali | 266101 | Dorli | 83 | 96.037593 | 28.298691 | SINGLE | 83 | A | Dorli |
| 1366 | Arunachal Pradesh | Lower Subansiri | Yatali | Ziro-I | 264901 | Kamcho Tarim | 84 | 93.784661 | 27.453536 | SINGLE | 84 | A | Kamcho Tarim |
| 1367 | Arunachal Pradesh | West Siang | Sibe | Genol | 263705 | Yachung Garuh | 84 | 94.42484 | 27.745198 | SINGLE | 84 | A | Yachung Garuh |
| 1368 | Arunachal Pradesh | Upper Subansiri | Chetam (Peer Ngau) | Giba | 263093 | Hina | 85 | 93.642047 | 27.830388 | SINGLE | 85 | A | Hina |
| 1369 | Arunachal Pradesh | Upper Subansiri | Payang | Tacha | 262597 | Uingulne | 86 | 94.140511 | 28.257249 | SINGLE | 86 | A | Uingulne |
| 1370 | Arunachal Pradesh | Anjak | Hawai | Walong | 268905 | Lautul | 86 | 96.740014 | 27.970197 | SINGLE | 86 | A | Lautul |
| 1371 | Arunachal Pradesh | Lower Subansiri | Yatali | Ziro-II | 264902 | Seer | 86 | Not Found | Not Found | SINGLE | 86 | A | Seer |
| 1372 | Arunachal Pradesh | Changlang | Yatlam | Changlang | 264066 | Sabbethong | 87 | Not Found | Not Found | SINGLE | 87 | A | Sabbethong |
| 1373 | Arunachal Pradesh | Upper Subansiri | Soyam | Soyam | 262859 | Bynamet | 88 | 94.002666 | 28.27659 | SINGLE | 88 | A | Bynamet |
| 1374 | Arunachal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262232 | Nampe Bagang | 89 | 93.1185 | 27.652078 | SINGLE | 89 | A | Nampe Bagang |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effective Pop | Site Type | Tower Location |
|---------|--------------------|-----------------|---------------------|---------------|--------------|----------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|----------------|
| 1375 | Assamachal Pradesh | West Siang | Momigong | Momigong | 263363 | Yorkkodom | 89 | 94.25852 | 28.20955 | SINGLE | 89 | A | Yorkkodom |
| 1376 | Assamachal Pradesh | Tirap | Saha | Mamsang | 264430 | Borak | 89 | 95.630478 | 27.214742 | SINGLE | 89 | A | Borak |
| 1377 | Assamachal Pradesh | Upper Subansiri | Chetani (Peer Yapu) | Giba | 263077 | Boging | 50 | 93.992598 | 28.052075 | SINGLE | 90 | A | Boging |
| 1378 | Assamachal Pradesh | West Kameng | Thembang | Dihang | 261704 | Chercong | 91 | 92.356434 | 27.355775 | SINGLE | 91 | A | Chercong |
| 1379 | Assamachal Pradesh | East Kameng | Dising-Passo | Sejosa | 261931 | Taposo | 91 | 93.119091 | 27.06305 | SINGLE | 91 | A | Taposo |
| 1380 | Assamachal Pradesh | Upper Subansiri | Gih-Ripa | Dumpanepi | 263264 | Kigimuri | 92 | 94.330648 | 28.133445 | SINGLE | 92 | A | Kigimuri |
| 1381 | Assamachal Pradesh | Anjaw | Manchal | Manchal | 266785 | Mangung | 92 | 96.752155 | 28.001742 | SINGLE | 92 | A | Mangung |
| 1382 | Assamachal Pradesh | West Siang | Litomoba | Litomba | 263529 | Botak - Kawi | 93 | 94.406247 | 28.176743 | SINGLE | 93 | A | Botak - Kawi |
| 1383 | Assamachal Pradesh | Papuni Pare | Pirang | Sagellie | 262639 | Jope | 53 | Not Found | Not Found | SINGLE | 93 | A | Jope |
| 1384 | Assamachal Pradesh | Lower Subansiri | Yachuli | Zro-Il | 264878 | Probrin Happa | 94 | 93.805784 | 27.698695 | SINGLE | 94 | A | Probrin Happa |
| 1385 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265881 | Sojam | 94 | 93.908896 | 27.905647 | SINGLE | 94 | A | Sojam |
| 1386 | Assamachal Pradesh | Kurung Kumey | Parsi-Pardo | Parsi-Pardo | 265739 | Tawringiang | 94 | 93.533312 | 27.944605 | SINGLE | 94 | A | Tawringiang |
| 1387 | Assamachal Pradesh | West Siang | Momigong | Momigong | 263388 | Yang-Hog | 95 | 94.295637 | 28.719567 | SINGLE | 95 | A | Yangrang |
| 1388 | Assamachal Pradesh | West Siang | Payum | Saying-Payum | 263420 | Reying | 95 | 94.653969 | 28.451895 | SINGLE | 95 | A | Reying |
| 1389 | Assamachal Pradesh | Upper Subansiri | Desporjo | Desporjo | 263134 | Pisa | 96 | 94.349662 | 28.029342 | SINGLE | 96 | A | Pisa |
| 1390 | Assamachal Pradesh | Changlang | Maimao | Maimao | 264156 | New Juth | 96 | 95.840512 | 27.191218 | SINGLE | 96 | A | New Juth |
| 1391 | Assamachal Pradesh | Changlang | Lynbok-Longtol | Munnaid | 264179 | New Longtol | 96 | 95.881034 | 27.256494 | SINGLE | 96 | A | New Longtol |
| 1392 | Assamachal Pradesh | Kurung Kumey | Tarak-Lengdi | Tali | 265665 | Padpa | 97 | 93.806425 | 27.848169 | SINGLE | 97 | A | Padpa |
| 1393 | Assamachal Pradesh | West Siang | Sibe | Seni | 263704 | Lutak | 97 | 94.461698 | 27.785423 | SINGLE | 97 | A | Lutak |
| 1394 | Assamachal Pradesh | West Siang | Kamba | Darak | 263479 | Karbak Dahi | 97 | 94.619236 | 28.195308 | SINGLE | 97 | A | Karbak Dahi |
| 1395 | Assamachal Pradesh | Upper Subansiri | Chetani (Peer Yapu) | Giba | 263049 | Choktanjo | 99 | 94.111119 | 28.085409 | SINGLE | 99 | A | Choktanjo |
| 1396 | Assamachal Pradesh | East Siang | Boleng | Paigin | 263786 | Mesang | 99 | 94.80624 | 28.462426 | SINGLE | 99 | A | Mesang |
| 1397 | Assamachal Pradesh | Changlang | Khumyong | Khumyong | 264046 | Tongthung Havi | 99 | 95.712634 | 26.952921 | SINGLE | 99 | A | Tongthung Havi |
| 1398 | Assamachal Pradesh | Kurung Kumey | Tali | Tali | 265899 | Jha | 100 | 93.792808 | 27.951031 | SINGLE | 100 | A | Jha |
| 1399 | Assamachal Pradesh | Kurung Kumey | Gangte | Chambang | 265565 | Tungte | 100 | 93.843882 | 27.795883 | SINGLE | 100 | A | Tungte |
| 1400 | Assamachal Pradesh | West Siang | Mechuka | Mechuka | 263339 | Rapum | 100 | 94.256045 | 28.532074 | SINGLE | 100 | A | Rapum |
| 1401 | Assamachal Pradesh | West Siang | Momigong | Momigong | 263389 | Greching | 101 | 94.297797 | 28.640517 | SINGLE | 101 | A | Greching |
| 1402 | Assamachal Pradesh | Anjaw | Gollang | Havulrang | 266790 | Niang | 101 | 96.65795 | 28.176139 | SINGLE | 101 | A | Niang |
| 1403 | Assamachal Pradesh | Anjaw | Somang | Havulrang | 266793 | Britong | 101 | 96.686464 | 28.139714 | SINGLE | 101 | A | Britong |




RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------|--------------|-----------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|-----------------------|
| 1404 | Arunachal Pradesh | Papum Pare | Sagalee | Sagalee | 262598 | Apop-1 | 102 | 93.511764 | 27.316283 | SINGLE | 102 | A | Apop-1 |
| 1405 | Arunachal Pradesh | East Kameng | Ritchhikrong | Bora | 262034 | New Longte Poubie | 103 | 92.924672 | 27.326343 | SINGLE | 103 | A | New Longte Poubie |
| 1406 | Arunachal Pradesh | Lower Subansiri | Dallongmukh | Tamen-Pujja | 265107 | Ohga | 103 | 94.129403 | 27.58159 | SINGLE | 103 | A | Ohga |
| 1407 | Arunachal Pradesh | West Siang | Sibe | Genal | 263700 | Liduk | 103 | 94.520882 | 27.87153 | SINGLE | 103 | A | Liduk |
| 1408 | Arunachal Pradesh | Lehri | Tebu | Tebu | 266422 | Uago | 104 | Not Found | Not Found | SINGLE | 104 | A | Uago |
| 1409 | Arunachal Pradesh | Upper Subansiri | Taksang | Lumking | 262775 | Quga | 105 | 93.242508 | 28.386181 | SINGLE | 105 | A | Quga |
| 1410 | Arunachal Pradesh | East Kameng | Pitrang(Veo) | Pakke-Kessang | 261976 | Hote Veo | 105 | 93.282863 | 27.353476 | SINGLE | 105 | A | Hote Veo |
| 1411 | Arunachal Pradesh | Papum Pare | Mengjo | Mengjo | 262693 | Yalpu | 106 | 93.560364 | 27.436833 | SINGLE | 106 | A | Yalpu |
| 1412 | Arunachal Pradesh | Changlang | Vijaynagar | Khaqam | 264249 | Buddhamandir | 106 | 97.063958 | 27.280003 | SINGLE | 106 | A | Buddhamandir |
| 1413 | Arunachal Pradesh | East Kameng | Pitrang(Veo) | Pakke-Kessang | 261968 | Pajewa | 106 | Not Found | Not Found | SINGLE | 106 | A | Pajewa |
| 1414 | Arunachal Pradesh | West Siang | Likabali | Likabali | 265717 | Sij Labour Camp | 106 | 94.718872 | 27.749372 | SINGLE | 106 | A | Sij Labour Camp |
| 1415 | Arunachal Pradesh | Kunang Kumey | Tarak Longor | Toli | 265627 | Pierbang | 106 | 93.678906 | 27.779621 | SINGLE | 106 | A | Rembang |
| 1416 | Arunachal Pradesh | Papum Pare | Kimin | Kimin | 262732 | Belo - II | 107 | 93.95763 | 27.293375 | SINGLE | 107 | A | Belo - II |
| 1417 | Arunachal Pradesh | Kunang Kumey | Parsi-Phiso | Parsi-Parlo | 265754 | Lumte Tacha (Sepente) | 107 | 93.546543 | 28.653581 | SINGLE | 107 | A | Lumte Tacha (Sepente) |
| 1418 | Arunachal Pradesh | Changlang | Lyngok-Longto | Manmao | 264178 | Lyngok | 108 | 95.850078 | 27.269319 | SINGLE | 108 | A | Lyngok |
| 1419 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265158 | Koho | 110 | 94.119152 | 27.822042 | SINGLE | 110 | A | Kocho |
| 1420 | Arunachal Pradesh | West Siang | Kangdu | Likabali | 263744 | Germe | 110 | 94.41905 | 27.601292 | SINGLE | 110 | A | Germe |
| 1421 | Arunachal Pradesh | Kunang Kumey | Gangri | Chambang | 265620 | Rendo | 110 | Not Found | Not Found | SINGLE | 110 | A | Rendo |
| 1422 | Arunachal Pradesh | East Kameng | Gyawe Purang | Pipu | 262180 | Tatoniako | 111 | 93.139535 | 27.460653 | SINGLE | 111 | A | Tatoniako |
| 1423 | Arunachal Pradesh | East Kameng | Sawa | Chayangtajo | 262247 | Bodhi | 111 | 93.108186 | 27.599942 | SINGLE | 111 | A | Bodhi |
| 1424 | Arunachal Pradesh | West Kameng | Balema | KaloKiang | 261885 | L700 Chain PWD Camp | 111 | 92.105097 | 26.925731 | SINGLE | 111 | A | L700 Chain PWD Camp |
| 1425 | Arunachal Pradesh | Upper Siang | Singa | Singa-Gelling | 262964 | Nyokong | 112 | 95.000935 | 28.888169 | SINGLE | 112 | A | Nyokong |
| 1426 | Arunachal Pradesh | Papum Pare | Parang | Sagalee | 262635 | Pochhapa | 112 | Not Found | Not Found | SINGLE | 112 | A | Pochhapa |
| 1427 | Arunachal Pradesh | Papum Pare | Uperkong | Sagalee | 262664 | Longyi Puthung | 113 | 93.384638 | 27.284176 | SINGLE | 113 | A | Longyi Puthung |
| 1428 | Arunachal Pradesh | Lower Subansiri | Ziro (Saidul) | Ziro-I | 264593 | Kijang | 115 | Not Found | Not Found | SINGLE | 115 | A | Kijang |
| 1429 | Arunachal Pradesh | Kunang Kumey | Sangram | Sangram | 265326 | Paching | 116 | 93.540031 | 27.820558 | SINGLE | 116 | A | Paching |



RAMESHWAR DHARIVAL
 Partner (49-1) S. Pvt. Ltd. Co.
 Director (T-1) USOF
 Greater Noida, West Sector
 Deptt. of Telecom, Govt. of India
 and Bhubaneswar, Odisha

| Sl. No. | State Name | District Name | Sub-District Name | CD-Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-------------------|---------------|--------------|---------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 1430 | Arunachal Pradesh | Upper Subansiri | Siyom | Siyom | 262852 | Long | 116 | 94.046621 | 28.306594 | SINGLE | 116 | A | long |
| 1431 | Arunachal Pradesh | Kurang Kurney | Tali | Tali | 265879 | Hokpu | 117 | 93.906267 | 27.941871 | SINGLE | 117 | A | Hokpu |
| 1432 | Arunachal Pradesh | Changlang | Changlang | Changlang | 264104 | Ranglum | 117 | 95.862565 | 27.076532 | SINGLE | 117 | A | Ranglum |
| 1433 | Arunachal Pradesh | West Siang | Mompong | Mompong | 263383 | Sheet | 118 | 94.307797 | 28.683717 | SINGLE | 118 | A | Sheet |
| 1434 | Arunachal Pradesh | Papum Pare | Leporang | Sagalie | 262670 | Moger-Hapa | 119 | 93.332374 | 27.251793 | SINGLE | 119 | A | Mega-Hapa |
| 1435 | Arunachal Pradesh | West Siang | Aiso | Aiso East | 263592 | Nig | 120 | 94.654511 | 28.126286 | SINGLE | 120 | A | Nig |
| 1436 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261953 | Passo Canji | 121 | 93.131132 | 27.18421 | SINGLE | 121 | A | Passo Camp |
| 1437 | Arunachal Pradesh | Papum Pare | Leporang | Sagalie | 262676 | Pape | 121 | 93.336003 | 27.257396 | SINGLE | 121 | A | Pape |
| 1438 | Arunachal Pradesh | Papum Pare | Taraso | Baljan | 262413 | Sango | 121 | 93.3558 | 27.01529 | SINGLE | 121 | A | Sango |
| 1439 | Arunachal Pradesh | Kurang Kurney | Damih | Damih | 265823 | Seyang | 121 | 93.376611 | 28.117356 | SINGLE | 121 | A | Seyang |
| 1440 | Arunachal Pradesh | Upper Siang | Gelling | Sanga-Gelling | 263959 | Bishing | 121 | 95.057175 | 29.082581 | SINGLE | 121 | A | Bishing |
| 1441 | Arunachal Pradesh | Changlang | Jaramour | Nampong | 264234 | Hetlong | 121 | 96.028564 | 27.255869 | SINGLE | 121 | A | Hetlong |
| 1442 | Arunachal Pradesh | Lower Subansiri | Yazali | Zro-I | 264911 | Seer Hoo | 122 | 93.7656 | 27.420984 | SINGLE | 122 | A | Seer Hoo |
| 1443 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262556 | Giri | 123 | 94.290259 | 27.945928 | SINGLE | 123 | A | Giri |
| 1444 | Arunachal Pradesh | Upper Subansiri | Piyeng | Taliba | 263002 | Eche | 123 | Not Found | Not Found | SINGLE | 123 | A | Eche |
| 1445 | Arunachal Pradesh | Tirap | Lapu | Lapu | 264575 | Upper Chuhuan | 123 | Not Found | Not Found | SINGLE | 123 | A | Upper Chuhuan |
| 1446 | Arunachal Pradesh | West Kameng | Shergoon | Kalaktang | 261780 | Demachang | 125 | 97.234447 | 26.946725 | SINGLE | 125 | A | Demachang |
| 1447 | Arunachal Pradesh | West Siang | Mibulgong | Mompong | 263360 | Nema Sibb | 125 | 94.200572 | 28.805761 | SINGLE | 125 | A | Nema Sibb |
| 1448 | Arunachal Pradesh | West Siang | Talbin | Talbin | 263629 | Nigasi | 126 | 94.557619 | 27.970711 | SINGLE | 126 | A | Nigasi |
| 1449 | Arunachal Pradesh | West Siang | Kamba | Darak | 263494 | Sere Tali | 126 | 94.66063 | 28.263496 | SINGLE | 126 | A | Sere Tali |
| 1450 | Arunachal Pradesh | Lower Subansiri | Yazali | Zro-II | 264891 | Tabampassa | 126 | 93.734031 | 27.381661 | SINGLE | 126 | A | Tabampassa |
| 1451 | Arunachal Pradesh | East Kameng | Ladu | Kheniwa | 262085 | Nubaling | 127 | 92.77573 | 27.560263 | SINGLE | 127 | A | Nubaling |
| 1452 | Arunachal Pradesh | Papum Pare | Kakoi | Kimin | 262762 | Tano-Hapa | 130 | 93.989154 | 27.40589 | SINGLE | 130 | A | Tano-Hapa |
| 1453 | Arunachal Pradesh | Papum Pare | Paranj | Sagalie | 262634 | Pkyranj | 131 | Not Found | Not Found | SINGLE | 131 | A | Pkyranj |
| 1454 | Arunachal Pradesh | East Kameng | Pipu-Dipu | Pipu | 262143 | Lochung | 131 | 93.089553 | 27.504414 | SINGLE | 131 | A | Lochung |
| 1455 | Arunachal Pradesh | West Siang | Bogra | Aiso West | 263766 | Yomko Bagra | 131 | 94.728918 | 28.062315 | SINGLE | 131 | A | Yomko Bagra |
| 1456 | Arunachal Pradesh | Anjaw | Merengiang | Chuglam | 266849 | Rolliang | 133 | 96.529464 | 28.159734 | SINGLE | 133 | A | Rolliang |
| 1457 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Korona | 266232 | Arasang | 133 | 95.849735 | 28.022339 | SINGLE | 133 | A | Arasang |
| 1458 | Arunachal Pradesh | East Kameng | Dising-Passo | Seljosa | 261938 | Namorah | 133 | 93.135183 | 26.94514 | SINGLE | 133 | A | Namorah |
| 1459 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261537 | Koko | 135 | 93.209878 | 27.146292 | SINGLE | 135 | A | Koko |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Deputy Director, Area Office
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sl. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|---------------------------|---------------|--------------|----------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 1460 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262917 | Talibakamatra | 137 | 94.079673 | 28.366537 | SINGLE | 137 | A | Terningkasar |
| 1461 | Arunachal Pradesh | Triap | Dadani | Khoode | 264491 | Boaktoam I | 137 | 95.413678 | 26.917576 | SINGLE | 137 | A | Boaktoam I |
| 1462 | Arunachal Pradesh | Karung Kumey | Longding Kolin (Piporang) | Piporang | 265863 | Keyang | 138 | 93.617589 | 28.230922 | SINGLE | 138 | A | Keyang |
| 1463 | Arunachal Pradesh | Changlang | Vijaynagar | Ahagam | 264243 | Wamaagar | 138 | 96.937666 | 27.230388 | SINGLE | 138 | A | Kammyagar |
| 1464 | Arunachal Pradesh | Karung Kumey | Longding Kolin (Piporang) | Piporang | 265859 | Nikha | 139 | 93.550872 | 28.091193 | SINGLE | 139 | A | Nikha |
| 1465 | Arunachal Pradesh | West Siang | Padi | Mechuka | 263398 | Barbo | 139 | 94.404383 | 28.551869 | SINGLE | 139 | A | Barbo |
| 1466 | Arunachal Pradesh | Papam Pare | Gumto | Domukh | 262521 | Bogoli | 139 | 93.838695 | 27.386937 | SINGLE | 139 | A | Bogoli |
| 1467 | Arunachal Pradesh | West Siang | Tribin | Taliba | 263627 | Lutak | 142 | 94.578467 | 27.996567 | SINGLE | 142 | A | Lutak |
| 1468 | Arunachal Pradesh | Changlang | Mameao | Mannan | 264157 | Old Jukha | 142 | 95.870655 | 27.165853 | SINGLE | 142 | A | Old Jukha |
| 1469 | Arunachal Pradesh | Karung Kumey | Daman | Daman | 265817 | Galan | 143 | 93.827541 | 28.105621 | SINGLE | 143 | A | Galan |
| 1470 | Arunachal Pradesh | Karung Kumey | Parsi-Parlo | Parsi-Parlo | 265743 | Nyokuriang | 145 | Not Found | Not Found | SINGLE | 145 | A | Nyokuriang |
| 1471 | Arunachal Pradesh | Karung Kumey | Sangram | Sangram | 265298 | Hocho | 149 | 93.471595 | 27.85879 | SINGLE | 149 | A | Hocho |
| 1472 | Arunachal Pradesh | West Siang | Yomcha | Liromba | 263555 | Lago Gamlin | 149 | 94.561333 | 28.065522 | SINGLE | 149 | A | Lago Gamlin |
| 1473 | Arunachal Pradesh | West Siang | Jomlo-Mobuk | Ruingong | 263524 | Sipeng | 149 | 94.774561 | 28.219045 | SINGLE | 149 | A | Sipeng |
| 1474 | Arunachal Pradesh | Karung Kumey | Nyapin | Nyapin | 265391 | Beksa | 150 | 93.482504 | 27.722254 | SINGLE | 150 | A | Beksa |
| 1475 | Arunachal Pradesh | East Siang | Kera | Pamle-Bango | 263836 | Lipin | 150 | 94.979583 | 27.846283 | SINGLE | 150 | A | Lipin |
| 1476 | Arunachal Pradesh | East Kameng | Dising Passo | Sejosa | 261932 | Passo | 150 | 92.956333 | 27.005097 | SINGLE | 150 | A | Passo |
| 1477 | Arunachal Pradesh | Lower Dibang Valley | Damduk | Dumduk | 266300 | Tipo | 151 | 95.612393 | 28.030395 | SINGLE | 151 | A | Tipo |
| 1478 | Arunachal Pradesh | West Siang | Lironoba | Liromba | 263548 | Rise | 152 | 94.445051 | 28.079356 | SINGLE | 152 | A | Rise |
| 1479 | Arunachal Pradesh | Upper Siang | Gelling | Singa-Gelling | 265963 | Norbudling | 153 | 94.973406 | 29.127742 | SINGLE | 153 | A | Norbudling |
| 1480 | Arunachal Pradesh | Lower Dibang Valley | Roing | Roing-Koromu | 266211 | Bangkong | 154 | 95.784752 | 27.990074 | SINGLE | 154 | A | Bangkong |
| 1481 | Arunachal Pradesh | Karung Kumey | Tali | Tali | 265875 | Pamio | 155 | 93.856855 | 28.034305 | SINGLE | 155 | A | Pamio |
| 1482 | Arunachal Pradesh | Papam Pare | Parang | Sagadee | 262629 | Totpo-1 | 157 | 93.629534 | 27.350333 | SINGLE | 157 | A | Totpo-1 |
| 1483 | Arunachal Pradesh | East Kameng | Gyawa Purang | Pipu | 262168 | Serewa | 160 | 93.119542 | 27.284492 | SINGLE | 160 | A | Serewa |
| 1484 | Arunachal Pradesh | Triap | Lawru | Karubak | 264525 | Kamru | 160 | 95.260333 | 26.999595 | SINGLE | 160 | A | Kamru |
| 1485 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262972 | Dumjung-Maling | 161 | 94.039951 | 28.206923 | SINGLE | 161 | A | Dumjung-Maling |
| 1486 | Arunachal Pradesh | Upper Subansiri | Dapotpio | Dapotpio | 263339 | Mottu | 162 | 94.156139 | 27.992297 | SINGLE | 162 | A | Mottu |
| 1487 | Arunachal Pradesh | East Kameng | Bameng | Bameng | 262110 | Jawa Camp | 163 | 93.038667 | 27.563508 | SINGLE | 163 | A | Jawa Camp |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No. | Effectv e Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|---------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|-------------|---------------|-----------|----------------|
| 1488 | Assamchal Pradesh | Tirap | Kamubari | Xanubari | 264509 | Sangsalbam | 163 | 95.231805 | 26.904075 | SINGLE | 163 | A | Sangsalbam |
| 1489 | Assamchal Pradesh | Upper Sang | Pulling | Tuting | 263957 | Palling H.Q. | 165 | 94.782722 | 28.809286 | SINGLE | 165 | A | Palling H.Q. |
| 1490 | Assamchal Pradesh | Changlang | Nampong | Nampong | 264202 | Sangwai | 165 | 96.198206 | 27.402275 | SINGLE | 165 | A | Sangwai |
| 1491 | Assamchal Pradesh | East Kameng | Chayangtajo | Chayangtajo | 262222 | Khamlang | 166 | 93.12981 | 27.729046 | SINGLE | 166 | A | Khamlang |
| 1492 | Assamchal Pradesh | Upper Subansiri | Chietam (Peer Yapo) | Giba | 263088 | Keyong | 166 | 94.008414 | 27.982567 | SINGLE | 166 | A | Keyong |
| 1493 | Assamchal Pradesh | Lower Subansiri | Kamporjo | Tamen-Raga | 265069 | Dabu | 166 | 94.09665 | 27.774892 | SINGLE | 166 | A | Dabu |
| 1494 | Assamchal Pradesh | East Sang | Bolong | Pangin | 263785 | Jully | 166 | 94.760536 | 28.485908 | SINGLE | 166 | A | Jully |
| 1495 | Assamchal Pradesh | East Kameng | Lalra | Khanawa | 262083 | Ussong | 166 | 92.788927 | 27.544182 | SINGLE | 166 | A | Ussong |
| 1496 | Assamchal Pradesh | Papum Pare | Kakoi | Minin | 262755 | Sallang | 167 | 93.993746 | 27.33497 | SINGLE | 167 | A | Sallang |
| 1497 | Assamchal Pradesh | West Sang | Yomcha | Lromba | 263558 | Lower Jumi | 169 | 94.597323 | 27.33497 | SINGLE | 169 | A | Lower Jumi |
| 1498 | Assamchal Pradesh | West Sang | Montong | Monging | 263376 | Tego Gamin | 176 | 94.337353 | 28.081329 | SINGLE | 176 | A | Tego Gamin |
| 1499 | Assamchal Pradesh | Changlang | Vijonagar | Khangam | 264245 | Jercing | 179 | 96.958804 | 27.222201 | SINGLE | 179 | A | Jercing |
| 1500 | Assamchal Pradesh | Kurung Kumey | Damin | Damin | 265786 | Chidudi | 180 | 93.383094 | 27.963847 | SINGLE | 180 | A | Chidudi |
| 1501 | Assamchal Pradesh | Lower Subansiri | Pistana | Zro-II | 264866 | Moruk | 180 | 93.63575 | 27.567153 | SINGLE | 180 | A | Moruk |
| 1502 | Assamchal Pradesh | East Sang | Kebarang | Pangin | 263904 | Ekaraya | 180 | 95.119373 | 28.143308 | SINGLE | 180 | A | Ekaraya |
| 1503 | Assamchal Pradesh | Tirap | Kanubari | Kanubari | 264504 | Sossen | 180 | 95.26532 | 26.923511 | SINGLE | 180 | A | Sossen |
| 1504 | Assamchal Pradesh | Upper Subansiri | Gassar | Dumpejo | 263238 | Longrakshie | 181 | 94.27427 | 28.105594 | SINGLE | 181 | A | Longrakshie |
| 1505 | Assamchal Pradesh | Changlang | Vijonagar | Khangam | 264239 | Uti | 184 | 96.02023 | 27.223146 | SINGLE | 184 | A | Uti |
| 1506 | Assamchal Pradesh | Kurung Kumey | Yangte | Sangram | 265268 | Dawodi | 185 | Not Found | Not Found | SINGLE | 185 | A | Dawodi |
| 1507 | Assamchal Pradesh | East Sang | Bolong | Pangin | 263781 | Rangha | 186 | 94.503824 | 28.451163 | SINGLE | 186 | A | Rangha |
| 1508 | Assamchal Pradesh | East Kameng | Bumding | Bameng | 262122 | Supsang | 188 | 92.862311 | 27.588182 | SINGLE | 188 | A | Supsang |
| 1509 | Assamchal Pradesh | Kurung Kumey | Koloriang | Koloriang | 265444 | Paksa | 189 | 93.434369 | 27.929061 | SINGLE | 189 | A | Paksa |
| 1510 | Assamchal Pradesh | Upper Subansiri | Syam | Syam | 262889 | Sangbum | 190 | 94.07822 | 28.358314 | SINGLE | 190 | A | Sangbum |
| 1511 | Assamchal Pradesh | Kurung Kumey | Damin | Damin | 265799 | Yeba | 193 | 93.441441 | 28.157808 | SINGLE | 193 | A | Yeba |
| 1512 | Assamchal Pradesh | East Kameng | Pipu-Dipo | Pipu | 262152 | Sejki | 194 | 93.123336 | 27.502922 | SINGLE | 194 | A | Sejki |
| 1513 | Assamchal Pradesh | Changlang | Namtok | Changlang | 264146 | Dabri | 194 | 95.68861 | 27.207199 | SINGLE | 194 | A | Dabri |
| 1514 | Assamchal Pradesh | Lower Subansiri | Kamporjo | Tamen-Raga | 265038 | Relangan | 195 | 93.980705 | 27.748078 | SINGLE | 195 | A | Relangan |
| 1515 | Assamchal Pradesh | Upper Subansiri | Taliba | Taliba | 262965 | Yattap | 195 | 94.082246 | 28.712756 | SINGLE | 195 | A | Yattap |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sl. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------|------------------------------|---------------|--------------|---------------------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|---------------------------------|
| 1516 | Arunachal Pradesh | East Kameng | Khemewa | Khemewa | 262192 | Mianglinga Camp | 196 | 93.056756 | 27.611908 | SINGLE | 196 | A | Mianglinga Camp |
| 1517 | Arunachal Pradesh | Popur Pare | Parang | Sagatee | 262631 | Parang(Parang) | 196 | Not Found | Not Found | SINGLE | 196 | A | Parang(Parang) |
| 1518 | Arunachal Pradesh | West Siang | Daring | Basar | 263682 | Zirbo | 197 | 94.842075 | 27.834396 | SINGLE | 197 | A | Zirbo |
| 1519 | Arunachal Pradesh | Aijaw | Merengiang | Changlam | 266838 | Merengiang | 197 | 96.447854 | 28.098089 | SINGLE | 197 | A | Merengiang |
| 1520 | Arunachal Pradesh | Tirap | Namsang | Namsang | 264407 | Lomphong | 201 | Not Found | Not Found | SINGLE | 201 | A | Lomphong |
| 1521 | Arunachal Pradesh | West Siang | Bagra | Aho West | 263775 | Pushi Doke | 210 | 94.705047 | 28.029118 | SINGLE | 210 | A | Pushi Doke |
| 1522 | Arunachal Pradesh | East Siang | Mebo | Mebo | 263915 | Aohali | 216 | 95.520728 | 28.256261 | SINGLE | 216 | A | Aohali |
| 1523 | Arunachal Pradesh | Upper Siang | Mopom (Adipost) | Mariyang | 264029 | Adipasi-Sikko | 217 | 95.240744 | 28.360703 | SINGLE | 217 | A | Adipasi-Sikko |
| 1524 | Arunachal Pradesh | Tirap | Namsang | Namsang | 264411 | Lamlo | 217 | Not Found | Not Found | SINGLE | 217 | A | Lamlo |
| 1525 | Arunachal Pradesh | Changlang | Namtok | Changlang | 264145 | Coffee Plantation (Old Yumcham) | 219 | 95.725386 | 27.232022 | SINGLE | 219 | A | Coffee Plantation (Old Yumcham) |
| 1526 | Arunachal Pradesh | Popur Pare | Parang | Sagalee | 262638 | Puteh | 219 | Not Found | Not Found | SINGLE | 219 | A | Puteh |
| 1527 | Arunachal Pradesh | East Kameng | Pakke-Kessang | Pakke-Kessang | 261935 | Gamte | 220 | 93.171517 | 27.205189 | SINGLE | 220 | A | Gumte |
| 1528 | Arunachal Pradesh | Kurung Kumey | Longling Koling (Pipsoarang) | Pipsoarang | 265831 | Tedjang | 222 | 93.688376 | 28.150799 | SINGLE | 222 | A | Tedjang |
| 1529 | Arunachal Pradesh | Changlang | Namtok | Changlang | 264136 | Longma | 225 | 95.647954 | 27.196471 | SINGLE | 225 | A | Longma |
| 1530 | Arunachal Pradesh | Tirap | Soha | Namung | 264431 | Dongrong | 227 | 95.619839 | 27.186054 | SINGLE | 227 | A | Dongrong |
| 1531 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265874 | Sartam | 228 | 93.819183 | 28.005464 | SINGLE | 228 | A | Sartam |
| 1532 | Arunachal Pradesh | Kurung Kumey | Palin | Palin | 265227 | Dokur | 229 | 93.671192 | 27.680069 | SINGLE | 229 | A | Dokur |
| 1533 | Arunachal Pradesh | Kurung Kumey | Longling Koling (Pipsoarang) | Pipsoarang | 265864 | New Zera | 230 | 93.594572 | 28.120025 | SINGLE | 230 | A | New Zera |
| 1534 | Arunachal Pradesh | Kurung Kumey | Longling Koling (Pipsoarang) | Pipsoarang | 265845 | Nayeni | 230 | 93.825892 | 28.061282 | SINGLE | 230 | A | Nayeni |
| 1535 | Arunachal Pradesh | East Kameng | Dissing Passo | Sejosa | 261923 | Upper Dibai Muth | 231 | 93.252751 | 26.957336 | SINGLE | 231 | A | Upper Dibai Muth |
| 1536 | Arunachal Pradesh | Kurung Kumey | Longling Koling (Pipsoarang) | Pipsoarang | 265844 | Zera | 232 | 93.757477 | 28.167602 | SINGLE | 232 | A | Zera |
| 1537 | Arunachal Pradesh | Anjaw | Kibithoo | Walong | 266870 | Misal Jabbar Camp | 232 | 92.062485 | 28.252007 | SINGLE | 232 | A | Misal Jabbar Camp |
| 1538 | Arunachal Pradesh | West Siang | Piyani | Kaying Piyani | 263412 | Gaming | 237 | 94.669581 | 28.150031 | SINGLE | 237 | A | Gaming |
| 1539 | Arunachal Pradesh | Kurung Kumey | Parso Parlo | Parso Parlo | 265714 | Tenk | 237 | 93.479799 | 27.933906 | SINGLE | 237 | A | Tenk |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Neware Bazar, New Delhi
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|------------------------------|----------------|--------------|-----------------|-----------------------------|-----------|-----------|------------|---------------|-----------|-----------------|
| 1540 | Arunachal Pradesh | Kurung Kumey | Longling Koling (Pipisorang) | Pipisorang | 265853 | Nyache | 238 | 93.596828 | 28.016686 | SINGLE | 238 | A | Nyache |
| 1541 | Arunachal Pradesh | West Siang | Tibin | Tibin | 263614 | Sodo Dobe | 242 | 94.510778 | 28.020011 | SINGLE | 242 | A | Sodo Dobe |
| 1542 | Arunachal Pradesh | East Kameng | Piarang(Veo) | Pakke-Kesiang | 261979 | Kamrung(Mezang) | 252 | 93.029888 | 27.273573 | SINGLE | 252 | A | Kamrung(Mezang) |
| 1543 | Arunachal Pradesh | Lower Subansiri | Vachuli | Ziro-II | 264851 | Nyuch | 254 | 93.802608 | 27.531443 | SINGLE | 254 | A | Nyuch |
| 1544 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265726 | Langbang | 258 | Not Found | Not Found | SINGLE | 258 | A | Langbang |
| 1545 | Arunachal Pradesh | Anjaw | Kibithoo | Walong | 266869 | Musar | 262 | 97.03115 | 28.264912 | SINGLE | 262 | A | Musar |
| 1546 | Arunachal Pradesh | Kurung Kumey | Longling Koling (Pipisorang) | Pipisorang | 265849 | Kaba | 262 | 93.758917 | 28.103578 | SINGLE | 262 | A | Kaba |
| 1547 | Arunachal Pradesh | Kurung Kumey | Longling Koling (Pipisorang) | Pipisorang | 265835 | Koling | 263 | 93.642015 | 28.124575 | SINGLE | 263 | A | Koling |
| 1548 | Arunachal Pradesh | Changlang | Miao | Khagam | 264279 | Songlin II | 265 | 96.221631 | 27.40674 | SINGLE | 265 | A | Songlin II |
| 1549 | Arunachal Pradesh | Changlang | Vjorneigr | Khagam | 264247 | Twohut | 266 | 96.968104 | 27.289953 | SINGLE | 266 | A | Twohut |
| 1550 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265898 | Dotte | 270 | 93.764987 | 27.956997 | SINGLE | 270 | A | Dotte |
| 1551 | Arunachal Pradesh | Kurung Kumey | Tali | Tali | 265892 | Rhapuk | 271 | 93.671521 | 27.957214 | SINGLE | 271 | A | Rhapuk |
| 1552 | Arunachal Pradesh | Tawang | Tawang Yangre | Tawang | 261449 | Mandrelling | 279 | 91.812619 | 27.592824 | SINGLE | 279 | A | Mandrelling |
| 1553 | Arunachal Pradesh | Kurung Kumey | | Sengram | 265271 | Dabo | 282 | Not Found | Not Found | SINGLE | 282 | A | Dabo |
| 1554 | Arunachal Pradesh | Kurung Kumey | Nyapin | Nyapin | 265384 | Lomte | 283 | 93.419067 | 27.755994 | SINGLE | 283 | A | Lomte |
| 1555 | Arunachal Pradesh | East Kameng | Pipu-Dipu | Pipu | 262134 | Pipu H.O. | 287 | 93.1457 | 27.522308 | SINGLE | 287 | A | Pipu H.O. |
| 1556 | Arunachal Pradesh | West Kameng | Balemu | Kalaktang | 261883 | Balemu H.O. | 287 | Not Found | Not Found | SINGLE | 287 | A | Balemu H.O. |
| 1557 | Arunachal Pradesh | East Kameng | Khenswa | Khenswa | 262204 | Johua | 289 | 93.048622 | 27.637586 | SINGLE | 289 | A | Johua |
| 1558 | Arunachal Pradesh | Kurung Kumey | Longling Koling (Pipisorang) | Pipisorang | 265846 | Ha | 289 | 93.793914 | 28.026586 | SINGLE | 289 | A | Ha |
| 1559 | Arunachal Pradesh | Anjaw | Hawar | Walong | 266926 | Walong | 289 | 96.788759 | 27.895388 | SINGLE | 289 | A | Walong |
| 1560 | Arunachal Pradesh | Lower Dibang Valley | Reing | Reing-Korou | 266262 | Yaklong | 293 | Not Found | Not Found | SINGLE | 293 | A | Yaklong |
| 1561 | Arunachal Pradesh | Papum Pare | Sagalae | Sagalae | 262615 | Khyate | 294 | 93.399683 | 27.258663 | SINGLE | 294 | A | Khyate |
| 1562 | Arunachal Pradesh | Lower Dibang Valley | Reing | Reing-Korou | 266228 | Turung | 299 | 95.841744 | 27.994735 | SINGLE | 299 | A | Turung |
| 1563 | Arunachal Pradesh | Kurung Kumey | Parsi-Parlo | Parsi-Parlo | 265719 | Reingcha Porang | 301 | 93.504075 | 27.946339 | SINGLE | 301 | A | Reingcha Porang |
| 1564 | Arunachal Pradesh | Changlang | Vjorneigr Lammu | Khagam Kambari | 264240 | Phapbari | 317 | 96.964121 | 27.204219 | SINGLE | 317 | A | Phapbari |
| 1565 | Arunachal Pradesh | Tiapp | Lammu | Kambari | 264522 | Nantong | 321 | 95.322944 | 27.057876 | SINGLE | 321 | A | Nantong |



64

रामेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (E-T) 9.09.2019
 Director (T-1) USOP
 Ministry (Rural), New Delhi
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr No. | State Name | District Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|--------|-------------------|---------------------|---------------------|-----------------------------|---------------------|--------------|---------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 1566 | Arunachal Pradesh | Changlang | Changlang | Yardim | Changlang | 264007 | Jongphohare | 322 | 95.657877 | 27.166955 | SINGLE | 322 | A | Jongphohare |
| 1567 | Arunachal Pradesh | Upper Siang | Upper Siang | Tuting | Tuting | 263957 | Nongging | 330 | 94.833269 | 28.954361 | SINGLE | 330 | A | Nongging |
| 1568 | Arunachal Pradesh | Kurung Kumey | Kurung Kumey | Tali | Tali | 265873 | Rubi | 338 | 93.753328 | 27.974808 | SINGLE | 338 | A | Rubi |
| 1569 | Arunachal Pradesh | Upper Siang | Upper Siang | Katan | Geku | 264034 | Pongging | 339 | 95.204219 | 28.182066 | SINGLE | 339 | A | Pongging |
| 1570 | Arunachal Pradesh | Lower Dibang Valley | Lower Dibang Valley | Timali (Paglam) | Dombak | 266331 | Anpurn III | 340 | 95.576378 | 27.995105 | SINGLE | 340 | A | Anpurn III |
| 1571 | Arunachal Pradesh | East Siang | East Siang | Rebo-Pingang | Pangin | 263818 | Mopit | 345 | 94.931611 | 28.283825 | SINGLE | 345 | A | Mopit |
| 1572 | Arunachal Pradesh | Trap | Trap | Lawru | Karubari | 264511 | Rusa | 359 | 95.254375 | 27.019819 | SINGLE | 359 | A | Rusa |
| 1573 | Arunachal Pradesh | Kurung Kumey | Kurung Kumey | Yangte | Sangram | 265254 | Nyong | 358 | Not Found | Not Found | SINGLE | 358 | A | Nyong |
| 1574 | Arunachal Pradesh | West Siang | West Siang | Tirbin | Tirbin | 263638 | Ti | 361 | 94.53355 | 27.97736 | SINGLE | 361 | A | Ti |
| 1575 | Arunachal Pradesh | Lower Dibang Valley | Lower Dibang Valley | Timali (Paglam) | Dombak | 266330 | Banggo | 368 | 95.533642 | 27.950514 | SINGLE | 368 | A | Banggo |
| 1576 | Arunachal Pradesh | Kurung Kumey | Kurung Kumey | Longling Koling (Pipcorang) | Pipcorang | 265827 | Korabu | 380 | 93.639294 | 28.204442 | SINGLE | 380 | A | Korabu |
| 1577 | Arunachal Pradesh | Lower Dibang Valley | Lower Dibang Valley | Timali (Paglam) | Dombak | 266340 | Mobuk | 380 | 95.564109 | 27.953133 | SINGLE | 380 | A | Mobuk |
| 1578 | Arunachal Pradesh | Lower Dibang Valley | Lower Dibang Valley | Karonir | Pong-Koronu | 266353 | Anuboli | 382 | Not Found | Not Found | SINGLE | 382 | A | Anuboli |
| 1579 | Arunachal Pradesh | Anjaw | Anjaw | Walong | Walong | 266901 | Walong H.Q. | 392 | 96.989839 | 28.134472 | SINGLE | 392 | A | Walong H.Q. |
| 1580 | Arunachal Pradesh | Changlang | Changlang | Yardim | Changlang | 264074 | Wolom | 407 | 95.695731 | 27.089687 | SINGLE | 407 | A | Wolom |
| 1581 | Arunachal Pradesh | East Kameng | East Kameng | Puzang/Veo | Pakke-Kessang | 261985 | New Nere | 409 | 93.059998 | 27.271164 | SINGLE | 409 | A | New Nere |
| 1582 | Arunachal Pradesh | West Siang | West Siang | Khying | Khying-Payum | 263455 | Kerang I | 409 | 94.681922 | 28.324961 | SINGLE | 409 | A | Kerang I |
| 1583 | Arunachal Pradesh | Changlang | Changlang | Khimiyoung | Khimiyoung | 264045 | Jongli Havi | 414 | 95.764586 | 26.983543 | SINGLE | 414 | A | Jongli Havi |
| 1584 | Arunachal Pradesh | Kurung Kumey | Kurung Kumey | Longling Koling (Pipcorang) | Pipzarah | 265843 | Nabiya | 435 | 93.728219 | 28.133053 | SINGLE | 435 | A | Nabiya |
| 1585 | Arunachal Pradesh | Kurung Kumey | Kurung Kumey | Tali | Tali | 265878 | Tungmor | 437 | 93.849987 | 27.99518 | SINGLE | 437 | A | Tungmor |
| 1586 | Arunachal Pradesh | West Siang | West Siang | Yoncha | Litomba | 263557 | Gamsak | 437 | 94.555334 | 28.08768 | SINGLE | 437 | A | Gamsak |
| 1587 | Arunachal Pradesh | Kurung Kumey | Kurung Kumey | Longling Koling (Pipcorang) | Pipcorang | 265840 | Gyapin | 439 | 93.654158 | 28.042144 | SINGLE | 439 | A | Gyapin |
| 1588 | Arunachal Pradesh | Changlang | Changlang | Oyur | Oyur | 264343 | Manabhum H.Q. | 464 | 96.108673 | 27.558267 | SINGLE | 464 | A | Manabhum H.Q. |
| 1589 | Arunachal Pradesh | Trap | Trap | Lawru | Karubari | 264523 | Otonghua | 464 | 96.324272 | 27.064035 | SINGLE | 464 | A | Otonghua |
| 1590 | Arunachal Pradesh | East Kameng | East Kameng | Kheneva | Kheneva | 262207 | Jonoh | 469 | 93.002914 | 27.651353 | SINGLE | 469 | A | Jonoh |
| 1591 | Arunachal Pradesh | West Siang | West Siang | Koying | Khying-Payum | 263451 | Tumbin | 477 | 94.663003 | 28.427002 | SINGLE | 477 | A | Tumbin |
| 1592 | Arunachal Pradesh | Tawang | Tawang | Thingbu | Jang-Thingbu | 261607 | Mago | 486 | 92.207939 | 27.688247 | SINGLE | 486 | A | Mago |
| 1593 | Arunachal Pradesh | Lohit | Lohit | Lekang (Mihadevuar) | Lekang (Mihadevuar) | 266613 | Kharva Chuk | 519 | 95.819195 | 27.659897 | SINGLE | 519 | A | Kharva Chuk |



| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|---------------------|-------------------|---------------|--------------|-----------------------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|-----------------------------------|
| 1594 | Arunachal Pradesh | Tirap | Khensi | Khensi | 264434 | Old Chanyak (Kolgaon) | 561 | 95.039911 | 27.063156 | SINGLE | 561 | A | Old Chanyak (Kolgaon) |
| 1595 | Arunachal Pradesh | Changlang | Miao | Khagin | 264284 | M'Pent | 612 | 96.273444 | 27.500822 | SINGLE | 612 | A | M'Pent |
| 1596 | Arunachal Pradesh | Upper Siang | Yinglong | Yinglong | 263979 | Gobuk | 634 | 95.126807 | 28.57399 | SINGLE | 634 | A | Gobuk |
| 1597 | Arunachal Pradesh | Lower Dibang Valley | Tinahi (Piglam) | Dambuk | 266330 | Ampum II | 683 | 95.601561 | 28.012539 | SINGLE | 683 | A | Ampum II |
| 1598 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263444 | Tato H.O. (including Labour Camp) | 748 | 94.389183 | 28.507456 | SINGLE | 748 | A | Tato H.O. (including Labour Camp) |
| 1599 | Arunachal Pradesh | Tirap | Pangchau | Pangchau | 264555 | Jagan | 802 | 95.378467 | 26.886956 | SINGLE | 802 | A | Jagan |
| 1600 | Arunachal Pradesh | Tirap | Waska | Waska | 264560 | Changkhao | 805 | 95.452339 | 26.757164 | SINGLE | 805 | A | Changkhao |
| 1601 | Arunachal Pradesh | Tirap | Waska | Waska | 264563 | Nigru | 967 | 95.378314 | 26.835508 | SINGLE | 967 | A | Nigru |
| 1602 | Arunachal Pradesh | Tirap | Lingding | Miasta | 264540 | Longsom | 995 | 95.308172 | 26.93509 | SINGLE | 995 | A | Longsom |
| 1603 | Arunachal Pradesh | Tirap | Kanubari | Kanubari | 264502 | Banera | 1094 | 95.229636 | 26.948869 | SINGLE | 1094 | B | Banera |
| 1604 | Arunachal Pradesh | Tirap | Waska | Waska | 264561 | Khanu | 1678 | 95.394622 | 26.769142 | SINGLE | 1678 | B | Khanu |
| 1605 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264627 | Tayoga | 81 | 93.93813 | 27.53435 | SSSS8 | 81 | B | Tayoga |
| 1606 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264626 | Pabili | 8 | 93.937424 | 27.536964 | SSSS8 | 8 | NIL | |
| 1607 | Arunachal Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264628 | Sallyoga | 14 | 93.938483 | 27.530612 | SSSS8 | 14 | NIL | |
| 1608 | Arunachal Pradesh | West Siang | Tate | Mechuka | 263431 | Igo | 190 | 94.462417 | 28.476953 | T1 | 295 | B | Igo |
| 1609 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263430 | Tadigra | 105 | 94.475878 | 28.477022 | T1 | 11 | NIL | |
| 1610 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263425 | Tato Village | 286 | 94.36764 | 28.507759 | T2 | 341 | B | Tato Village |
| 1611 | Arunachal Pradesh | West Siang | Tato | Mechuka | 263440 | Lower Heyo | 55 | 94.355836 | 28.513403 | T2 | 11 | NIL | |
| 1612 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263344 | Gapo | 95 | 94.311114 | 28.511664 | T3 | 108 | B | Gapo |
| 1613 | Arunachal Pradesh | West Siang | Mechuka | Mechuka | 263345 | Miening | 33 | 94.334461 | 28.521428 | T3 | 11 | NIL | |
| 1614 | Arunachal Pradesh | Upper Subansiri | Limeking | Limeking | 262794 | Orak II | 81 | 93.500341 | 28.364169 | TTT9 | 103 | B | Orak II |
| 1615 | Arunachal Pradesh | Upper Subansiri | Limeking | Limeking | 262795 | Orak III | 41 | 93.510511 | 28.356965 | TTT9 | 11 | NIL | |
| 1616 | Arunachal Pradesh | West Siang | Payum | Kaying-Payum | 263425 | Yio | 167 | 94.621628 | 28.506539 | UB | 298 | B | Yio |
| 1617 | Arunachal Pradesh | West Siang | Payum | Kaying-Payum | 263428 | Molo | 131 | 94.625914 | 28.502572 | UB | 11 | NIL | |
| 1618 | Arunachal Pradesh | Upper Subansiri | Payeng | Talaha | 262995 | Peliring | 137 | 94.148502 | 28.275773 | UUJ2 | 214 | B | Peliring |
| 1619 | Arunachal Pradesh | Upper Subansiri | Payeng | Talaha | 262993 | Maki | 77 | 94.187751 | 28.267419 | UUJ2 | 11 | NIL | |
| 1620 | Arunachal Pradesh | Upper Subansiri | Payeng | Talaha | 262998 | Kayang-Maling | 139 | 94.140148 | 28.251438 | UUJ3 | 300 | B | Kayang-Maling |



रमेश्वर धारिवाल
RAMESHWAR DHARIVAL
 Director (S-I) 9, 1st floor, 1st floor,
 Govt. of Telecom, Govt. of India
 Dept. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------|--------------|-----------------|-----------------------------|-----------|------------|------------|---------------|-----------|-----------------|
| 1621 | Arunachal Pradesh | Upper Subansiri | Paying | Taliba | 263000 | Ahijobe | 61 | 94.132321 | 28.249985 | UUU3 | | NIL | |
| 1622 | Arunachal Pradesh | Upper Subansiri | Giba | Giba | 265011 | Lomigaling | 71 | 94.071014 | 28.121158 | UUU5 | 134 | B | Lomigaling |
| 1623 | Arunachal Pradesh | Upper Subansiri | Giba | Giba | 263013 | Sarme-Yoid | 63 | 94.066171 | 28.132297 | UUU5 | | NIL | |
| 1624 | Arunachal Pradesh | Lower Subansiri | Yezali | Ziro-II | 264892 | Pekir Passa | 63 | 93.704354 | 27.432022 | UUUU9 | 109 | B | Pekir Passa |
| 1625 | Arunachal Pradesh | Lower Subansiri | Yezali | Ziro-II | 264893 | Nyilo | 48 | 93.715999 | 27.4216729 | UUUU9 | | NIL | |
| 1626 | Arunachal Pradesh | Upper Subansiri | Limeking | Limeking | 262790 | Gelincenak Camp | 8 | 93.476828 | 28.350389 | V5 | 12 | B | Gelincenak Camp |
| 1627 | Arunachal Pradesh | Upper Subansiri | Limeking | Limeking | 262793 | Orak Camp | 4 | 93.494933 | 28.342903 | V5 | | NIL | |
| 1628 | Arunachal Pradesh | Upper Subansiri | Limeking | Limeking | 262798 | Mepu | 9 | 93.558647 | 28.354611 | V6 | 12 | B | Mepu |
| 1629 | Arunachal Pradesh | Upper Subansiri | Limeking | Limeking | 262796 | Nyare | 3 | 93.550294 | 28.336194 | V6 | | NIL | |
| 1630 | Arunachal Pradesh | Upper Subansiri | Limeking | Limeking | 262798 | Limeking H.Q. | 376 | 93.594939 | 28.337947 | V7 | 384 | B | Limeking H.Q. |
| 1631 | Arunachal Pradesh | Upper Subansiri | Limeking | Limeking | 262797 | Mukovo | 8 | 93.572236 | 28.336906 | V7 | | NIL | |
| 1632 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262828 | Kojinalah | 76 | 93.819658 | 28.337742 | V8 | 92 | B | Kojinalah |
| 1633 | Arunachal Pradesh | Upper Subansiri | Nacho | Nacho | 262837 | Kojup | 10 | 93.801322 | 28.358578 | V8 | | NIL | |
| 1634 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263159 | Luf | 65 | 94.215739 | 27.875166 | VVV6 | 96 | B | Luf |
| 1635 | Arunachal Pradesh | Upper Subansiri | Puchi Geko | Puchi Geko | 263158 | Tidiegi | 31 | 94.216107 | 27.876162 | VVV6 | | NIL | |
| 1636 | Arunachal Pradesh | Lower Subansiri | Posana | Ziro-II | 264938 | Hiku | 91 | 93.888144 | 27.506318 | VVV3 | 128 | B | Hiku |
| 1637 | Arunachal Pradesh | Lower Subansiri | Posana | Ziro-II | 264939 | Berani | 37 | 93.686573 | 27.502877 | VVV3 | | NIL | |
| 1638 | Arunachal Pradesh | Lower Subansiri | Posana | Ziro-II | 264937 | Kulu Tago | 66 | 93.688938 | 27.513198 | VVV4 | 112 | B | Kulu Tago |
| 1639 | Arunachal Pradesh | Lower Subansiri | Posana | Ziro-II | 264936 | Yebin Lebri | 46 | 93.686556 | 27.519285 | VVV4 | | NIL | |
| 1640 | Arunachal Pradesh | Lower Subansiri | Posana | Ziro-II | 264934 | New Povu | 59 | 93.701641 | 27.521137 | VVV5 | 93 | B | New Povu |




रमेश्वर धरिवाल
RAMESHWAR DHARIMAL
 Director (E-I) & Vt. Off. In-charge
 Director (E-I) USOF
 Deputy Director, Vt. Off. In-charge
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|-------------------|-----------------|-------------------|---------------|--------------|-----------------|-----------------------------|-----------|-----------|------------|---------------|-----------|-----------------|
| 1641 | Arunachal Pradesh | Lower Subansiri | Pistana | Ziro-II | 264955 | Buech Geka | 34 | 93.701376 | 27.516374 | VVW5 | | NIL | |
| 1642 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265133 | Taya-Simla | 72 | 94.071141 | 27.767471 | WWW2 | 115 | B | Taya-Simla |
| 1643 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265103 | Boa Model | 41 | 94.070789 | 27.75133 | WWW2 | | NIL | |
| 1644 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265091 | Telisi | 45 | 94.071495 | 27.794494 | WWW5 | 74 | B | Telisi |
| 1645 | Arunachal Pradesh | Lower Subansiri | Kamporijo | Tamen-Raga | 265092 | Kache Tale | 28 | 94.007805 | 27.793143 | WWW5 | | NIL | |
| 1646 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265144 | Tamenchi | 47 | 94.053652 | 27.818271 | WWW7 | 84 | B | Tamenchi |
| 1647 | Arunachal Pradesh | Lower Subansiri | Raga | Tamen-Raga | 265145 | Dokae Puri | 37 | 94.054448 | 27.815095 | WWW7 | | NIL | |
| 1648 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262962 | Ayngiga | 231 | 94.13913 | 28.180097 | WWW8 | 335 | B | Ayngiga |
| 1649 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262926 | Potungdul | 104 | 94.157643 | 28.173801 | WWW8 | | NIL | |
| 1650 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262909 | Setungbobingmar | 160 | 94.137782 | 28.138448 | WWW9 | 220 | B | Setungbobingmar |
| 1651 | Arunachal Pradesh | Upper Subansiri | Taliba | Taliba | 262911 | Bojngboktemari | 60 | 94.146504 | 28.144744 | WWW9 | | NIL | |
| 1652 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumporjo | 263237 | Ngepi | 124 | 94.22037 | 28.106622 | XXX3 | 214 | B | Ngepi |
| 1653 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumporjo | 263236 | Deeni | 80 | 94.220723 | 28.109445 | XXX3 | | NIL | |
| 1654 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumporjo | 263234 | Talte | 41 | 94.200963 | 28.105916 | XXX4 | 64 | B | Talte |
| 1655 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumporjo | 263235 | Gippi | 23 | 94.20061 | 28.109445 | XXX4 | | NIL | |
| 1656 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumporjo | 263230 | Leyarjo | 120 | 94.184379 | 28.085451 | XXX6 | 162 | B | Leyarjo |
| 1657 | Arunachal Pradesh | Upper Subansiri | Gussar | Dumporjo | 263231 | Painjo | 42 | 94.184026 | 28.089332 | XXX6 | | NIL | |
| 1658 | Arunachal Pradesh | Upper Subansiri | Daporjo | Daporjo | 263117 | Narenemuri | 146 | 94.167352 | 27.91644 | XXX9 | 275 | B | Narenemuri |
| 1659 | Arunachal Pradesh | Upper Subansiri | Daporjo | Daporjo | 263115 | Hegi-Nyechi | 129 | 94.166432 | 27.92462 | XXX9 | | NIL | |
| 1660 | Arunachal Pradesh | Upper Subansiri | Daporjo | Daporjo | 263114 | Bome-koto | 300 | 94.165343 | 27.925553 | YYY1 | 342 | B | Bome-koto |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Ministry of Telecom, Govt. of India
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr No. | State Name | District Name | Sub District Name | CD-Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|--------|-------------------|-----------------|--------------------|---------------|--------------|--------------|-----------------------------|-----------|-----------|------------|---------------|-----------|----------------|
| 1661 | Anusachal Pradesh | Upper Subansiri | Daporiyo | Daporiyo | 263113 | Serijo | 42 | 94.165343 | 27.932001 | YY1 | | NIL | |
| 1662 | Anusachal Pradesh | Upper Subansiri | Daporiyo | Daporiyo | 263106 | Pija | 119 | 94.135808 | 27.945623 | YY2 | 167 | B | Pija |
| 1663 | Anusachal Pradesh | Upper Subansiri | Daporiyo | Daporiyo | 263107 | Tompa Rijo | 48 | 94.160439 | 27.938817 | YY2 | | NIL | |
| 1664 | Anusachal Pradesh | Upper Subansiri | Daporiyo | Daporiyo | 263136 | Duba | 112 | 94.174288 | 28.022168 | YY4 | 186 | B | Duba |
| 1665 | Anusachal Pradesh | Upper Subansiri | Daporiyo | Daporiyo | 263135 | Ngadar | 74 | 94.174707 | 28.027379 | YY4 | | NIL | |
| 1666 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263056 | Namchi | 151 | 94.111916 | 28.038917 | YY5 | 265 | B | Namchi |
| 1667 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263057 | Lechin | 114 | 94.10102 | 28.038191 | YY5 | | NIL | |
| 1668 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263097 | Semma | 107 | 94.085526 | 28.070568 | YY5 | 195 | B | Semma |
| 1669 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263091 | Loni | 88 | 94.080623 | 28.066754 | YY6 | | NIL | |
| 1670 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263072 | Hara | 91 | 94.030409 | 28.038696 | YY8 | 130 | B | Hara |
| 1671 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263076 | Jumbu Page | 39 | 94.016606 | 28.048503 | YY8 | | NIL | |
| 1672 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263084 | Hengindoku | 135 | 93.992089 | 28.052589 | YY9 | 226 | B | Hengindoku |
| 1673 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263085 | Leka Rijo | 91 | 93.992367 | 28.046323 | YY9 | | NIL | |
| 1674 | Anusachal Pradesh | Lower Subansiri | Pistana | Ziro-II | 264980 | Rhowoo | 127 | 93.687879 | 27.639166 | YYY7 | 224 | B | Rhowoo |
| 1675 | Anusachal Pradesh | Lower Subansiri | Pistana | Ziro-II | 264979 | Seya II | 97 | 93.687879 | 27.642342 | YYY7 | | NIL | |
| 1676 | Anusachal Pradesh | West Siroj | Sibe | Genal | 263709 | Diten | 123 | 94.361327 | 27.705679 | ZZ5 | 166 | B | Diten |
| 1677 | Anusachal Pradesh | West Siroj | Sibe | Genal | 263711 | Sibe Rije | 43 | 94.337333 | 27.698151 | ZZ5 | | NIL | |
| 1678 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263083 | Raha village | 125 | 93.991545 | 28.051896 | ZZ1 | 189 | B | Raha village |
| 1679 | Anusachal Pradesh | Upper Subansiri | Chetam (Peer Yapu) | Giba | 263080 | Hemiga | 64 | 93.968839 | 28.066487 | ZZ1 | | NIL | |
| 1680 | Anusachal Pradesh | Lower Subansiri | Kamporjo | Turner-Raga | 265076 | Menigi-Kabak | 55 | 93.954611 | 27.889207 | ZZ3 | 89 | B | Menigi-Kabak |
| 1681 | Anusachal Pradesh | Lower Subansiri | Kamporjo | Turner-Raga | 265081 | Mid Putu | 34 | 93.97499 | 27.897675 | ZZ3 | | NIL | |




शशिधर धरिवाल
RAMESHWAR DHARIWAL
 Director (E-I) & Operations
 Director (T-I) USOP
 Director (E-I) & Operations
 Deptt. of Telecom, Govt. of India
 New Delhi

| Sr. No. | State Name | District Name | Sub District Name | CD Block Name | Village Code | Village Name | Total Population of Village | LONG | LAT | Cluster No | Effective Pop | Site Type | Tower Location |
|---------|---------------|-----------------|-------------------|---------------|--------------|------------------|-----------------------------|-----------|-----------|------------|---------------|-----------|------------------|
| 1680 | Uttar Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264558 | Bamin Michharian | 15 | 93.864737 | 27.507564 | ZZZ26 | 17 | B | Bamin Michharian |
| 1681 | Uttar Pradesh | Lower Subansiri | Ziro (Sadar) | Ziro-I | 264557 | Tawitbe | 2 | 93.867912 | 27.512153 | ZZZ26 | | NAL | |




रमेश्वर धरिवाल
RAMESHWAR DHARIWAL
 Director (T-1) USOF
 Director (T-1) USOF
 Deptt. of Telecom, Govt. of India
 (New Delhi)

No. 30-252-5/2020-USF
Department of Telecommunications
Office of the Administrator, USO Fund

Dated: 15th December, 2021

To

M/s Bharti Hexacom Limited
Airtel Center, Plot No. 16
Udyog Vihar, Phase-IV
Gurugram, Haryana-122015

Subject: Clarification/Amendment regarding clause No. 2.5 & 5.3.5 of agreement No. 30-252-5/2020-USF Dated: 29.10.2021 with M/s Bharti Hexacom Ltd. for "Provision of 4G based mobile services in identified uncovered villages in Arunachal Pradesh."

Mobile connectivity in the uncovered villages in identified uncovered villages in Arunachal Pradesh is being provided under the instant agreement. The issue of identification of villages for installation of tower and associated infrastructure for providing mobile services has been raised by the Universal Service Providers (USPs) due to pre-existing mobile coverage in some of the villages.

2. The relevant clauses of the agreement are reproduced below:

"Clause 2.5: Installation of tower and associated infrastructure in an uncovered village is not required if it is already covered from any type of technology i.e. 2G or 3G or 4G or a combination thereof through any TSP. The same should be duly justified and certified by the USP."

"Clause 5.3.5: Installation of tower and associated infrastructure in an uncovered village is not required if it is already covered from any type of technology i.e. 2G or 3G or 4G or a combination thereof through any TSP. The USP is advised to verify non-availability of the coverage in the villages before installing equipment for which it intends to claim support from Universal Service Obligation Fund. No claims shall be admissible for cases of duplicate/redundant infrastructure sites/towers. Date of survey is to be considered as the cutoff date for existing coverage validation."

3. The matter has been examined in DoT and it has been decided that the USP's claim for support from USOF shall be admissible for installation of tower and associated infrastructure only in those villages where the following criteria is met:

"Less than 60% street level coverage (including paths used by people, where "streets" are not there) of mobile services pre-exists in the inhabited areas of the village from a single operator as per the criteria specified in DoT's applicable Test Schedule & Test Procedure (TSTP)".

This issues with the approval of competent authority.



Director (T-1), USOF
Tel. No. 011 2303 6409
Email: dirusof2-dot@gov.in

No. 30-252-5/2021-USF/Arunachal/Execution
भारत सरकार/GOVT. OF INDIA
संचार मंत्रालय/Ministry of Communications
दूरसंचार विभाग/Department of Telecommunications
सार्वभौमिक सेवा दायित्व निधि/Universal Service Obligation Fund
संचार भवन, नई दिल्ली/ Sanchar Bhawan, New Delhi

Dated: 14/08/2023

To,

M/s Bharti Hexacom Ltd.
Airtel Centre, Plot No, 16,
Udyog Vihar, Phase- IV,
Gurugram, Haryana-122 015.

Subject: Amendment of Agreement No.30-252-5/2020-USF dated 29-10-2021 signed with M/s Bharti Hexacom Ltd. (BHL) regarding provision of 4G based mobile services in identified uncovered villages in Arunachal Pradesh.

In Pursuance of the **clause 4.6 [Extension of the Agreement]** and in view of **clause 4.7 [Modification in terms and Conditions of the Agreement]** & **clause 6.5.3 [Roll Out]** of the agreement dated 29-10-2021, the terms and conditions of the captioned Agreement are hereby further amended to the extent as detailed below: -

| Existing Clause | Amended Clause |
|---|---|
| <p>Clause-2 (Section-I):
 This Agreement will remain valid for ten (10) years & twenty one months unless revoked earlier for any reason whatsoever. Date of effect of this Agreement shall be the date of signing of the agreement.</p> | <p>Clause-2 (Section-I):
 This Agreement will remain valid for ten (10) years & twenty four months unless revoked earlier for any reason whatsoever. Date of effect of this Agreement shall be the date of signing of the agreement.</p> |
| <p>Clause 2.2 (ii) i) (Section-II)
 Continued Operation and Maintenance of the Tower and infrastructure created and provision of 4G based mobile services compliant with the terms and conditions of the License Agreement signed with DoT, for a period of 21 months (rollout period) + Ten years from the date of effect of the agreement with USOF.</p> | <p>Clause 2.2 (ii) i) (Section-II)
 Continued Operation and Maintenance of the Tower and infrastructure created and provision of 4G based mobile services compliant with the terms and conditions of the License Agreement signed with DoT, for a period of 24 months (rollout period) + Ten years from the date of effect of the agreement with USOF.</p> |
| <p>Clause-4.5 (Section-IV):
 The Agreement shall be valid for a period of 21 months (rollout period) +Ten years from the effective date unless revoked earlier for reasons as specified elsewhere in the document.</p> | <p>Clause-4.5 (Section-IV):
 The Agreement shall be valid for a period of 24 months (rollout period) +Ten years from the effective date unless revoked earlier for reasons as specified elsewhere in the document.</p> |

| | |
|--|--|
| <p>The subsidy support period and subsidy claim and disbursement schedule is as per Section VII: Financial Conditions of this document. USP shall be responsible for operation and maintenance of the created infrastructure and provision of specified services for a period of 21 months (rollout period) + Ten years from the effective date of the agreement and also after the expiry of Agreement period, as the telecom service providers under the license conditions are bound to provide services under the license terms.</p> | <p>The subsidy support period and subsidy claim and disbursement schedule is as per Section VII: Financial Conditions of this document. USP shall be responsible for operation and maintenance of the created infrastructure and provision of specified services for a period of 24 months (rollout period) + Ten years from the effective date of the agreement and also after the expiry of Agreement period, as the telecom service providers under the license conditions are bound to provide services under the license terms.</p> |
| <p>Clause 6.5.2 (Section-VI)
The USP shall complete the field survey for at least 30% of sites in the bidding unit in three months from the date of signing of the agreement, at least another 30% of sites in six months from the date of signing of the agreement and the remaining sites in nine months from the date of signing of the agreement to finalize location and type of infrastructure (A&B,) at each site. The USP shall commission and provide 4G based mobile services from all the infrastructure sites within a period of 21 months from the date of signing of the Agreement.</p> | <p>Clause 6.5.2 (Section-VI)
The USP shall complete the field survey for at least 30% of sites in the bidding unit in three months from the date of signing of the agreement, at least another 30% of sites in six months from the date of signing of the agreement and the remaining sites in nine months from the date of signing of the agreement to finalize location and type of infrastructure (A&B,) at each site. The USP shall commission and provide 4G based mobile services from all the infrastructure sites within a period of 24 months from the date of signing of the Agreement.</p> |

2. This is issued with the approval of Administrator, USOF

Signed by

Rameshwar Dhariwal

Date: 14-08-2023 15:34:48

(R. Dhariwal)
Director (Mobile-III), USOF
Tel No. 011-23036489

Copy to:

1. JA(F), USOF,
2. Concerned CCA/LSA

No. 30-252-5/2021-USF/Arunachal/Execution
भारत सरकार/GOVT. OF INDIA
संचार मंत्रालय/Ministry of Communications
दूरसंचार विभाग/Department of Telecommunications
सार्वभौमिक सेवा दायित्व निधि/Universal Service Obligation Fund
संचार भवन, नई दिल्ली/ Sanchar Bhawan, New Delhi

Dated: 25/05/2023

To,

M/s Bharti Hexacom Ltd.
Airtel Centre, Plot No, 16,
Udyog Vihar, Phase- IV,
Gurugram, Haryana-122 015.

Subject: Amendment of Agreement No.30-252-5/2020-USF dated 29-10-2021 signed with M/s Bharti Hexacom Ltd. (BHL) regarding provision of 4G based mobile services in identified uncovered villages in Arunachal Pradesh.

In Pursuance of the **clause 4.6 [Extension of the Agreement]** and in view of **clause 4.7 [Modification in terms and Conditions of the Agreement]** & **clause 6.5.3 [Roll Out]** of the agreement dated 29-10-2021, the terms and conditions of the captioned Agreement are hereby further amended to the extent as detailed below: -

| Existing Clause | Amended Clause |
|--|--|
| Clause-2 (Section-I):
This Agreement will remain valid for ten (10) years & Eighteen months unless revoked earlier for any reason whatsoever. Date of effect of this Agreement shall be the date of signing of the agreement. | Clause-2 (Section-I):
This Agreement will remain valid for ten (10) years & twenty one months unless revoked earlier for any reason whatsoever. Date of effect of this Agreement shall be the date of signing of the agreement. |
| Clause 2.2 (ii) i) (Section-II)
Continued Operation and Maintenance of the Tower and infrastructure created and provision of 4G based mobile services compliant with the terms and conditions of the License Agreement signed with DoT, for a period of 18 months (rollout period) + Ten years from the date of effect of the agreement with USOF. | Clause 2.2 (ii) i) (Section-II)
Continued Operation and Maintenance of the Tower and infrastructure created and provision of 4G based mobile services compliant with the terms and conditions of the License Agreement signed with DoT, for a period of 21 months (rollout period) + Ten years from the date of effect of the agreement with USOF. |
| Clause-4.5 (Section-IV):
The Agreement shall be valid for a period of 18 months (rollout period) +Ten years from the effective date unless revoked earlier for reasons as specified elsewhere in the document. | Clause-4.5 (Section-IV):
The Agreement shall be valid for a period of 21 months (rollout period) +Ten years from the effective date unless revoked earlier for reasons as specified elsewhere in the document. |



| Existing Clause | Amended Clause |
|---|---|
| <p>The subsidy support period and subsidy claim and disbursement schedule is as per Section VII: Financial Conditions of this document. USP shall be responsible for operation and maintenance of the created infrastructure and provision of specified services for a period of 18 months (rollout period) + Ten years from the effective date of the agreement and also after the expiry of Agreement period, as the telecom service providers under the license conditions are bound to provide services under the license terms.</p> | <p>The subsidy support period and subsidy claim and disbursement schedule is as per Section VII: Financial Conditions of this document. USP shall be responsible for operation and maintenance of the created infrastructure and provision of specified services for a period of 21 months (rollout period) + Ten years from the effective date of the agreement and also after the expiry of Agreement period, as the telecom service providers under the license conditions are bound to provide services under the license terms.</p> |
| <p>Clause 6.5.2 (Section-VI)
 The USP shall complete the field survey for at least 30% of sites in the bidding unit in three months from the date of signing of the agreement, at least another 30% of sites in six months from the date of signing of the agreement and the remaining sites in nine months from the date of signing of the agreement to finalize location and type of infrastructure (A&B,) at each site. The USP shall commission and provide 4G based mobile services from all the infrastructure sites within a period of 18 months from the date of signing of the Agreement.</p> | <p>Clause 6.5.2 (Section-VI)
 The USP shall complete the field survey for at least 30% of sites in the bidding unit in three months from the date of signing of the agreement, at least another 30% of sites in six months from the date of signing of the agreement and the remaining sites in nine months from the date of signing of the agreement to finalize location and type of infrastructure (A&B,) at each site. The USP shall commission and provide 4G based mobile services from all the infrastructure sites within a period of 21 months from the date of signing of the Agreement.</p> |

2. This is issued with the approval of Administrator, USOF



(Md Aftab Alam)
Director (Mobile-I), USOF
Tel No. 011-23036362

Copy to:

1. JA(F), USOF,
2. Concerned CCA/LSA